

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality Levels	Site Specific Trigger Levels	Comments
EPA Site Specific Trigger Levels											70			
ASBESTOS-ST1-2/13/09	030904384-0001	Southwest Area (sidewalk bridge level)	2/13/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST2-2/13/09	030904384-0002	Southeast Area (sidewalk bridge level)	2/13/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST4-2/13/09	030904384-0003	Northwest Area (street-level)	2/13/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST5-2/13/09	030904384-0004	Firehouse #10 (roof level)	2/13/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST10-2/13/09	030904384-0005	North Side Sidewalk Bridge	2/13/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST11-2/13/09	030904384-0006	90 Trinity Place (roof level)	2/13/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST12-2/13/09	030904384-0007	110 Greenwich Street (roof level)	2/13/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST13-2/13/09	030904384-0008	Marriott Hotel, 38th Floor (roof level)	2/13/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST14-2/13/09	030904384-0009	West Face - South end at corner (scaffolding level)	2/13/09	1	2.820	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST15-2/13/09	030904384-0010	South Face - East end at corner (scaffolding level)	2/13/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST16-2/13/09	030904384-0011	East Face - North end at corner (scaffolding level)	2/13/09	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST17-2/13/09	030904384-0012	North Face - West end at corner (scaffolding level)	2/13/09	1	2.910	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST1-2/14/09	030904387-0001	Southwest Area (sidewalk bridge level)	2/14/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST2-2/14/09	030904387-0002	Southeast Area (sidewalk bridge level)	2/14/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST4-2/14/09	030904387-0003	Northwest Area (street-level)	2/14/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST5-2/14/09	030904387-0004	Firehouse #10 (roof level)	2/14/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST10-2/14/09	030904387-0005	North Side Sidewalk Bridge	2/14/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST11-2/14/09	030904387-0006	90 Trinity Place (roof level)	2/14/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST12-2/14/09	030904387-0007	110 Greenwich Street (roof level)	2/14/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST13-2/14/09	030904387-0008	Marriott Hotel, 38th Floor (roof level)	2/14/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 15.00	No	No		
ASBESTOS-ST14-2/14/09	030904387-0009	West Face - South end at corner (scaffolding level)	2/14/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST15-2/14/09	030904387-0010	South Face - East end at corner (scaffolding level)	2/14/09	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST16-2/14/09	030904387-0011	East Face - North end at corner (scaffolding level)	2/14/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST17-2/14/09	030904387-0012	North Face - West end at corner (scaffolding level)	2/14/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST1-2/15/09	030904390-0001	Southwest Area (sidewalk bridge level)	2/15/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST2-2/15/09	030904390-0002	Southeast Area (sidewalk bridge level)	2/15/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST4-2/15/09	030904390-0003	Northwest Area (street-level)	2/15/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST5-2/15/09	030904390-0004	Firehouse #10 (roof level)	2/15/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST10-2/15/09	030904390-0005	North Side Sidewalk Bridge	2/15/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST11-2/15/09	030904390-0006	90 Trinity Place (roof level)	2/15/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST12-2/15/09	030904390-0007	110 Greenwich Street (roof level)	2/15/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST13-2/15/09	030904390-0008	Marriott Hotel, 38th Floor (roof level)	2/15/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST14-2/15/09	030904390-0009	West Face - South end at corner (scaffolding level)	2/15/09	1	3.230	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST15-2/15/09	030904390-0010	South Face - East end at corner (scaffolding level)	2/15/09	1	3.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST16-2/15/09	030904390-0011	East Face - North end at corner (scaffolding level)	2/15/09	1	3.240	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST17-2/15/09	030904390-0012	North Face - West end at corner (scaffolding level)	2/15/09	1	3.260	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/09	< 13.00	No	No		
ASBESTOS-ST1-2/16/09	030904548-0001	Southwest Area (sidewalk bridge level)	2/16/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		
ASBESTOS-ST2-2/16/09	030904548-0002	Southeast Area (sidewalk bridge level)	2/16/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		
ASBESTOS-ST4-2/16/09	030904548-0003	Northwest Area (street-level)	2/16/09	1	3.220	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		
ASBESTOS-ST5-2/16/09	030904548-0004	Firehouse #10 (roof level)	2/16/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		
ASBESTOS-ST10-2/16/09	030904548-0005	North Side Sidewalk Bridge	2/16/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		
ASBESTOS-ST11-2/16/09	030904548-0006	90 Trinity Place (roof level)	2/16/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		
ASBESTOS-ST12-2/16/09	030904548-0007	110 Greenwich Street (roof level)	2/16/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		
ASBESTOS-ST13-2/16/09	030904548-0008	Marriott Hotel, 38th Floor (roof level)	2/16/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		
ASBESTOS-ST14-2/16/09	030904548-0009	West Face - South end at corner (scaffolding level)	2/16/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		
ASBESTOS-ST15-2/16/09	030904548-0010	South Face - East end at corner (scaffolding level)	2/16/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		
ASBESTOS-ST16-2/16/09	030904548-0011	East Face - North end at corner (scaffolding level)	2/16/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		
ASBESTOS-ST17-2/16/09	030904548-0012	North Face - West end at corner (scaffolding level)	2/16/09	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		
ASBESTOS-ST1-2/17/09	030904627-0001	Southwest Area (sidewalk bridge level)	2/17/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 15.00	No	No		
ASBESTOS-ST2-2/17/09	030904627-0002	Southeast Area (sidewalk bridge level)	2/17/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		
ASBESTOS-ST4-2/17/09	030904627-0003	Northwest Area (street-level)	2/17/09	1	3.250	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 15.00	No	No		
ASBESTOS-ST5-2/17/09	030904627-0004	Firehouse #10 (roof level)	2/17/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 15.00	No	No		
ASBESTOS-ST10-2/17/09	030904627-0005	North Side Sidewalk Bridge	2/17/09	1	2.910	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		
ASBESTOS-ST100-2/17/09	030904627-0013	Station 10 Field Duplicate	2/17/09	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 15.00	No	No		
ASBESTOS-ST11-2/17/09	030904627-0006	90 Trinity Place (roof level)	2/17/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		
ASBESTOS-ST12-2/17/09	030904627-0007	110 Greenwich Street (roof level)	2/17/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		
ASBESTOS-ST13-2/17/09	030904627-0008	Marriott Hotel, 38th Floor (roof level)	2/17/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 15.00	No	No		
ASBESTOS-ST14-2/17/09	030904627-0009	West Face - South end at corner (scaffolding level)	2/17/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		
ASBESTOS-ST15-2/17/09	030904627-0010	South Face - East end at corner (scaffolding level)	2/17/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		
ASBESTOS-ST16-2/17/09	030904627-0011	East Face - North end at corner (scaffolding level)	2/17/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		
ASBESTOS-ST17-2/17/09	030904627-0012	North Face - West end at corner (scaffolding level)	2/17/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/18/09	< 13.00	No	No		