

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels											70			
ASBESTOS-ST1-3/16/07	030708342-0001	Southwest Area (sidewalk bridge level)	3/16/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST2-3/16/07	030708342-0002	Southeast Area (sidewalk bridge level)	3/16/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST4-3/16/07	030708342-0003	Northwest Area (street-level)	3/16/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST5-3/16/07	030708342-0004	Firehouse #10 (roof level)	3/16/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST10-3/16/07	030708342-0005	North Side Sidewalk Bridge	3/16/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST100-3/16/07	030708342-0013	Station 10 Field Duplicate	3/16/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST11-3/16/07	030708342-0006	90 Trinity Place (roof level)	3/16/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST12-3/16/07	030708342-0007	110 Greenwich Street (roof level)	3/16/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST13-3/16/07	030708342-0008	Marriott Hotel, 38th Floor (roof level)	3/16/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST14-3/16/07	030708342-0009	West Face - South end at corner (scaffolding level)	3/16/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST15-3/16/07	030708342-0010	South Face - East end at corner (scaffolding level)	3/16/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST16-3/16/07	030708342-0011	East Face - North end at corner (scaffolding level)	3/16/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST17-3/16/07	030708342-0012	North Face - West end at corner (scaffolding level)	3/16/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST1-3/17/07	030708344-0001	Southwest Area (sidewalk bridge level)	3/17/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST2-3/17/07	030708344-0002	Southeast Area (sidewalk bridge level)	3/17/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST4-3/17/07	030708344-0003	Northwest Area (street-level)	3/17/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 15.00	No	No		
ASBESTOS-ST5-3/17/07	030708344-0004	Firehouse #10 (roof level)	3/17/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 15.00	No	No		
ASBESTOS-ST10-3/17/07	030708344-0005	North Side Sidewalk Bridge	3/17/07	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 15.00	No	No		
ASBESTOS-ST11-3/17/07	030708344-0006	90 Trinity Place (roof level)	3/17/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST12-3/17/07	030708344-0007	110 Greenwich Street (roof level)	3/17/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST13-3/17/07	030708344-0008	Marriott Hotel, 38th Floor (roof level)	3/17/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST1-3/18/07	030708345-0001	Southwest Area (sidewalk bridge level)	3/18/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 15.00	No	No		
ASBESTOS-ST2-3/18/07	030708345-0002	Southeast Area (sidewalk bridge level)	3/18/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 15.00	No	No		
ASBESTOS-ST4-3/18/07	030708345-0003	Northwest Area (street-level)	3/18/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST5-3/18/07	030708345-0004	Firehouse #10 (roof level)	3/18/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST10-3/18/07	030708345-0005	North Side Sidewalk Bridge	3/18/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST11-3/18/07	030708345-0006	90 Trinity Place (roof level)	3/18/07	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST12-3/18/07	030708345-0007	110 Greenwich Street (roof level)	3/18/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST13-3/18/07	030708345-0008	Marriott Hotel, 38th Floor (roof level)	3/18/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/19/07	< 13.00	No	No		
ASBESTOS-ST1-3/19/07	030708474-0001	Southwest Area (sidewalk bridge level)	3/19/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/20/07	< 13.00	No	No		
ASBESTOS-ST2-3/19/07	030708474-0002	Southeast Area (sidewalk bridge level)	3/19/07	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/20/07	< 15.00	No	No		
ASBESTOS-ST5-3/19/07	030708474-0004	Firehouse #10 (roof level)	3/19/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/20/07	< 13.00	No	No		
ASBESTOS-ST10-3/19/07	030708474-0005	North Side Sidewalk Bridge	3/19/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/20/07	< 13.00	No	No		
ASBESTOS-ST11-3/19/07	030708474-0006	90 Trinity Place (roof level)	3/19/07	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/20/07	< 13.00	No	No		
ASBESTOS-ST12-3/19/07	030708474-0007	110 Greenwich Street (roof level)	3/19/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/20/07	< 13.00	No	No		
ASBESTOS-ST13-3/19/07	030708474-0008	Marriott Hotel, 38th Floor (roof level)	3/19/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/20/07	< 13.00	No	No		
ASBESTOS-ST14-3/19/07	030708474-0009	West Face - South end at corner (scaffolding level)	3/19/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/20/07	< 13.00	No	No		
ASBESTOS-ST15-3/19/07	030708474-0010	South Face - East end at corner (scaffolding level)	3/19/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/20/07	< 15.00	No	No		
ASBESTOS-ST16-3/19/07	030708474-0011	East Face - North end at corner (scaffolding level)	3/19/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/20/07	< 13.00	No	No		
ASBESTOS-ST17-3/19/07	030708474-0012	North Face - West end at corner (scaffolding level)	3/19/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/20/07	< 13.00	No	No		

- Note:
- Asbestos samples at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on March 17 and 18, 2007 were not available for analysis. The hoists to the scaffolding were not in service.
 - Asbestos sample at Station 4 (Northwest Area [street level]) on March 19, 2007 was not available for analysis on account of sample loss.