

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
										NA	Air Quality	Site Specific	
										70	Levels	Trigger Levels	
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-5/12/2010	031012344-0001	Southwest Area (sidewalk bridge level)	5/12/10	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/10	< 13.00	No	No	
ASBESTOS-ST2-5/12/2010	031012344-0002	Southeast Area (sidewalk bridge level)	5/12/10	1	3.260	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/10	< 13.00	No	No	
ASBESTOS-ST4-5/12/2010	031012344-0003	Northwest Area (street-level)	5/12/10	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/10	< 13.00	No	No	
ASBESTOS-ST5-5/12/2010	031012344-0004	Firehouse #10 (roof level)	5/12/10	1	2.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/10	< 13.00	No	No	
ASBESTOS-ST11-5/12/2010	031012344-0006	90 Trinity Place (roof level)	5/12/10	1	2.820	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/10	< 13.00	No	No	
ASBESTOS-ST12-5/12/2010	031012344-0007	110 Greenwich Street (roof level)	5/12/10	1	2.600	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/10	< 13.00	No	No	
ASBESTOS-ST20-5/12/2010	031012344-0005	Northeast Area, Sidewalk Bridge	5/12/10	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/10	< 13.00	No	No	
ASBESTOS-ST21-5/12/2010	031012344-0008	Marriott Hotel, 4th Floor	5/12/10	1	2.530	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/13/10	< 11.00	No	No	
ASBESTOS-ST1-5/13/10	031012467-0001	Southwest Area (sidewalk bridge level)	5/13/10	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/14/10	< 13.00	No	No	
ASBESTOS-ST2-5/13/10	031012467-0002	Southeast Area (sidewalk bridge level)	5/13/10	1	3.020	Asbestos	SEM	EMSL	5/13/10	< 3.94	No	No	
ASBESTOS-ST4-5/13/10	031012467-0003	Northwest Area (street-level)	5/13/10	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/14/10	< 15.00	No	No	
ASBESTOS-ST5-5/13/10	031012467-0004	Firehouse #10 (roof level)	5/13/10	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/14/10	< 15.00	No	No	
ASBESTOS-ST11-5/13/10	031012467-0006	90 Trinity Place (roof level)	5/13/10	1	3.240	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/14/10	< 15.00	No	No	
ASBESTOS-ST12-5/13/10	031012467-0007	110 Greenwich Street (roof level)	5/13/10	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/14/10	< 15.00	No	No	
ASBESTOS-ST20-5/13/10	031012467-0005	Northeast Area, Sidewalk Bridge	5/13/10	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/14/10	< 15.00	No	No	
ASBESTOS-ST21-5/13/10	031012467-0008	Marriott Hotel, 4th Floor	5/13/10	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/14/10	< 15.00	No	No	
ASBESTOS-ST1-5/14/10	031012607-0001	Southwest Area (sidewalk bridge level)	5/14/10	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/10	< 13.00	No	No	
ASBESTOS-ST2-5/14/10	031012607-0002	Southeast Area (sidewalk bridge level)	5/14/10	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/10	< 13.00	No	No	
ASBESTOS-ST4-5/14/10	031012607-0003	Northwest Area (street-level)	5/14/10	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/10	< 13.00	No	No	
ASBESTOS-ST5-5/14/10	031012607-0004	Firehouse #10 (roof level)	5/14/10	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/10	< 13.00	No	No	
ASBESTOS-ST11-5/14/10	031012607-0006	90 Trinity Place (roof level)	5/14/10	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/10	< 13.00	No	No	
ASBESTOS-ST12-5/14/10	031012607-0007	110 Greenwich Street (roof level)	5/14/10	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/10	< 13.00	No	No	
ASBESTOS-ST20-5/14/10	031012607-0005	Northeast Area, Sidewalk Bridge	5/14/10	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/10	< 13.00	No	No	
ASBESTOS-ST21-5/14/10	031012607-0008	Marriott Hotel, 4th Floor	5/14/10	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/15/10	< 13.00	No	No	