

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1- 6/6/09	030914140-0001	Southwest Area (sidewalk bridge level)	6/6/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/09	< 13.00	No	No	
ASBESTOS-ST2-6/6/09	030914140-0002	Southeast Area (sidewalk bridge level)	6/6/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/09	< 13.00	No	No	
ASBESTOS-ST4-6/6/09	030914140-0003	Northwest Area (street-level)	6/6/09	1	3.190	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/09	< 13.00	No	No	
ASBESTOS-ST5-6/6/09	030914140-0004	Firehouse #10 (roof level)	6/6/09	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/09	< 13.00	No	No	
ASBESTOS-ST10-6/6/09	030914140-0005	North Side Sidewalk Bridge	6/6/09	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/09	< 13.00	No	No	
ASBESTOS-ST11-6/6/09	030914140-0006	90 Trinity Place (roof level)	6/6/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/09	< 13.00	No	No	
ASBESTOS-ST12-6/6/09	030914140-0007	110 Greenwich Street (roof level)	6/6/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/09	< 13.00	No	No	
ASBESTOS-ST13-6/6/09	030914140-0008	Marriott Hotel, 38th Floor (roof level)	6/6/09	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/09	< 13.00	No	No	
ASBESTOS-ST1-6/7/09	030914139-0001	Southwest Area (sidewalk bridge level)	6/7/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/09	< 13.00	No	No	
ASBESTOS-ST2-6/7/09	030914139-0002	Southeast Area (sidewalk bridge level)	6/7/09	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/09	< 13.00	No	No	
ASBESTOS-ST4-6/7/09	030914139-0003	Northwest Area (street-level)	6/7/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/09	< 13.00	No	No	
ASBESTOS-ST5-6/7/09	030914139-0004	Firehouse #10 (roof level)	6/7/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/09	< 13.00	No	No	
ASBESTOS-ST10-6/7/09	030914139-0005	North Side Sidewalk Bridge	6/7/09	1	3.250	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/09	< 13.00	No	No	
ASBESTOS-ST11-6/7/09	030914139-0006	90 Trinity Place (roof level)	6/7/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/09	< 13.00	No	No	
ASBESTOS-ST12-6/7/09	030914139-0007	110 Greenwich Street (roof level)	6/7/09	1	3.230	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/09	< 13.00	No	No	
ASBESTOS-ST13-6/7/09	030914139-0008	Marriott Hotel, 38th Floor (roof level)	6/7/09	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/09	< 13.00	No	No	
ASBESTOS-ST1-6/8/09	030914208-0001	Southwest Area (sidewalk bridge level)	6/8/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/9/09	< 13.00	No	No	
ASBESTOS-ST2-6/8/09	030914208-0002	Southeast Area (sidewalk bridge level)	6/8/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/9/09	< 13.00	No	No	
ASBESTOS-ST4-6/8/09	030914208-0003	Northwest Area (street-level)	6/8/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/9/09	< 13.00	No	No	
ASBESTOS-ST5-6/8/09	030914208-0004	Firehouse #10 (roof level)	6/8/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/9/09	< 13.00	No	No	
ASBESTOS-ST10-6/8/09	030914208-0005	North Side Sidewalk Bridge	6/8/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/9/09	< 13.00	No	No	
ASBESTOS-ST11-6/8/09	030914208-0006	90 Trinity Place (roof level)	6/8/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/9/09	< 13.00	No	No	
ASBESTOS-ST12-6/8/09	030914208-0007	110 Greenwich Street (roof level)	6/8/09	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/9/09	< 13.00	No	No	
ASBESTOS-ST13-6/8/09	030914208-0008	Marriott Hotel, 38th Floor (roof level)	6/8/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/9/09	< 13.00	No	No	