

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-6/13/09	030914782-0001	Southwest Area (sidewalk bridge level)	6/13/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/15/09	13.00	No	No	
ASBESTOS-ST2-6/13/09	030914782-0002	Southeast Area (sidewalk bridge level)	6/13/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/15/09	< 13.00	No	No	
ASBESTOS-ST4-6/13/09	030914782-0003	Northwest Area (street-level)	6/13/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/15/09	< 13.00	No	No	
ASBESTOS-ST5-6/13/09	030914782-0004	Firehouse #10 (roof level)	6/13/09	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/15/09	< 13.00	No	No	
ASBESTOS-ST10-6/13/09	030914782-0005	North Side Sidewalk Bridge	6/13/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/15/09	< 13.00	No	No	
ASBESTOS-ST11-6/13/09	030914782-0006	90 Trinity Place (roof level)	6/13/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/15/09	< 13.00	No	No	
ASBESTOS-ST12-6/13/09	030914782-0007	110 Greenwich Street (roof level)	6/13/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/15/09	< 13.00	No	No	
ASBESTOS-ST13-6/13/09	030914782-0008	Marriott Hotel, 38th Floor (roof level)	6/13/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/15/09	< 13.00	No	No	
ASBESTOS-ST1-6/14/09	030914753-0001	Southwest Area (sidewalk bridge level)	6/14/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/15/09	< 13.00	No	No	
ASBESTOS-ST2-6/14/09	030914753-0002	Southeast Area (sidewalk bridge level)	6/14/09	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/15/09	< 13.00	No	No	
ASBESTOS-ST4-6/14/09	030914753-0003	Northwest Area (street-level)	6/14/09	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/15/09	< 13.00	No	No	
ASBESTOS-ST5-6/14/09	030914753-0004	Firehouse #10 (roof level)	6/14/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/15/09	< 13.00	No	No	
ASBESTOS-ST10-6/14/09	030914753-0005	North Side Sidewalk Bridge	6/14/09	1	3.280	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/15/09	< 13.00	No	No	
ASBESTOS-ST11-6/14/09	030914753-0006	90 Trinity Place (roof level)	6/14/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/15/09	< 13.00	No	No	
ASBESTOS-ST12-6/14/09	030914753-0007	110 Greenwich Street (roof level)	6/14/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/15/09	< 13.00	No	No	
ASBESTOS-ST13-6/14/09	030914753-0008	Marriott Hotel, 38th Floor (roof level)	6/14/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/15/09	< 13.00	No	No	
ASBESTOS-ST1-6/15/09	030914822-0001	Southwest Area (sidewalk bridge level)	6/15/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/09	< 13.00	No	No	
ASBESTOS-ST2-6/15/09	030914822-0002	Southeast Area (sidewalk bridge level)	6/15/09	1	2.870	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/09	< 13.00	No	No	
ASBESTOS-ST4-6/15/09	030914822-0003	Northwest Area (street-level)	6/15/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/09	< 13.00	No	No	
ASBESTOS-ST5-6/15/09	030914822-0004	Firehouse #10 (roof level)	6/15/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/09	< 13.00	No	No	
ASBESTOS-ST100-6/15/09	030914822-0008	Station 10 Field Duplicate	6/15/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/09	< 13.00	No	No	
ASBESTOS-ST11-6/15/09	030914822-0005	90 Trinity Place (roof level)	6/15/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/09	< 13.00	No	No	
ASBESTOS-ST12-6/15/09	030914822-0006	110 Greenwich Street (roof level)	6/15/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/09	< 13.00	No	No	
ASBESTOS-ST13-6/15/09	030914822-0007	Marriott Hotel, 38th Floor (roof level)	6/15/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/09	< 13.00	No	No	

Note:

1. The asbestos sample from Station 10 (North Side Sidewalk Bridge) on June 15, 2009 was not available for analysis as the collection media was found disconnected from the sampling pump.