

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
										NA	Air Quality Levels	Site Specific Trigger Levels	
										70			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-6/15/07	030719702-0001	Southwest Area (sidewalk bridge level)	6/15/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST2-6/15/07	030719702-0002	Southeast Area (sidewalk bridge level)	6/15/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST4-6/15/07	030719702-0003	Northwest Area (street-level)	6/15/07	1	2.840	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST5-6/15/07	030719702-0004	Firehouse #10 (roof level)	6/15/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 15.00	No	No	
ASBESTOS-ST10-6/15/07	030719702-0005	North Side Sidewalk Bridge	6/15/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 15.00	No	No	
ASBESTOS-ST11-6/15/07	030719702-0006	90 Trinity Place (roof level)	6/15/07	1	3.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 15.00	No	No	
ASBESTOS-ST12-6/15/07	030719702-0007	110 Greenwich Street (roof level)	6/15/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 15.00	No	No	
ASBESTOS-ST13-6/15/07	030719702-0008	Marriott Hotel, 38th Floor (roof level)	6/15/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST14-6/15/07	030719702-0009	West Face - South end at corner (scaffolding level)	6/15/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST15-6/15/07	030719702-0010	South Face - East end at corner (scaffolding level)	6/15/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST16-6/15/07	030719702-0011	East Face - North end at corner (scaffolding level)	6/15/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST17-6/15/07	030719702-0012	North Face - West end at corner (scaffolding level)	6/15/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST1-6/16/07	030719703-0001	Southwest Area (sidewalk bridge level)	6/16/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST2-6/16/07	030719703-0002	Southeast Area (sidewalk bridge level)	6/16/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST4-6/16/07	030719703-0003	Northwest Area (street-level)	6/16/07	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST5-6/16/07	030719703-0004	Firehouse #10 (roof level)	6/16/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST10-6/16/07	030719703-0005	North Side Sidewalk Bridge	6/16/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST11-6/16/07	030719703-0006	90 Trinity Place (roof level)	6/16/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST12-6/16/07	030719703-0007	110 Greenwich Street (roof level)	6/16/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST13-6/16/07	030719703-0008	Marriott Hotel, 38th Floor (roof level)	6/16/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST14-6/16/07	030719703-0009	West Face - South end at corner (scaffolding level)	6/16/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST15-6/16/07	030719703-0010	South Face - East end at corner (scaffolding level)	6/16/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST16-6/16/07	030719703-0011	East Face - North end at corner (scaffolding level)	6/16/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST17-6/16/07	030719703-0012	North Face - West end at corner (scaffolding level)	6/16/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST1-6/17/07	030719704-0001	Southwest Area (sidewalk bridge level)	6/17/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST2-6/17/07	030719704-0002	Southeast Area (sidewalk bridge level)	6/17/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST4-6/17/07	030719704-0003	Northwest Area (street-level)	6/17/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST5-6/17/07	030719704-0004	Firehouse #10 (roof level)	6/17/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST10-6/17/07	030719704-0005	North Side Sidewalk Bridge	6/17/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST11-6/17/07	030719704-0006	90 Trinity Place (roof level)	6/17/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST12-6/17/07	030719704-0007	110 Greenwich Street (roof level)	6/17/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST13-6/17/07	030719704-0008	Marriott Hotel, 38th Floor (roof level)	6/17/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST14-6/17/07	030719704-0009	West Face - South end at corner (scaffolding level)	6/17/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST15-6/17/07	030719704-0010	South Face - East end at corner (scaffolding level)	6/17/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST16-6/17/07	030719704-0011	East Face - North end at corner (scaffolding level)	6/17/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	
ASBESTOS-ST17-6/17/07	030719704-0012	North Face - West end at corner (scaffolding level)	6/17/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/18/07	< 13.00	No	No	