

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA				
										70				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-6/16/06	030618633-0001	Southwest Area (sidewalk bridge level)	6/16/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST2-6/16/06	030618633-0002	Southeast Area (sidewalk bridge level)	6/16/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST4-6/16/06	030618633-0003	Northwest Area (street-level)	6/16/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST5-6/16/06	030618633-0004	Firehouse #10 (roof level)	6/16/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST10-6/16/06	030618633-0005	North Side Sidewalk Bridge	6/16/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST11-6/16/06	030618633-0006	90 Trinity Place (roof level)	6/16/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST12-6/16/06	030618633-0007	110 Greenwich Street (roof level)	6/16/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	13.00		No	No	
ASBESTOS-ST13-6/16/06	030618633-0008	Marriott Hotel, 38th Floor (roof level)	6/16/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST14-6/16/06	030618633-0009	West Face - South end at corner (scaffolding level)	6/16/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST15-6/16/06	030618633-0010	South Face - East end at corner (scaffolding level)	6/16/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST16-6/16/06	030618633-0011	East Face - North end at corner (scaffolding level)	6/16/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	13.00		No	No	
ASBESTOS-ST17-6/16/06	030618633-0012	North Face - West end at corner (scaffolding level)	6/16/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST1-6/17/06	030618632-0001	Southwest Area (sidewalk bridge level)	6/17/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST2-6/17/06	030618632-0002	Southeast Area (sidewalk bridge level)	6/17/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST4-6/17/06	030618632-0003	Northwest Area (street-level)	6/17/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST5-6/17/06	030618632-0004	Firehouse #10 (roof level)	6/17/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST10-6/17/06	030618632-0005	North Side Sidewalk Bridge	6/17/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST11-6/17/06	030618632-0006	90 Trinity Place (roof level)	6/17/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST12-6/17/06	030618632-0007	110 Greenwich Street (roof level)	6/17/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST13-6/17/06	030618632-0008	Marriott Hotel, 38th Floor (roof level)	6/17/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST14-6/17/06	030618632-0009	West Face - South end at corner (scaffolding level)	6/17/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST15-6/17/06	030618632-0010	South Face - East end at corner (scaffolding level)	6/17/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST16-6/17/06	030618632-0011	East Face - North end at corner (scaffolding level)	6/17/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST17-6/17/06	030618632-0012	North Face - West end at corner (scaffolding level)	6/17/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST1-6/18/06	030618634-0001	Southwest Area (sidewalk bridge level)	6/18/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST2-6/18/06	030618634-0002	Southeast Area (sidewalk bridge level)	6/18/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST4-6/18/06	030618634-0003	Northwest Area (street-level)	6/18/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST5-6/18/06	030618634-0004	Firehouse #10 (roof level)	6/18/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST10-6/18/06	030618634-0005	North Side Sidewalk Bridge	6/18/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST11-6/18/06	030618634-0006	90 Trinity Place (roof level)	6/18/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST12-6/18/06	030618634-0007	110 Greenwich Street (roof level)	6/18/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST13-6/18/06	030618634-0008	Marriott Hotel, 38th Floor (roof level)	6/18/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST14-6/18/06	030618634-0009	West Face - South end at corner (scaffolding level)	6/18/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST15-6/18/06	030618634-0010	South Face - East end at corner (scaffolding level)	6/18/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST16-6/18/06	030618634-0011	East Face - North end at corner (scaffolding level)	6/18/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST17-6/18/06	030618634-0012	North Face - West end at corner (scaffolding level)	6/18/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/19/06	< 13.00		No	No	
ASBESTOS-ST1-6/19/06	030618755-0001	Southwest Area (sidewalk bridge level)	6/19/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/20/06	< 13.00		No	No	
ASBESTOS-ST2-6/19/06	030618755-0002	Southeast Area (sidewalk bridge level)	6/19/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/20/06	< 13.00		No	No	
ASBESTOS-ST4-6/19/06	030618755-0003	Northwest Area (street-level)	6/19/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/20/06	< 13.00		No	No	
ASBESTOS-ST5-6/19/06	030618755-0004	Firehouse #10 (roof level)	6/19/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/20/06	< 13.00		No	No	
ASBESTOS-ST10-6/19/06	030618755-0005	North Side Sidewalk Bridge	6/19/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/20/06	< 13.00		No	No	
ASBESTOS-ST100-6/19/06	030618755-0013	Station 10 Field Duplicate	6/19/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/20/06	< 13.00		No	No	
ASBESTOS-ST11-6/19/06	030618755-0006	90 Trinity Place (roof level)	6/19/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/20/06	< 13.00		No	No	
ASBESTOS-ST12-6/19/06	030618755-0007	110 Greenwich Street (roof level)	6/19/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/20/06	< 13.00		No	No	
ASBESTOS-ST13-6/19/06	030618755-0008	Marriott Hotel, 38th Floor (roof level)	6/19/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/20/06	< 13.00		No	No	
ASBESTOS-ST14-6/19/06	030618755-0009	West Face - South end at corner (scaffolding level)	6/19/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/20/06	< 13.00		No	No	
ASBESTOS-ST15-6/19/06	030618755-0010	South Face - East end at corner (scaffolding level)	6/19/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/20/06	< 13.00		No	No	
ASBESTOS-ST16-6/19/06	030618755-0011	East Face - North end at corner (scaffolding level)	6/19/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/20/06	< 13.00		No	No	
ASBESTOS-ST17-6/19/06	030618755-0012	North Face - West end at corner (scaffolding level)	6/19/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/20/06	< 13.00		No	No	