

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
										NA	Air Quality Levels	Site Specific Trigger Levels		
										70				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-6/30/06	030620360-0001	Southwest Area (sidewalk bridge level)	6/30/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST2-6/30/06	030620360-0002	Southeast Area (sidewalk bridge level)	6/30/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST4-6/30/06	030620360-0003	Northwest Area (street-level)	6/30/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST5-6/30/06	030620360-0004	Firehouse #10 (roof level)	6/30/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST10-6/30/06	030620360-0005	North Side Sidewalk Bridge	6/30/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST11-6/30/06	030620360-0006	90 Trinity Place (roof level)	6/30/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST12-6/30/06	030620360-0007	110 Greenwich Street (roof level)	6/30/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST13-6/30/06	030620360-0008	Marriott Hotel, 38th Floor (roof level)	6/30/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST14-6/30/06	030620360-0009	West Face - South end at corner (scaffolding level)	6/30/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST15-6/30/06	030620360-0010	South Face - East end at corner (scaffolding level)	6/30/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST16-6/30/06	030620360-0011	East Face - North end at corner (scaffolding level)	6/30/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST17-6/30/06	030620360-0012	North Face - West end at corner (scaffolding level)	6/30/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST1-7/1/06	030620361-0001	Southwest Area (sidewalk bridge level)	7/1/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST2-7/1/06	030620361-0002	Southeast Area (sidewalk bridge level)	7/1/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST4-7/1/06	030620361-0003	Northwest Area (street-level)	7/1/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST5-7/1/06	030620361-0004	Firehouse #10 (roof level)	7/1/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST10-7/1/06	030620361-0005	North Side Sidewalk Bridge	7/1/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST11-7/1/06	030620361-0006	90 Trinity Place (roof level)	7/1/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST12-7/1/06	030620361-0007	110 Greenwich Street (roof level)	7/1/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST13-7/1/06	030620361-0008	Marriott Hotel, 38th Floor (roof level)	7/1/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST14-7/1/06	030620361-0009	West Face - South end at corner (scaffolding level)	7/1/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST15-7/1/06	030620361-0010	South Face - East end at corner (scaffolding level)	7/1/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST16-7/1/06	030620361-0011	East Face - North end at corner (scaffolding level)	7/1/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST17-7/1/06	030620361-0012	North Face - West end at corner (scaffolding level)	7/1/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST1-7/2/06	030620362-0001	Southwest Area (sidewalk bridge level)	7/2/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST2-7/2/06	030620362-0002	Southeast Area (sidewalk bridge level)	7/2/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST4-7/2/06	030620362-0003	Northwest Area (street-level)	7/2/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST5-7/2/06	030620362-0004	Firehouse #10 (roof level)	7/2/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST10-7/2/06	030620362-0005	North Side Sidewalk Bridge	7/2/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST11-7/2/06	030620362-0006	90 Trinity Place (roof level)	7/2/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST12-7/2/06	030620362-0007	110 Greenwich Street (roof level)	7/2/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST13-7/2/06	030620362-0008	Marriott Hotel, 38th Floor (roof level)	7/2/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST14-7/2/06	030620362-0009	West Face - South end at corner (scaffolding level)	7/2/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST15-7/2/06	030620362-0010	South Face - East end at corner (scaffolding level)	7/2/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST16-7/2/06	030620362-0011	East Face - North end at corner (scaffolding level)	7/2/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		
ASBESTOS-ST17-7/2/06	030620362-0012	North Face - West end at corner (scaffolding level)	7/2/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/06	< 13.00	No	No		