

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-7/3/09	030916786-0001	Southwest Area (sidewalk bridge level)	7/3/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST2-7/3/09	030916786-0002	Southeast Area (sidewalk bridge level)	7/3/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST4-7/3/09	030916786-0003	Northwest Area (street-level)	7/3/09	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST5-7/3/09	030916786-0004	Firehouse #10 (roof level)	7/3/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST10-7/3/09	030916786-0005	North Side Sidewalk Bridge	7/3/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST11-7/3/09	030916786-0006	90 Trinity Place (roof level)	7/3/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST12-7/3/09	030916786-0007	110 Greenwich Street (roof level)	7/3/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST13-7/3/09	030916786-0008	Marriott Hotel, 38th Floor (roof level)	7/3/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST1-7/4/09	030916788-0001	Southwest Area (sidewalk bridge level)	7/4/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST2-7/4/09	030916788-0002	Southeast Area (sidewalk bridge level)	7/4/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST4-7/4/09	030916788-0003	Northwest Area (street-level)	7/4/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST5-7/4/09	030916788-0004	Firehouse #10 (roof level)	7/4/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST10-7/4/09	030916788-0005	North Side Sidewalk Bridge	7/4/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST11-7/4/09	030916788-0006	90 Trinity Place (roof level)	7/4/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST12-7/4/09	030916788-0007	110 Greenwich Street (roof level)	7/4/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST13-7/4/09	030916788-0008	Marriott Hotel, 38th Floor (roof level)	7/4/09	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST1-7/5/09	030916789-0001	Southwest Area (sidewalk bridge level)	7/5/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST2-7/5/09	030916789-0002	Southeast Area (sidewalk bridge level)	7/5/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST4-7/5/09	030916789-0003	Northwest Area (street-level)	7/5/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST5-7/5/09	030916789-0004	Firehouse #10 (roof level)	7/5/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST10-7/5/09	030916789-0005	North Side Sidewalk Bridge	7/5/09	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	13.00	No	No	
ASBESTOS-ST11-7/5/09	030916789-0006	90 Trinity Place (roof level)	7/5/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST12-7/5/09	030916789-0007	110 Greenwich Street (roof level)	7/5/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	
ASBESTOS-ST13-7/5/09	030916789-0008	Marriott Hotel, 38th Floor (roof level)	7/5/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/6/09	< 13.00	No	No	