

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|---|----------------|---|-----------------------|------------|---------------------------------|----------|---------------------------------|------|-------------------------|--------------------------------------|-----------------------------------|--|----------|
| Target Air Quality Levels | | | | | | | | | | NA | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | | 70 | | | |
| ASBESTOS-ST1-7/11/09 | 030917549-0001 | Southwest Area (sidewalk bridge level) | 7/11/09 | 1 | 3.030 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 7/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST2-7/11/09 | 030917549-0002 | Southeast Area (sidewalk bridge level) | 7/11/09 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 7/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST4-7/11/09 | 030917549-0003 | Northwest Area (street-level) | 7/11/09 | 1 | 2.980 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 7/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST5-7/11/09 | 030917549-0004 | Firehouse #10 (roof level) | 7/11/09 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 7/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST10-7/11/09 | 030917549-0005 | North Side Sidewalk Bridge | 7/11/09 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 7/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST11-7/11/09 | 030917549-0006 | 90 Trinity Place (roof level) | 7/11/09 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 7/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST12-7/11/09 | 030917549-0007 | 110 Greenwich Street (roof level) | 7/11/09 | 1 | 3.070 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 7/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST13-7/11/09 | 030917549-0008 | Marriott Hotel, 38th Floor (roof level) | 7/11/09 | 1 | 3.030 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 7/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST1-7/12/09 | 030917532-0001 | Southwest Area (sidewalk bridge level) | 7/12/09 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 7/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST2-7/12/09 | 030917532-0002 | Southeast Area (sidewalk bridge level) | 7/12/09 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 7/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST4-7/12/09 | 030917532-0003 | Northwest Area (street-level) | 7/12/09 | 1 | 3.210 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 7/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST5-7/12/09 | 030917532-0004 | Firehouse #10 (roof level) | 7/12/09 | 1 | 3.160 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 7/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST10-7/12/09 | 030917532-0005 | North Side Sidewalk Bridge | 7/12/09 | 1 | 3.130 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 7/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST11-7/12/09 | 030917532-0006 | 90 Trinity Place (roof level) | 7/12/09 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 7/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST12-7/12/09 | 030917532-0007 | 110 Greenwich Street (roof level) | 7/12/09 | 1 | 3.110 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 7/13/09 | < 13.00 | No | No | |
| ASBESTOS-ST13-7/12/09 | 030917532-0008 | Marriott Hotel, 38th Floor (roof level) | 7/12/09 | 1 | 3.300 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 7/13/09 | < 13.00 | No | No | |