

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
										NA	Air Quality Levels	Site Specific Trigger Levels	
										70			
ASBESTOS-ST1-8/6/08	030826938-0001	Southwest Area (sidewalk bridge level)	8/6/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/08	< 15.00	No	No	
ASBESTOS-ST2-8/6/08	030826938-0002	Southeast Area (sidewalk bridge level)	8/6/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/08	< 13.00	No	No	
ASBESTOS-ST4-8/6/08	030826938-0003	Northwest Area (street-level)	8/6/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/08	< 13.00	No	No	
ASBESTOS-ST5-8/6/08	030826938-0004	Firehouse #10 (roof level)	8/6/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/08	< 15.00	No	No	
ASBESTOS-ST10-8/6/08	030826938-0005	North Side Sidewalk Bridge	8/6/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/08	< 15.00	No	No	
ASBESTOS-ST11-8/6/08	030826938-0006	90 Trinity Place (roof level)	8/6/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/08	< 15.00	No	No	
ASBESTOS-ST12-8/6/08	030826938-0007	110 Greenwich Street (roof level)	8/6/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/08	< 15.00	No	No	
ASBESTOS-ST13-8/6/08	030826938-0008	Marriott Hotel, 38th Floor (roof level)	8/6/08	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/08	< 15.00	No	No	
ASBESTOS-ST14-8/6/08	030826938-0009	West Face - South end at corner (scaffolding level)	8/6/08	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/08	< 13.00	No	No	
ASBESTOS-ST15-8/6/08	030826938-0010	South Face - East end at corner (scaffolding level)	8/6/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/08	< 15.00	No	No	
ASBESTOS-ST16-8/6/08	030826938-0011	East Face - North end at corner (scaffolding level)	8/6/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/08	< 13.00	No	No	
ASBESTOS-ST17-8/6/08	030826938-0012	North Face - West end at corner (scaffolding level)	8/6/08	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/08	< 15.00	No	No	
ASBESTOS-ST1-8/7/08	030827080-0001	Southwest Area (sidewalk bridge level)	8/7/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/8/08	< 13.00	No	No	
ASBESTOS-ST2-8/7/08	030827080-0002	Southeast Area (sidewalk bridge level)	8/7/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/8/08	< 13.00	No	No	
ASBESTOS-ST4-8/7/08	030827080-0003	Northwest Area (street-level)	8/7/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/8/08	< 13.00	No	No	
ASBESTOS-ST5-8/7/08	030827080-0004	Firehouse #10 (roof level)	8/7/08	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/8/08	< 13.00	No	No	
ASBESTOS-ST10-8/7/08	030827080-0005	North Side Sidewalk Bridge	8/7/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/8/08	< 13.00	No	No	
ASBESTOS-ST11-8/7/08	030827080-0006	90 Trinity Place (roof level)	8/7/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/8/08	< 13.00	No	No	
ASBESTOS-ST12-8/7/08	030827080-0007	110 Greenwich Street (roof level)	8/7/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/8/08	< 13.00	No	No	
ASBESTOS-ST13-8/7/08	030827080-0008	Marriott Hotel, 38th Floor (roof level)	8/7/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/8/08	< 13.00	No	No	
ASBESTOS-ST14-8/7/08	030827080-0009	West Face - South end at corner (scaffolding level)	8/7/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/8/08	< 13.00	No	No	
ASBESTOS-ST15-8/7/08	030827080-0010	South Face - East end at corner (scaffolding level)	8/7/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/8/08	< 13.00	No	No	
ASBESTOS-ST16-8/7/08	030827080-0011	East Face - North end at corner (scaffolding level)	8/7/08	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/8/08	< 13.00	No	No	
ASBESTOS-ST17-8/7/08	030827080-0012	North Face - West end at corner (scaffolding level)	8/7/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/8/08	< 13.00	No	No	
ASBESTOS-ST1-8/8/08	030827240-0001	Southwest Area (sidewalk bridge level)	8/8/08	1	3.200	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/9/08	< 13.00	No	No	
ASBESTOS-ST2-8/8/08	030827240-0002	Southeast Area (sidewalk bridge level)	8/8/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/9/08	< 13.00	No	No	
ASBESTOS-ST4-8/8/08	030827240-0003	Northwest Area (street-level)	8/8/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/9/08	< 13.00	No	No	
ASBESTOS-ST5-8/8/08	030827240-0004	Firehouse #10 (roof level)	8/8/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/9/08	< 13.00	No	No	
ASBESTOS-ST10-8/8/08	030827240-0005	North Side Sidewalk Bridge	8/8/08	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/9/08	< 13.00	No	No	
ASBESTOS-ST11-8/8/08	030827240-0006	90 Trinity Place (roof level)	8/8/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/9/08	< 13.00	No	No	
ASBESTOS-ST12-8/8/08	030827240-0007	110 Greenwich Street (roof level)	8/8/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/9/08	< 13.00	No	No	
ASBESTOS-ST13-8/8/08	030827240-0008	Marriott Hotel, 38th Floor (roof level)	8/8/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/9/08	< 13.00	No	No	
ASBESTOS-ST14-8/8/08	030827240-0009	West Face - South end at corner (scaffolding level)	8/8/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/9/08	< 13.00	No	No	
ASBESTOS-ST15-8/8/08	030827240-0010	South Face - East end at corner (scaffolding level)	8/8/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/9/08	< 13.00	No	No	
ASBESTOS-ST16-8/8/08	030827240-0011	East Face - North end at corner (scaffolding level)	8/8/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/9/08	< 13.00	No	No	
ASBESTOS-ST17-8/8/08	030827240-0012	North Face - West end at corner (scaffolding level)	8/8/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/9/08	< 13.00	No	No	