

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|---|----------------|---|-----------------------|------------|---------------------------------|----------|---------------------------------|------|-------------------------|--------------------------------------|-----------------------------------|--|----------|
| Target Air Quality Levels | | | | | | | | | | NA | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | | 70 | | | |
| ASBESTOS-ST1-8/17/09 | 030921402-0001 | Southwest Area (sidewalk bridge level) | 8/17/09 | 1 | 3.070 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/18/09 | < 13.00 | No | No | |
| ASBESTOS-ST2-8/17/09 | 030921402-0002 | Southeast Area (sidewalk bridge level) | 8/17/09 | 1 | 3.090 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/18/09 | < 13.00 | No | No | |
| ASBESTOS-ST4-8/17/09 | 030921402-0003 | Northwest Area (street-level) | 8/17/09 | 1 | 3.030 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/18/09 | < 13.00 | No | No | |
| ASBESTOS-ST5-8/17/09 | 030921402-0004 | Firehouse #10 (roof level) | 8/17/09 | 1 | 3.310 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/18/09 | < 13.00 | No | No | |
| ASBESTOS-ST10-8/17/09 | 030921402-0005 | North Side Sidewalk Bridge | 8/17/09 | 1 | 3.070 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/18/09 | < 13.00 | No | No | |
| ASBESTOS-ST11-8/17/09 | 030921402-0006 | 90 Trinity Place (roof level) | 8/17/09 | 1 | 3.130 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/18/09 | < 13.00 | No | No | |
| ASBESTOS-ST12-8/17/09 | 030921402-0007 | 110 Greenwich Street (roof level) | 8/17/09 | 1 | 2.960 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/18/09 | < 13.00 | No | No | |
| ASBESTOS-ST13-8/17/09 | 030921402-0008 | Marriott Hotel, 38th Floor (roof level) | 8/17/09 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/18/09 | < 13.00 | No | No | |
| ASBESTOS-ST1-8/18/09 | 030921519-0001 | Southwest Area (sidewalk bridge level) | 8/18/09 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/19/09 | < 13.00 | No | No | |
| ASBESTOS-ST2-8/18/09 | 030921519-0002 | Southeast Area (sidewalk bridge level) | 8/18/09 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/19/09 | < 13.00 | No | No | |
| ASBESTOS-ST4-8/18/09 | 030921519-0003 | Northwest Area (street-level) | 8/18/09 | 1 | 3.180 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/19/09 | < 13.00 | No | No | |
| ASBESTOS-ST5-8/18/09 | 030921519-0004 | Firehouse #10 (roof level) | 8/18/09 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/19/09 | < 13.00 | No | No | |
| ASBESTOS-ST10-8/18/09 | 030921519-0005 | North Side Sidewalk Bridge | 8/18/09 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/19/09 | < 13.00 | No | No | |
| ASBESTOS-ST11-8/18/09 | 030921519-0006 | 90 Trinity Place (roof level) | 8/18/09 | 1 | 3.050 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/19/09 | < 13.00 | No | No | |
| ASBESTOS-ST12-8/18/09 | 030921519-0007 | 110 Greenwich Street (roof level) | 8/18/09 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/19/09 | < 13.00 | No | No | |
| ASBESTOS-ST13-8/18/09 | 030921519-0008 | Marriott Hotel, 38th Floor (roof level) | 8/18/09 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/19/09 | < 13.00 | No | No | |