

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-8/26/09	030922343-0001	Southwest Area (sidewalk bridge level)	8/26/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/27/09	< 13.00	No	No	
ASBESTOS-ST2-8/26/09	030922343-0002	Southeast Area (sidewalk bridge level)	8/26/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/27/09	< 13.00	No	No	
ASBESTOS-ST4-8/26/09	030922343-0003	Northwest Area (street-level)	8/26/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/27/09	< 13.00	No	No	
ASBESTOS-ST5-8/26/09	030922343-0004	Firehouse #10 (roof level)	8/26/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/27/09	< 13.00	No	No	
ASBESTOS-ST10-8/26/09	030922343-0005	North Side Sidewalk Bridge	8/26/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/27/09	< 13.00	No	No	
ASBESTOS-ST11-8/26/09	030922343-0006	90 Trinity Place (roof level)	8/26/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/27/09	< 13.00	No	No	
ASBESTOS-ST12-8/26/09	030922343-0007	110 Greenwich Street (roof level)	8/26/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/27/09	< 13.00	No	No	
ASBESTOS-ST13-8/26/09	030922343-0008	Marriott Hotel, 38th Floor (roof level)	8/26/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/27/09	< 13.00	No	No	
ASBESTOS-ST1-8/27/09	030922462-0001	Southwest Area (sidewalk bridge level)	8/27/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/09	< 13.00	No	No	
ASBESTOS-ST2-8/27/09	030922462-0002	Southeast Area (sidewalk bridge level)	8/27/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/09	< 13.00	No	No	
ASBESTOS-ST4-8/27/09	030922462-0003	Northwest Area (street-level)	8/27/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/09	< 13.00	No	No	
ASBESTOS-ST5-8/27/09	030922462-0004	Firehouse #10 (roof level)	8/27/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/09	< 13.00	No	No	
ASBESTOS-ST10-8/27/09	030922462-0005	North Side Sidewalk Bridge	8/27/09	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/09	< 13.00	No	No	
ASBESTOS-ST11-8/27/09	030922462-0006	90 Trinity Place (roof level)	8/27/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/09	< 13.00	No	No	
ASBESTOS-ST12-8/27/09	030922462-0007	110 Greenwich Street (roof level)	8/27/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/09	< 13.00	No	No	
ASBESTOS-ST13-8/27/09	030922462-0008	Marriott Hotel, 38th Floor (roof level)	8/27/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/09	< 13.00	No	No	
ASBESTOS-ST1-8/28/09	030922539-0001	Southwest Area (sidewalk bridge level)	8/28/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/09	< 13.00	No	No	
ASBESTOS-ST2-8/28/09	030922539-0002	Southeast Area (sidewalk bridge level)	8/28/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/09	< 13.00	No	No	
ASBESTOS-ST4-8/28/09	030922539-0003	Northwest Area (street-level)	8/28/09	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/09	< 13.00	No	No	
ASBESTOS-ST5-8/28/09	030922539-0004	Firehouse #10 (roof level)	8/28/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/09	< 13.00	No	No	
ASBESTOS-ST10-8/28/09	030922539-0005	North Side Sidewalk Bridge	8/28/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/09	< 13.00	No	No	
ASBESTOS-ST100-8/28/09	030922539-0009	Station 10 Field Duplicate	8/28/09	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/09	< 13.00	No	No	
ASBESTOS-ST11-8/28/09	030922539-0006	90 Trinity Place (roof level)	8/28/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/09	< 13.00	No	No	
ASBESTOS-ST12-8/28/09	030922539-0007	110 Greenwich Street (roof level)	8/28/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/09	< 13.00	No	No	
ASBESTOS-ST13-8/28/09	030922539-0008	Marriott Hotel, 38th Floor (roof level)	8/28/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/09	< 13.00	No	No	