

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-9/1/09	030922867-0001	Southwest Area (sidewalk bridge level)	9/1/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/09	< 13.00	No	No	
ASBESTOS-ST2-9/1/09	030922867-0002	Southeast Area (sidewalk bridge level)	9/1/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/09	< 13.00	No	No	
ASBESTOS-ST4-9/1/09	030922867-0003	Northwest Area (street-level)	9/1/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/09	< 13.00	No	No	
ASBESTOS-ST5-9/1/09	030922867-0004	Firehouse #10 (roof level)	9/1/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/09	< 13.00	No	No	
ASBESTOS-ST10-9/1/09	030922867-0005	North Side Sidewalk Bridge	9/1/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/09	< 13.00	No	No	
ASBESTOS-ST11-9/1/09	030922867-0006	90 Trinity Place (roof level)	9/1/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/09	< 13.00	No	No	
ASBESTOS-ST12-9/1/09	030922867-0007	110 Greenwich Street (roof level)	9/1/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/09	< 13.00	No	No	
ASBESTOS-ST13-9/1/09	030922867-0008	Marriott Hotel, 38th Floor (roof level)	9/1/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/09	< 13.00	No	No	
ASBESTOS-ST1-9/2/09	030922975-0001	Southwest Area (sidewalk bridge level)	9/2/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/09	< 13.00	No	No	
ASBESTOS-ST2-9/2/09	030922975-0002	Southeast Area (sidewalk bridge level)	9/2/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/09	< 13.00	No	No	
ASBESTOS-ST4-9/2/09	030922975-0003	Northwest Area (street-level)	9/2/09	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/09	< 13.00	No	No	
ASBESTOS-ST5-9/2/09	030922975-0004	Firehouse #10 (roof level)	9/2/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/09	< 13.00	No	No	
ASBESTOS-ST10-9/2/09	030922975-0005	North Side Sidewalk Bridge	9/2/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/09	< 13.00	No	No	
ASBESTOS-ST11-9/2/09	030922975-0006	90 Trinity Place (roof level)	9/2/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/09	< 13.00	No	No	
ASBESTOS-ST12-9/2/09	030922975-0007	110 Greenwich Street (roof level)	9/2/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/09	< 13.00	No	No	
ASBESTOS-ST13-9/2/09	030922975-0008	Marriott Hotel, 38th Floor (roof level)	9/2/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/09	< 13.00	No	No	
ASBESTOS-ST1-9/3/09	030923085-0001	Southwest Area (sidewalk bridge level)	9/3/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/4/09	< 13.00	No	No	
ASBESTOS-ST2-9/3/09	030923085-0002	Southeast Area (sidewalk bridge level)	9/3/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/4/09	< 13.00	No	No	
ASBESTOS-ST4-9/3/09	030923085-0003	Northwest Area (street-level)	9/3/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/4/09	< 13.00	No	No	
ASBESTOS-ST5-9/3/09	030923085-0004	Firehouse #10 (roof level)	9/3/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/4/09	< 13.00	No	No	
ASBESTOS-ST10-9/3/09	030923085-0005	North Side Sidewalk Bridge	9/3/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/4/09	< 13.00	No	No	
ASBESTOS-ST11-9/3/09	030923085-0006	90 Trinity Place (roof level)	9/3/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/4/09	< 13.00	No	No	
ASBESTOS-ST12-9/3/09	030923085-0007	110 Greenwich Street (roof level)	9/3/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/4/09	< 13.00	No	No	
ASBESTOS-ST13-9/3/09	030923085-0008	Marriott Hotel, 38th Floor (roof level)	9/3/09	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/4/09	< 13.00	No	No	
ASBESTOS-ST1-9/4/09	030923144-0001	Southwest Area (sidewalk bridge level)	9/4/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/5/09	< 13.00	No	No	
ASBESTOS-ST2-9/4/09	030923144-0002	Southeast Area (sidewalk bridge level)	9/4/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/5/09	< 13.00	No	No	
ASBESTOS-ST4-9/4/09	030923144-0003	Northwest Area (street-level)	9/4/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/5/09	< 13.00	No	No	
ASBESTOS-ST5-9/4/09	030923144-0004	Firehouse #10 (roof level)	9/4/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/5/09	< 13.00	No	No	
ASBESTOS-ST10-9/4/09	030923144-0005	North Side Sidewalk Bridge	9/4/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/5/09	< 13.00	No	No	
ASBESTOS-ST11-9/4/09	030923144-0006	90 Trinity Place (roof level)	9/4/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/5/09	< 13.00	No	No	
ASBESTOS-ST12-9/4/09	030923144-0007	110 Greenwich Street (roof level)	9/4/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/5/09	< 13.00	No	No	
ASBESTOS-ST13-9/4/09	030923144-0008	Marriott Hotel, 38th Floor (roof level)	9/4/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/5/09	< 13.00	No	No	