

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels											70	Levels	Trigger Levels	
ASBESTOS-ST1-9/8/06	030629844-0001	Southwest Area (sidewalk bridge level)	9/8/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/12/06	< 13.00	No	No		
ASBESTOS-ST2-9/8/06	030629844-0002	Southeast Area (sidewalk bridge level)	9/8/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/12/06	< 13.00	No	No		
ASBESTOS-ST4-9/8/06	030629844-0003	Northwest Area (street-level)	9/8/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/12/06	< 13.00	No	No		
ASBESTOS-ST5-9/8/06	030629844-0004	Firehouse #10 (roof level)	9/8/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/12/06	< 13.00	No	No		
ASBESTOS-ST6-9/8/06	030629852-0001	Southwest Area (roof level)	9/8/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/12/06	< 13.00	No	No		
ASBESTOS-ST7-9/8/06	030629852-0002	Southeast Area (roof level)	9/8/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/12/06	< 13.00	No	No		
ASBESTOS-ST8-9/8/06	030629852-0003	Northeast Area (roof level)	9/8/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/12/06	< 13.00	No	No		
ASBESTOS-ST9-9/8/06	030629852-0004	Northwest Area (roof level)	9/8/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/12/06	< 13.00	No	No		
ASBESTOS-ST10-9/8/06	030629844-0005	North Side Sidewalk Bridge	9/8/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/12/06	< 13.00	No	No		
ASBESTOS-ST11-9/8/06	030629844-0006	90 Trinity Place (roof level)	9/8/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/12/06	< 13.00	No	No		
ASBESTOS-ST12-9/8/06	030629844-0007	110 Greenwich Street (roof level)	9/8/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/12/06	< 13.00	No	No		
ASBESTOS-ST13-9/8/06	030629844-0008	Marriott Hotel, 38th Floor (roof level)	9/8/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/12/06	< 13.00	No	No		
ASBESTOS-ST14-9/8/06	030629844-0009	West Face - South end at corner (scaffolding level)	9/8/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/12/06	< 13.00	No	No		
ASBESTOS-ST15-9/8/06	030629844-0010	South Face - East end at corner (scaffolding level)	9/8/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/12/06	< 13.00	No	No		
ASBESTOS-ST16-9/8/06	030629844-0011	East Face - North end at corner (scaffolding level)	9/8/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/12/06	< 13.00	No	No		
ASBESTOS-ST17-9/8/06	030629844-0012	North Face - West end at corner (scaffolding level)	9/8/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/12/06	< 13.00	No	No		
ASBESTOS-ST1-9/12/06	030629991-0001	Southwest Area (sidewalk bridge level)	9/12/06	1	3.400	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/06	< 13.00	No	No	Note 1	
ASBESTOS-ST2-9/12/06	030629991-0002	Southeast Area (sidewalk bridge level)	9/12/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/06	< 13.00	No	No		
ASBESTOS-ST4-9/12/06	030629991-0003	Northwest Area (street-level)	9/12/06	1	3.470	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/06	< 13.00	No	No	Note 1	
ASBESTOS-ST5-9/12/06	030629991-0004	Firehouse #10 (roof level)	9/12/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/06	< 13.00	No	No		
ASBESTOS-ST6-9/12/06	030630004-0001	Southwest Area (roof level)	9/12/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/06	< 13.00	No	No		
ASBESTOS-ST7-9/12/06	030630004-0002	Southeast Area (roof level)	9/12/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/06	< 13.00	No	No		
ASBESTOS-ST8-9/12/06	030630004-0003	Northeast Area (roof level)	9/12/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/06	< 13.00	No	No		
ASBESTOS-ST9-9/12/06	030630004-0004	Northwest Area (roof level)	9/12/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/06	< 13.00	No	No		
ASBESTOS-ST10-9/12/06	030629991-0005	North Side Sidewalk Bridge	9/12/06	1	3.280	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/06	< 13.00	No	No		
ASBESTOS-ST100-9/12/06	030629991-0013	Station 10 Field Duplicate	9/12/06	1	3.340	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/06	< 13.00	No	No		
ASBESTOS-ST11-9/12/06	030629991-0006	90 Trinity Place (roof level)	9/12/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/06	< 13.00	No	No		
ASBESTOS-ST12-9/12/06	030629991-0007	110 Greenwich Street (roof level)	9/12/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/06	< 13.00	No	No		
ASBESTOS-ST13-9/12/06	030629991-0008	Marriott Hotel, 38th Floor (roof level)	9/12/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/06	< 13.00	No	No		
ASBESTOS-ST14-9/12/06	030629991-0009	West Face - South end at corner (scaffolding level)	9/12/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/06	< 13.00	No	No		
ASBESTOS-ST15-9/12/06	030629991-0010	South Face - East end at corner (scaffolding level)	9/12/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/06	< 13.00	No	No		
ASBESTOS-ST16-9/12/06	030629991-0011	East Face - North end at corner (scaffolding level)	9/12/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/06	< 13.00	No	No		
ASBESTOS-ST17-9/12/06	030629991-0012	North Face - West end at corner (scaffolding level)	9/12/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/06	< 13.00	No	No		

Note:

1. Due to a flow rate RPD exceedances (22.2% and 25.5%) for asbestos at Station 1 (Southwest Area [sidewalk bridge level]) and Station 4 (Northwest Area [street-level]), respectively, on September 12, 2006, the sample volume and subsequent sample result are estimated.
2. Asbestos samples at all stations on September 9, 10, and 11, 2006 were not able to be collected; site access prohibited due to September 11 anniversary security measures.