

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>										NA			
<b>EPA Site Specific Trigger Levels</b>										70			
ASBESTOS-ST1-9/14/09	030923682-0001	Southwest Area (sidewalk bridge level)	9/14/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/15/09	< 13.00	No	No	
ASBESTOS-ST2-9/14/09	030923682-0002	Southeast Area (sidewalk bridge level)	9/14/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/15/09	< 13.00	No	No	
ASBESTOS-ST4-9/14/09	030923682-0003	Northwest Area (street-level)	9/14/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/15/09	< 13.00	No	No	
ASBESTOS-ST5-9/14/09	030923682-0004	Firehouse #10 (roof level)	9/14/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/15/09	< 13.00	No	No	
ASBESTOS-ST10-9/14/09	030923682-0005	North Side Sidewalk Bridge	9/14/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/15/09	< 13.00	No	No	
ASBESTOS-ST11-9/14/09	030923682-0006	90 Trinity Place (roof level)	9/14/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/15/09	< 13.00	No	No	
ASBESTOS-ST12-9/14/09	030923682-0007	110 Greenwich Street (roof level)	9/14/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/15/09	< 13.00	No	No	
ASBESTOS-ST13-9/14/09	030923682-0008	Marriott Hotel, 38th Floor (roof level)	9/14/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/15/09	< 13.00	No	No	
ASBESTOS-ST1-9/15/09	030923784-0001	Southwest Area (sidewalk bridge level)	9/15/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/16/09	< 13.00	No	No	
ASBESTOS-ST2-9/15/09	030923784-0002	Southeast Area (sidewalk bridge level)	9/15/09	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/16/09	< 13.00	No	No	
ASBESTOS-ST4-9/15/09	030923784-0003	Northwest Area (street-level)	9/15/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/16/09	< 13.00	No	No	
ASBESTOS-ST5-9/15/09	030923784-0004	Firehouse #10 (roof level)	9/15/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/16/09	< 13.00	No	No	
ASBESTOS-ST10-9/15/09	030923784-0005	North Side Sidewalk Bridge	9/15/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/16/09	< 13.00	No	No	
ASBESTOS-ST11-9/15/09	030923784-0006	90 Trinity Place (roof level)	9/15/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/16/09	< 13.00	No	No	
ASBESTOS-ST12-9/15/09	030923784-0007	110 Greenwich Street (roof level)	9/15/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/16/09	< 13.00	No	No	
ASBESTOS-ST13-9/15/09	030923784-0008	Marriott Hotel, 38th Floor (roof level)	9/15/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/16/09	< 13.00	No	No	