

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-10/5/05	030529961-0001	Southwest Area (street-level)	10/5/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/2005	< 19.00	No	No	
ASBESTOS-ST2-10/5/05	030529961-0002	Southeast Area (street-level)	10/5/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/2005	< 19.00	No	No	
ASBESTOS-ST4-10/5/05	030529961-0003	Northwest Area (street-level)	10/5/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/2005	< 19.00	No	No	
ASBESTOS-ST5-10/5/05	030529961-0004	Firehouse #10 (roof level)	10/5/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/2005	< 19.00	No	No	
ASBESTOS-ST10-10/5/05	030529961-0005	North Side Sidewalk Bridge	10/5/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/2005	< 19.00	No	No	
ASBESTOS-ST11-10/5/05	030529961-0006	90 Trinity Place (roof level)	10/5/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/2005	< 19.00	No	No	
ASBESTOS-ST13-10/5/05	030529961-0007	Marriott Hotel, 38th Floor (roof level)	10/5/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/2005	< 19.00	No	No	
ASBESTOS-ST1-10/6/05	030530065-0001	Southwest Area (street-level)	10/6/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/7/2005	< 13.00	No	No	
ASBESTOS-ST2-10/6/05	030530065-0002	Southeast Area (street-level)	10/6/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/7/2005	< 13.00	No	No	
ASBESTOS-ST4-10/6/05	030530065-0003	Northwest Area (street-level)	10/6/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/7/2005	< 13.00	No	No	
ASBESTOS-ST5-10/6/05	030530065-0004	Firehouse #10 (roof level)	10/6/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/7/2005	< 13.00	No	No	
ASBESTOS-ST10-10/6/05	030530065-0005	North Side Sidewalk Bridge	10/6/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/7/2005	< 13.00	No	No	
ASBESTOS-ST100-10/6/05	030530065-0009	Station 10 Field Duplicate	10/6/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/7/2005	< 13.00	No	No	
ASBESTOS-ST11-10/6/05	030530065-0006	90 Trinity Place (roof level)	10/6/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/7/2005	< 13.00	No	No	
ASBESTOS-ST12-10/6/05	030530065-0007	110 Greenwich Street (roof level)	10/6/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/7/2005	< 13.00	No	No	
ASBESTOS-ST13-10/6/05	030530065-0008	Marriott Hotel, 38th Floor (roof level)	10/6/2005	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/7/2005	< 13.00	No	No	