

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
										NA	Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
										70			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-10/7/09	030925736-0001	Southwest Area (sidewalk bridge level)	10/7/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/8/09	< 13.00	No	No	
ASBESTOS-ST2-10/7/09	030925736-0002	Southeast Area (sidewalk bridge level)	10/7/09	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/8/09	< 13.00	No	No	
ASBESTOS-ST4-10/7/09	030925736-0003	Northwest Area (street-level)	10/7/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/8/09	< 13.00	No	No	
ASBESTOS-ST5-10/7/09	030925736-0004	Firehouse #10 (roof level)	10/7/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/8/09	< 13.00	No	No	
ASBESTOS-ST10-10/7/09	030925736-0005	North Side Sidewalk Bridge	10/7/09	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/8/09	< 13.00	No	No	
ASBESTOS-ST11-10/7/09	030925736-0006	90 Trinity Place (roof level)	10/7/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/8/09	< 13.00	No	No	
ASBESTOS-ST12-10/7/09	030925736-0007	110 Greenwich Street (roof level)	10/7/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/8/09	< 13.00	No	No	
ASBESTOS-ST13-10/7/09	030925736-0008	Marriott Hotel, 38th Floor (roof level)	10/7/09	1	3.190	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/8/09	< 13.00	No	No	
ASBESTOS-ST1-10/8/09	030925831-0001	Southwest Area (sidewalk bridge level)	10/8/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/9/09	< 13.00	No	No	
ASBESTOS-ST2-10/8/09	030925831-0002	Southeast Area (sidewalk bridge level)	10/8/09	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/9/09	< 13.00	No	No	
ASBESTOS-ST4-10/8/09	030925831-0003	Northwest Area (street-level)	10/8/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/9/09	< 13.00	No	No	
ASBESTOS-ST5-10/8/09	030925831-0004	Firehouse #10 (roof level)	10/8/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/9/09	< 13.00	No	No	
ASBESTOS-ST10-10/8/09	030925831-0005	North Side Sidewalk Bridge	10/8/09	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/9/09	< 13.00	No	No	
ASBESTOS-ST11-10/8/09	030925831-0006	90 Trinity Place (roof level)	10/8/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/9/09	< 13.00	No	No	
ASBESTOS-ST12-10/8/09	030925831-0007	110 Greenwich Street (roof level)	10/8/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/9/09	< 13.00	No	No	
ASBESTOS-ST13-10/8/09	030925831-0008	Marriott Hotel, 38th Floor (roof level)	10/8/09	1	2.810	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/9/09	< 13.00	No	No	
ASBESTOS-ST1-10/9/09	030925901-0001	Southwest Area (sidewalk bridge level)	10/9/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/10/09	< 13.00	No	No	
ASBESTOS-ST2-10/9/09	030925901-0002	Southeast Area (sidewalk bridge level)	10/9/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/10/09	< 13.00	No	No	
ASBESTOS-ST4-10/9/09	030925901-0003	Northwest Area (street-level)	10/9/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/10/09	< 13.00	No	No	
ASBESTOS-ST5-10/9/09	030925901-0004	Firehouse #10 (roof level)	10/9/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/10/09	< 13.00	No	No	
ASBESTOS-ST10-10/9/09	030925901-0005	North Side Sidewalk Bridge	10/9/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/10/09	< 13.00	No	No	
ASBESTOS-ST11-10/9/09	030925901-0006	90 Trinity Place (roof level)	10/9/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/10/09	< 13.00	No	No	
ASBESTOS-ST12-10/9/09	030925901-0007	110 Greenwich Street (roof level)	10/9/09	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/10/09	< 15.00	No	No	
ASBESTOS-ST13-10/9/09	030925901-0008	Marriott Hotel, 38th Floor (roof level)	10/9/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/10/09	< 13.00	No	No	