

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels											Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels											NA		
											70		
ASBESTOS-ST1-10/12/09	030926118-0001	Southwest Area (sidewalk bridge level)	10/12/09	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/13/09	< 13.00	No	No	
ASBESTOS-ST2-10/12/09	030926118-0002	Southeast Area (sidewalk bridge level)	10/12/09	1	3.200	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/13/09	< 13.00	No	No	
ASBESTOS-ST4-10/12/09	030926118-0003	Northwest Area (street-level)	10/12/09	1	3.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/13/09	< 13.00	No	No	
ASBESTOS-ST5-10/12/09	030926118-0004	Firehouse #10 (roof level)	10/12/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/13/09	< 13.00	No	No	
ASBESTOS-ST10-10/12/09	030926118-0005	North Side Sidewalk Bridge	10/12/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/13/09	< 13.00	No	No	
ASBESTOS-ST11-10/12/09	030926118-0006	90 Trinity Place (roof level)	10/12/09	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/13/09	< 13.00	No	No	
ASBESTOS-ST12-10/12/09	030926118-0007	110 Greenwich Street (roof level)	10/12/09	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/13/09	< 13.00	No	No	
ASBESTOS-ST13-10/12/09	030926118-0008	Marriott Hotel, 38th Floor (roof level)	10/12/09	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/13/09	< 13.00	No	No	
ASBESTOS-ST1-10/13/09	030926234-0001	Southwest Area (sidewalk bridge level)	10/13/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/14/09	< 13.00	No	No	
ASBESTOS-ST2-10/13/09	030926234-0002	Southeast Area (sidewalk bridge level)	10/13/09	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/14/09	< 13.00	No	No	
ASBESTOS-ST4-10/13/09	030926234-0003	Northwest Area (street-level)	10/13/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/14/09	< 13.00	No	No	
ASBESTOS-ST5-10/13/09	030926234-0004	Firehouse #10 (roof level)	10/13/09	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/14/09	< 13.00	No	No	
ASBESTOS-ST10-10/13/09	030926234-0005	North Side Sidewalk Bridge	10/13/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/14/09	< 13.00	No	No	
ASBESTOS-ST100-10/13/09	030926234-0009	Station 10 Field Duplicate	10/13/09	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/14/09	< 13.00	No	No	
ASBESTOS-ST11-10/13/09	030926234-0006	90 Trinity Place (roof level)	10/13/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/14/09	< 13.00	No	No	
ASBESTOS-ST12-10/13/09	030926234-0007	110 Greenwich Street (roof level)	10/13/09	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/14/09	< 13.00	No	No	
ASBESTOS-ST13-10/13/09	030926234-0008	Marriott Hotel, 38th Floor (roof level)	10/13/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/14/09	< 13.00	No	No	

Note:

- Asbestos sample results are not available on October 11, 2009 since no sampling was conducted on this day due to the lack of work activities. This is in accordance with Amendment #9 to the September 2005 Ambient Air Monitoring Program Plan.