

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA			
										70			
ASBESTOS-ST1-11/2/05	030532895-0001	Southwest Area (street-level)	11/2/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/3/2005	< 13.00	No	No	
ASBESTOS-ST2-11/2/05	030532895-0002	Southeast Area (sidewalk bridge level)	11/2/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/3/2005	< 13.00	No	No	
ASBESTOS-ST4-11/2/05	030532895-0003	Northwest Area (street-level)	11/2/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/3/2005	< 13.00	No	No	
ASBESTOS-ST5-11/2/05	030532895-0004	Firehouse #10 (roof level)	11/2/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/3/2005	< 13.00	No	No	
ASBESTOS-ST10-11/2/05	030532895-0005	North Side Sidewalk Bridge	11/2/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/3/2005	< 13.00	No	No	
ASBESTOS-ST11-11/2/05	030532895-0006	90 Trinity Place (roof level)	11/2/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/3/2005	< 13.00	No	No	
ASBESTOS-ST12-11/2/05	030532895-0007	110 Greenwich Street (roof level)	11/2/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/3/2005	< 13.00	No	No	
ASBESTOS-ST13-11/2/05	030532895-0008	Marriott Hotel, 38th Floor (roof level)	11/2/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/3/2005	< 13.00	No	No	
ASBESTOS-ST1-11/3/05	030533037-0001	Southwest Area (street-level)	11/3/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/4/2005	< 13.00	No	No	
ASBESTOS-ST2-11/3/05	030533037-0002	Southeast Area (sidewalk bridge level)	11/3/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/4/2005	< 13.00	No	No	
ASBESTOS-ST4-11/3/05	030533037-0003	Northwest Area (street-level)	11/3/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/4/2005	< 13.00	No	No	
ASBESTOS-ST5-11/3/05	030533037-0004	Firehouse #10 (roof level)	11/3/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/4/2005	< 13.00	No	No	
ASBESTOS-ST10-11/3/05	030533037-0005	North Side Sidewalk Bridge	11/3/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/4/2005	< 13.00	No	No	
ASBESTOS-ST11-11/3/05	030533037-0006	90 Trinity Place (roof level)	11/3/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/4/2005	< 13.00	No	No	
ASBESTOS-ST12-11/3/05	030533037-0007	110 Greenwich Street (roof level)	11/3/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/4/2005	< 13.00	No	No	
ASBESTOS-ST13-11/3/05	030533037-0008	Marriott Hotel, 38th Floor (roof level)	11/3/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/4/2005	< 13.00	No	No	