

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality Levels	Site Specific Trigger Levels	Comments
EPA Site Specific Trigger Levels											70			
ASBESTOS-ST1-11/15/07	030736866-0001	Southwest Area (sidewalk bridge level)	11/15/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST2-11/15/07	030736866-0002	Southeast Area (sidewalk bridge level)	11/15/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST4-11/15/07	030736866-0003	Northwest Area (street-level)	11/15/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST5-11/15/07	030736866-0004	Firehouse #10 (roof level)	11/15/07	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST10-11/15/07	030736866-0005	North Side Sidewalk Bridge	11/15/07	1	2.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 9.60	No	No	Note 1	
ASBESTOS-ST11-11/15/07	030736866-0006	90 Trinity Place (roof level)	11/15/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST12-11/15/07	030736866-0007	110 Greenwich Street (roof level)	11/15/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST13-11/15/07	030736866-0008	Marriott Hotel, 38th Floor (roof level)	11/15/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST14-11/15/07	030736866-0009	West Face - South end at corner (scaffolding level)	11/15/07	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST15-11/15/07	030736866-0010	South Face - East end at corner (scaffolding level)	11/15/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST16-11/15/07	030736866-0011	East Face - North end at corner (scaffolding level)	11/15/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST17-11/15/07	030736866-0012	North Face - West end at corner (scaffolding level)	11/15/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST1-11/16/07	030736868-0001	Southwest Area (sidewalk bridge level)	11/16/07	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST2-11/16/07	030736868-0002	Southeast Area (sidewalk bridge level)	11/16/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST4-11/16/07	030736868-0003	Northwest Area (street-level)	11/16/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST5-11/16/07	030736868-0004	Firehouse #10 (roof level)	11/16/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST10-11/16/07	030736868-0005	North Side Sidewalk Bridge	11/16/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST11-11/16/07	030736868-0006	90 Trinity Place (roof level)	11/16/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST12-11/16/07	030736868-0007	110 Greenwich Street (roof level)	11/16/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST13-11/16/07	030736868-0008	Marriott Hotel, 38th Floor (roof level)	11/16/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST14-11/16/07	030736868-0009	West Face - South end at corner (scaffolding level)	11/16/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST15-11/16/07	030736868-0010	South Face - East end at corner (scaffolding level)	11/16/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST16-11/16/07	030736868-0011	East Face - North end at corner (scaffolding level)	11/16/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST17-11/16/07	030736868-0012	North Face - West end at corner (scaffolding level)	11/16/07	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/17/07	< 13.00	No	No		
ASBESTOS-ST1-11/17/07	030736965-0001	Southwest Area (sidewalk bridge level)	11/17/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No		
ASBESTOS-ST2-11/17/07	030736965-0002	Southeast Area (sidewalk bridge level)	11/17/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No		
ASBESTOS-ST4-11/17/07	030736965-0003	Northwest Area (street-level)	11/17/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No		
ASBESTOS-ST5-11/17/07	030736965-0004	Firehouse #10 (roof level)	11/17/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No		
ASBESTOS-ST10-11/17/07	030736965-0005	North Side Sidewalk Bridge	11/17/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No		
ASBESTOS-ST11-11/17/07	030736965-0006	90 Trinity Place (roof level)	11/17/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No		
ASBESTOS-ST12-11/17/07	030736965-0007	110 Greenwich Street (roof level)	11/17/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No		
ASBESTOS-ST13-11/17/07	030736965-0008	Marriott Hotel, 38th Floor (roof level)	11/17/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No		
ASBESTOS-ST14-11/17/07	030736965-0009	West Face - South end at corner (scaffolding level)	11/17/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No		
ASBESTOS-ST15-11/17/07	030736965-0010	South Face - East end at corner (scaffolding level)	11/17/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No		
ASBESTOS-ST16-11/17/07	030736965-0011	East Face - North end at corner (scaffolding level)	11/17/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No		
ASBESTOS-ST17-11/17/07	030736965-0012	North Face - West end at corner (scaffolding level)	11/17/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No		

Note:

1. Due to flow rate RPD exceedance (80.7%) for asbestos at Station 10 (North Side Sidewalk Bridge) on November 15, 2007, the result is deemed invalid.