

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-11/17/06	030637778-0001	Southwest Area (sidewalk bridge level)	11/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST2-11/17/06	030637778-0002	Southeast Area (sidewalk bridge level)	11/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST4-11/17/06	030637778-0003	Northwest Area (street-level)	11/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST5-11/17/06	030637778-0004	Firehouse #10 (roof level)	11/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST10-11/17/06	030637778-0005	North Side Sidewalk Bridge	11/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST11-11/17/06	030637778-0006	90 Trinity Place (roof level)	11/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST12-11/17/06	030637778-0007	110 Greenwich Street (roof level)	11/17/06	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST13-11/17/06	030637778-0008	Marriott Hotel, 38th Floor (roof level)	11/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST14-11/17/06	030637778-0009	West Face - South end at corner (scaffolding level)	11/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST15-11/17/06	030637778-0010	South Face - East end at corner (scaffolding level)	11/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST16-11/17/06	030637778-0011	East Face - North end at corner (scaffolding level)	11/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST17-11/17/06	030637778-0012	North Face - West end at corner (scaffolding level)	11/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST1-11/18/06	030637782-0001	Southwest Area (sidewalk bridge level)	11/18/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST2-11/18/06	030637782-0002	Southeast Area (sidewalk bridge level)	11/18/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST4-11/18/06	030637782-0003	Northwest Area (street-level)	11/18/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST5-11/18/06	030637782-0004	Firehouse #10 (roof level)	11/18/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST10-11/18/06	030637782-0005	North Side Sidewalk Bridge	11/18/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST11-11/18/06	030637782-0006	90 Trinity Place (roof level)	11/18/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST12-11/18/06	030637782-0007	110 Greenwich Street (roof level)	11/18/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST13-11/18/06	030637782-0008	Marriott Hotel, 38th Floor (roof level)	11/18/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST14-11/18/06	030637782-0009	West Face - South end at corner (scaffolding level)	11/18/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST15-11/18/06	030637782-0010	South Face - East end at corner (scaffolding level)	11/18/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST16-11/18/06	030637782-0011	East Face - North end at corner (scaffolding level)	11/18/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST17-11/18/06	030637782-0012	North Face - West end at corner (scaffolding level)	11/18/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST1-11/19/06	030637780-0001	Southwest Area (sidewalk bridge level)	11/19/06	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST2-11/19/06	030637780-0002	Southeast Area (sidewalk bridge level)	11/19/06	1	2.630	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 9.60	No	No	Note 1.
ASBESTOS-ST4-11/19/06	030637780-0003	Northwest Area (street-level)	11/19/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST5-11/19/06	030637780-0004	Firehouse #10 (roof level)	11/19/06	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST10-11/19/06	030637780-0005	North Side Sidewalk Bridge	11/19/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST11-11/19/06	030637780-0006	90 Trinity Place (roof level)	11/19/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST12-11/19/06	030637780-0007	110 Greenwich Street (roof level)	11/19/06	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST13-11/19/06	030637780-0008	Marriott Hotel, 38th Floor (roof level)	11/19/06	1	2.820	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST14-11/19/06	030637780-0009	West Face - South end at corner (scaffolding level)	11/19/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST15-11/19/06	030637780-0010	South Face - East end at corner (scaffolding level)	11/19/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST16-11/19/06	030637780-0011	East Face - North end at corner (scaffolding level)	11/19/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	
ASBESTOS-ST17-11/19/06	030637780-0012	North Face - West end at corner (scaffolding level)	11/19/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/06	< 13.00	No	No	

Note:
1. Due to flow rate RPD exceedance (29.7%) for asbestos at Station 2 (Southeast Area [sidewalk bridge level]) on November 19, 2006, the sample volume and subsequent sample result are estimated.