

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) | Exceeds Target | Exceeds EPA | Comments | |
|----------------------------------|----------------|-----------------------------------------------------|-----------------------|------------|---------------------------------|----------|---------------------------------|------|-------------------------|--------------------------------------|----------------|-------------|----------------|----------|
| Target Air Quality Levels | | | | | | | | | | | NA | Air Quality | Site Specific | Comments |
| EPA Site Specific Trigger Levels | | | | | | | | | | | 70 | Levels | Trigger Levels | |
| ASBESTOS-ST1-11/23/07 | 030737397-0001 | Southwest Area (sidewalk bridge level) | 11/23/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST2-11/23/07 | 030737397-0002 | Southeast Area (sidewalk bridge level) | 11/23/07 | 1 | 3.140 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST4-11/23/07 | 030737397-0003 | Northwest Area (street-level) | 11/23/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST5-11/23/07 | 030737397-0004 | Firehouse #10 (roof level) | 11/23/07 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST10-11/23/07 | 030737397-0005 | North Side Sidewalk Bridge | 11/23/07 | 1 | 2.920 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST11-11/23/07 | 030737397-0006 | 90 Trinity Place (roof level) | 11/23/07 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST12-11/23/07 | 030737397-0007 | 110 Greenwich Street (roof level) | 11/23/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST13-11/23/07 | 030737397-0008 | Marriott Hotel, 38th Floor (roof level) | 11/23/07 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST14-11/23/07 | 030737397-0009 | West Face - South end at corner (scaffolding level) | 11/23/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST15-11/23/07 | 030737397-0010 | South Face - East end at corner (scaffolding level) | 11/23/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST16-11/23/07 | 030737397-0011 | East Face - North end at corner (scaffolding level) | 11/23/07 | 1 | 3.140 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST17-11/23/07 | 030737397-0012 | North Face - West end at corner (scaffolding level) | 11/23/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST1-11/24/07 | 030737392-0001 | Southwest Area (sidewalk bridge level) | 11/24/07 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST2-11/24/07 | 030737392-0002 | Southeast Area (sidewalk bridge level) | 11/24/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST4-11/24/07 | 030737392-0003 | Northwest Area (street-level) | 11/24/07 | 1 | 2.910 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST5-11/24/07 | 030737392-0004 | Firehouse #10 (roof level) | 11/24/07 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST10-11/24/07 | 030737392-0005 | North Side Sidewalk Bridge | 11/24/07 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | 13.00 | No | No | | |
| ASBESTOS-ST11-11/24/07 | 030737392-0006 | 90 Trinity Place (roof level) | 11/24/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST12-11/24/07 | 030737392-0007 | 110 Greenwich Street (roof level) | 11/24/07 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST13-11/24/07 | 030737392-0008 | Marriott Hotel, 38th Floor (roof level) | 11/24/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 15.00 | No | No | | |
| ASBESTOS-ST14-11/24/07 | 030737392-0009 | West Face - South end at corner (scaffolding level) | 11/24/07 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST15-11/24/07 | 030737392-0010 | South Face - East end at corner (scaffolding level) | 11/24/07 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST16-11/24/07 | 030737392-0011 | East Face - North end at corner (scaffolding level) | 11/24/07 | 1 | 2.930 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST17-11/24/07 | 030737392-0012 | North Face - West end at corner (scaffolding level) | 11/24/07 | 1 | 3.030 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST1-11/25/07 | 030737394-0001 | Southwest Area (sidewalk bridge level) | 11/25/07 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST2-11/25/07 | 030737394-0002 | Southeast Area (sidewalk bridge level) | 11/25/07 | 1 | 3.280 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 15.00 | No | No | | |
| ASBESTOS-ST4-11/25/07 | 030737394-0003 | Northwest Area (street-level) | 11/25/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST5-11/25/07 | 030737394-0004 | Firehouse #10 (roof level) | 11/25/07 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST10-11/25/07 | 030737394-0005 | North Side Sidewalk Bridge | 11/25/07 | 1 | 3.140 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 15.00 | No | No | | |
| ASBESTOS-ST11-11/25/07 | 030737394-0006 | 90 Trinity Place (roof level) | 11/25/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST12-11/25/07 | 030737394-0007 | 110 Greenwich Street (roof level) | 11/25/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST13-11/25/07 | 030737394-0008 | Marriott Hotel, 38th Floor (roof level) | 11/25/07 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 15.00 | No | No | | |
| ASBESTOS-ST14-11/25/07 | 030737394-0009 | West Face - South end at corner (scaffolding level) | 11/25/07 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST15-11/25/07 | 030737394-0010 | South Face - East end at corner (scaffolding level) | 11/25/07 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST16-11/25/07 | 030737394-0011 | East Face - North end at corner (scaffolding level) | 11/25/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |
| ASBESTOS-ST17-11/25/07 | 030737394-0012 | North Face - West end at corner (scaffolding level) | 11/25/07 | 1 | 2.770 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 11/26/07 | < 13.00 | No | No | | |