

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA				
										70				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-12/01/06	030639156-0001	Southwest Area (sidewalk bridge level)	12/1/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST2-12/01/06	030639156-0002	Southeast Area (sidewalk bridge level)	12/1/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST4-12/01/06	030639156-0003	Northwest Area (street-level)	12/1/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST5-12/01/06	030639156-0004	Firehouse #10 (roof level)	12/1/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST10-12/01/06	030639156-0005	North Side Sidewalk Bridge	12/1/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST11-12/01/06	030639156-0006	90 Trinity Place (roof level)	12/1/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST12-12/01/06	030639156-0007	110 Greenwich Street (roof level)	12/1/06	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST13-12/01/06	030639156-0008	Marriott Hotel, 38th Floor (roof level)	12/1/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST14-12/01/06	030639156-0009	West Face - South end at corner (scaffolding level)	12/1/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST15-12/01/06	030639156-0010	South Face - East end at corner (scaffolding level)	12/1/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST16-12/01/06	030639156-0011	East Face - North end at corner (scaffolding level)	12/1/06	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST17-12/01/06	030639156-0012	North Face - West end at corner (scaffolding level)	12/1/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST1-12/02/06	030639154-0001	Southwest Area (sidewalk bridge level)	12/2/06	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST2-12/02/06	030639154-0002	Southeast Area (sidewalk bridge level)	12/2/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST4-12/02/06	030639154-0003	Northwest Area (street-level)	12/2/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST5-12/02/06	030639154-0004	Firehouse #10 (roof level)	12/2/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST10-12/02/06	030639154-0005	North Side Sidewalk Bridge	12/2/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST11-12/02/06	030639154-0006	90 Trinity Place (roof level)	12/2/06	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST12-12/02/06	030639154-0007	110 Greenwich Street (roof level)	12/2/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST13-12/02/06	030639154-0008	Marriott Hotel, 38th Floor (roof level)	12/2/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST14-12/02/06	030639154-0009	West Face - South end at corner (scaffolding level)	12/2/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST15-12/02/06	030639154-0010	South Face - East end at corner (scaffolding level)	12/2/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST16-12/02/06	030639154-0011	East Face - North end at corner (scaffolding level)	12/2/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST17-12/02/06	030639154-0012	North Face - West end at corner (scaffolding level)	12/2/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST1-12/03/06	030639152-0001	Southwest Area (sidewalk bridge level)	12/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST2-12/03/06	030639152-0002	Southeast Area (sidewalk bridge level)	12/3/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST4-12/03/06	030639152-0003	Northwest Area (street-level)	12/3/06	1	3.280	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST5-12/03/06	030639152-0004	Firehouse #10 (roof level)	12/3/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST10-12/03/06	030639152-0005	North Side Sidewalk Bridge	12/3/06	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST11-12/03/06	030639152-0006	90 Trinity Place (roof level)	12/3/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST12-12/03/06	030639152-0007	110 Greenwich Street (roof level)	12/3/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST13-12/03/06	030639152-0008	Marriott Hotel, 38th Floor (roof level)	12/3/06	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST14-12/03/06	030639152-0009	West Face - South end at corner (scaffolding level)	12/3/06	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST15-12/03/06	030639152-0010	South Face - East end at corner (scaffolding level)	12/3/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST16-12/03/06	030639152-0011	East Face - North end at corner (scaffolding level)	12/3/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST17-12/03/06	030639152-0012	North Face - West end at corner (scaffolding level)	12/3/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/4/06	< 13.00		No	No	
ASBESTOS-ST1-12/4/06	030639272-0001	Southwest Area (sidewalk bridge level)	12/4/06	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/5/06	< 13.00		No	No	
ASBESTOS-ST2-12/4/06	030639272-0002	Southeast Area (sidewalk bridge level)	12/4/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/5/06	< 13.00		No	No	
ASBESTOS-ST4-12/4/06	030639272-0003	Northwest Area (street-level)	12/4/06	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/5/06	< 13.00		No	No	
ASBESTOS-ST5-12/4/06	030639272-0004	Firehouse #10 (roof level)	12/4/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/5/06	< 13.00		No	No	
ASBESTOS-ST10-12/4/06	030639272-0005	North Side Sidewalk Bridge	12/4/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/5/06	< 13.00		No	No	
ASBESTOS-ST100-12/4/06	030639272-0013	Station 10 Field Duplicate	12/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/5/06	< 13.00		No	No	
ASBESTOS-ST11-12/4/06	030639272-0006	90 Trinity Place (roof level)	12/4/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/5/06	< 13.00		No	No	
ASBESTOS-ST12-12/4/06	030639272-0007	110 Greenwich Street (roof level)	12/4/06	1	2.840	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/5/06	< 13.00		No	No	
ASBESTOS-ST13-12/4/06	030639272-0008	Marriott Hotel, 38th Floor (roof level)	12/4/06	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/5/06	< 13.00		No	No	
ASBESTOS-ST14-12/4/06	030639272-0009	West Face - South end at corner (scaffolding level)	12/4/06	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/5/06	< 13.00		No	No	
ASBESTOS-ST15-12/4/06	030639272-0010	South Face - East end at corner (scaffolding level)	12/4/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/5/06	< 13.00		No	No	
ASBESTOS-ST16-12/4/06	030639272-0011	East Face - North end at corner (scaffolding level)	12/4/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/5/06	< 13.00		No	No	
ASBESTOS-ST17-12/4/06	030639272-0012	North Face - West end at corner (scaffolding level)	12/4/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/5/06	< 13.00		No	No	