

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels											70			
ASBESTOS-ST1-12/5/07	030738244-0001	Southwest Area (sidewalk bridge level)	12/5/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/6/07	< 13.00	No	No		
ASBESTOS-ST2-12/5/07	030738244-0002	Southeast Area (sidewalk bridge level)	12/5/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/6/07	< 13.00	No	No		
ASBESTOS-ST4-12/5/07	030738244-0003	Northwest Area (street-level)	12/5/07	1	2.220	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/6/07	< 11.00	No	No		
ASBESTOS-ST5-12/5/07	030738244-0004	Firehouse #10 (roof level)	12/5/07	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/6/07	< 11.00	No	No		
ASBESTOS-ST10-12/5/07	030738244-0005	North Side Sidewalk Bridge	12/5/07	1	3.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/6/07	< 13.00	No	No	Note 1	
ASBESTOS-ST11-12/5/07	030738244-0006	90 Trinity Place (roof level)	12/5/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/6/07	< 13.00	No	No		
ASBESTOS-ST12-12/5/07	030738244-0007	110 Greenwich Street (roof level)	12/5/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/6/07	< 13.00	No	No		
ASBESTOS-ST13-12/5/07	030738244-0008	Marriott Hotel, 38th Floor (roof level)	12/5/07	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/6/07	< 13.00	No	No		
ASBESTOS-ST14-12/5/07	030738244-0009	West Face - South end at corner (scaffolding level)	12/5/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/6/07	< 13.00	No	No		
ASBESTOS-ST15-12/5/07	030738244-0010	South Face - East end at corner (scaffolding level)	12/5/07	1	2.870	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/6/07	< 11.00	No	No		
ASBESTOS-ST16-12/5/07	030738244-0011	East Face - North end at corner (scaffolding level)	12/5/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/6/07	< 13.00	No	No		
ASBESTOS-ST17-12/5/07	030738244-0012	North Face - West end at corner (scaffolding level)	12/5/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/6/07	< 13.00	No	No		
ASBESTOS-ST1-12/6/07	030738378-0001	Southwest Area (sidewalk bridge level)	12/6/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/7/07	< 13.00	No	No		
ASBESTOS-ST2-12/6/07	030738378-0002	Southeast Area (sidewalk bridge level)	12/6/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/7/07	< 15.00	No	No		
ASBESTOS-ST4-12/6/07	030738378-0003	Northwest Area (street-level)	12/6/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/7/07	13.00	No	No		
ASBESTOS-ST5-12/6/07	030738378-0004	Firehouse #10 (roof level)	12/6/07	1	3.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/7/07	< 13.00	No	No		
ASBESTOS-ST10-12/6/07	030738378-0005	North Side Sidewalk Bridge	12/6/07	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/7/07	< 15.00	No	No		
ASBESTOS-ST100-12/6/07	030738378-0013	Station 10 Field Duplicate	12/6/07	1	3.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/7/07	< 19.00	No	No		
ASBESTOS-ST11-12/6/07	030738378-0006	90 Trinity Place (roof level)	12/6/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/7/07	< 13.00	No	No		
ASBESTOS-ST12-12/6/07	030738378-0007	110 Greenwich Street (roof level)	12/6/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/7/07	< 13.00	No	No		
ASBESTOS-ST13-12/6/07	030738378-0008	Marriott Hotel, 38th Floor (roof level)	12/6/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/7/07	< 13.00	No	No		
ASBESTOS-ST14-12/6/07	030738378-0009	West Face - South end at corner (scaffolding level)	12/6/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/7/07	< 13.00	No	No		
ASBESTOS-ST15-12/6/07	030738378-0010	South Face - East end at corner (scaffolding level)	12/6/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/7/07	< 13.00	No	No		
ASBESTOS-ST16-12/6/07	030738378-0011	East Face - North end at corner (scaffolding level)	12/6/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/7/07	< 13.00	No	No		
ASBESTOS-ST17-12/6/07	030738378-0012	North Face - West end at corner (scaffolding level)	12/6/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/7/07	< 13.00	No	No		
ASBESTOS-ST100-12/6/07	030738378-0013	Station 10 Field Duplicate	12/6/07	1	3.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/7/07	< 19.00	No	No		

Note:

1. Due to flow rate RPD exceedance (75.1%) for asbestos at Station 10 (North Side Sidewalk Bridge) on December 5, 2007, the sample result is invalid.