

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
										NA	Air Quality Levels	Site Specific Trigger Levels	
										70			
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-12/8/10	031033679-0001	Southwest Area (sidewalk bridge level)	12/8/10	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/9/10	< 13.00	No	No	
ASBESTOS-ST2-12/8/10	031033679-0002	Southeast Area (sidewalk bridge level)	12/8/10	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/9/10	< 13.00	No	No	
ASBESTOS-ST4-12/8/10	031033679-0003	Northwest Area (street-level)	12/8/10	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/9/10	< 13.00	No	No	
ASBESTOS-ST5-12/8/10	031033679-0004	Firehouse #10 (roof level)	12/8/10	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/9/10	< 13.00	No	No	
ASBESTOS-ST1-12/9/2010	031033826-0001	Southwest Area (sidewalk bridge level)	12/9/10	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/10/10	< 13.00	No	No	
ASBESTOS-ST2-12/9/2010	031033826-0002	Southeast Area (sidewalk bridge level)	12/9/10	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/10/10	< 13.00	No	No	
ASBESTOS-ST2000-12/9/10	031033826-0005	Station 2 Field Duplicate	12/9/10	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/10/10	< 13.00	No	No	
ASBESTOS-ST4-12/9/2010	031033826-0003	Northwest Area (street-level)	12/9/10	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/10/10	< 13.00	No	No	
ASBESTOS-ST5-12/9/2010	031033826-0004	Firehouse #10 (roof level)	12/9/10	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/10/10	< 13.00	No	No	
ASBESTOS-ST1-12/10/10	031034036-0001	Southwest Area (sidewalk bridge level)	12/10/10	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/13/10	< 13.00	No	No	
ASBESTOS-ST2-12/10/10	031034036-0002	Southeast Area (sidewalk bridge level)	12/10/10	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/13/10	< 13.00	No	No	
ASBESTOS-ST4-12/10/10	031034036-0003	Northwest Area (street-level)	12/10/10	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/13/10	< 13.00	No	No	
ASBESTOS-ST5-12/10/10	031034036-0004	Firehouse #10 (roof level)	12/10/10	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/13/10	< 13.00	No	No	
ASBESTOS-ST1-12/11/10	031034037-0001	Southwest Area (sidewalk bridge level)	12/11/10	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/13/10	< 13.00	No	No	
ASBESTOS-ST2-12/11/10	031034037-0002	Southeast Area (sidewalk bridge level)	12/11/10	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/13/10	< 13.00	No	No	
ASBESTOS-ST4-12/11/10	031034037-0003	Northwest Area (street-level)	12/11/10	1	3.070	Asbestos	SEM	EMSL	12/13/10	< 6.17	No	No	Note 1
ASBESTOS-ST5-12/11/10	031034037-0004	Firehouse #10 (roof level)	12/11/10	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/13/10	< 13.00	No	No	
ASBESTOS-ST1-12/12/10	031034038-0001	Southwest Area (sidewalk bridge level)	12/12/10	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/13/10	< 13.00	No	No	
ASBESTOS-ST2-12/12/10	031034038-0002	Southeast Area (sidewalk bridge level)	12/12/10	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/13/10	< 13.00	No	No	
ASBESTOS-ST4-12/12/10	031034038-0003	Northwest Area (street-level)	12/12/10	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/13/10	< 13.00	No	No	
ASBESTOS-ST5-12/12/10	031034038-0004	Firehouse #10 (roof level)	12/12/10	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/13/10	< 13.00	No	No	

Note:

1. The asbestos sample from Station 4 (Northwest Area [street level]) on December 11, 2010 was overloaded with particulate and underwent analysis via Scanning Electron Microscopy (SEM).