

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-1/2/08	0801019-01	Southwest Area (sidewalk bridge level)	1/2/08	0.64	Mercury	EPA 324/1631	BRL	1/4/08	< 23.0	No	No	
TotalHg-ST2-1/2/08	0801019-02	Southeast Area (sidewalk bridge level)	1/2/08	0.57	Mercury	EPA 324/1631	BRL	1/4/08	< 26.0	No	No	
TotalHg-ST4-1/2/08	0801019-03	Northwest Area (street-level)	1/2/08	0.57	Mercury	EPA 324/1631	BRL	1/4/08	< 26.0	No	No	
TotalHg-ST5-1/2/08	0801019-04	Firehouse #10 (roof level)	1/2/08	0.56	Mercury	EPA 324/1631	BRL	1/4/08	< 27.0	No	No	
TotalHg-ST10-1/2/08	0801019-05	North Side Sidewalk Bridge	1/2/08	0.53	Mercury	EPA 324/1631	BRL	1/4/08	< 28.0	No	No	
TotalHg-ST11-1/2/08	0801019-06	90 Trinity Place (roof level)	1/2/08	0.56	Mercury	EPA 324/1631	BRL	1/4/08	< 27.0	No	No	
TotalHg-ST12-1/2/08	0801019-07	110 Greenwich Street (roof level)	1/2/08	0.58	Mercury	EPA 324/1631	BRL	1/4/08	< 26.0	No	No	
TotalHg-ST13-1/2/08	0801019-08	Marriott Hotel, 38th Floor (roof level)	1/2/08	0.58	Mercury	EPA 324/1631	BRL	1/4/08	< 26.0	No	No	
TotalHg-ST14-1/2/08	0801019-09	West Face - South end at corner (scaffolding level)	1/2/08	0.57	Mercury	EPA 324/1631	BRL	1/4/08	< 26.0	No	No	
TotalHg-ST15-1/2/08	0801019-10	South Face - East end at corner (scaffolding level)	1/2/08	0.56	Mercury	EPA 324/1631	BRL	1/4/08	< 27.0	No	No	
TotalHg-ST16-1/2/08	0801019-11	East Face - North end at corner (scaffolding level)	1/2/08	0.52	Mercury	EPA 324/1631	BRL	1/4/08	< 29.0	No	No	
TotalHg-ST17-1/2/08	0801019-12	North Face - West end at corner (scaffolding level)	1/2/08	0.55	Mercury	EPA 324/1631	BRL	1/4/08	< 27.0	No	No	
TotalHg-ST1-1/3/08	0801027-01	Southwest Area (sidewalk bridge level)	1/3/08	0.60	Mercury	EPA 324/1631	BRL	1/5/08	< 25.0	No	No	
TotalHg-ST2-1/3/08	0801027-02	Southeast Area (sidewalk bridge level)	1/3/08	0.58	Mercury	EPA 324/1631	BRL	1/5/08	< 26.0	No	No	
TotalHg-ST4-1/3/08	0801027-03	Northwest Area (street-level)	1/3/08	0.61	Mercury	EPA 324/1631	BRL	1/5/08	< 25.0	No	No	
TotalHg-ST5-1/3/08	0801027-04	Firehouse #10 (roof level)	1/3/08	0.55	Mercury	EPA 324/1631	BRL	1/5/08	< 27.0	No	No	
TotalHg-ST10-1/3/08	0801027-05	North Side Sidewalk Bridge	1/3/08	0.51	Mercury	EPA 324/1631	BRL	1/5/08	< 29.0	No	No	
TotalHg-ST11-1/3/08	0801027-06	90 Trinity Place (roof level)	1/3/08	0.57	Mercury	EPA 324/1631	BRL	1/5/08	< 26.0	No	No	
TotalHg-ST12-1/3/08	0801027-07	110 Greenwich Street (roof level)	1/3/08	0.59	Mercury	EPA 324/1631	BRL	1/5/08	< 25.0	No	No	
TotalHg-ST13-1/3/08	0801027-08	Marriott Hotel, 38th Floor (roof level)	1/3/08	0.58	Mercury	EPA 324/1631	BRL	1/5/08	< 26.0	No	No	
TotalHg-ST14-1/3/08	0801027-09	West Face - South end at corner (scaffolding level)	1/3/08	0.58	Mercury	EPA 324/1631	BRL	1/5/08	< 26.0	No	No	
TotalHg-ST15-1/3/08	0801027-10	South Face - East end at corner (scaffolding level)	1/3/08	0.59	Mercury	EPA 324/1631	BRL	1/5/08	< 25.0	No	No	
TotalHg-ST16-1/3/08	0801027-11	East Face - North end at corner (scaffolding level)	1/3/08	0.61	Mercury	EPA 324/1631	BRL	1/5/08	< 25.0	No	No	
TotalHg-ST17-1/3/08	0801027-12	North Face - West end at corner (scaffolding level)	1/3/08	0.53	Mercury	EPA 324/1631	BRL	1/5/08	< 28.0	No	No	
TotalHg-ST1-1/4/08	0802001-01	Southwest Area (sidewalk bridge level)	1/4/08	0.52	Mercury	EPA 324/1631	BRL	1/7/08	< 29.0	No	No	
TotalHg-ST2-1/4/08	0802001-02	Southeast Area (sidewalk bridge level)	1/4/08	0.54	Mercury	EPA 324/1631	BRL	1/7/08	< 28.0	No	No	
TotalHg-ST4-1/4/08	0802001-03	Northwest Area (street-level)	1/4/08	0.54	Mercury	EPA 324/1631	BRL	1/7/08	< 28.0	No	No	
TotalHg-ST5-1/4/08	0802001-04	Firehouse #10 (roof level)	1/4/08	0.57	Mercury	EPA 324/1631	BRL	1/7/08	< 26.0	No	No	
TotalHg-ST10-1/4/08	0802001-05	North Side Sidewalk Bridge	1/4/08	0.54	Mercury	EPA 324/1631	BRL	1/7/08	< 28.0	No	No	
TotalHg-ST11-1/4/08	0802001-06	90 Trinity Place (roof level)	1/4/08	0.57	Mercury	EPA 324/1631	BRL	1/7/08	< 26.0	No	No	
TotalHg-ST12-1/4/08	0802001-07	110 Greenwich Street (roof level)	1/4/08	0.56	Mercury	EPA 324/1631	BRL	1/7/08	< 27.0	No	No	
TotalHg-ST13-1/4/08	0802001-08	Marriott Hotel, 38th Floor (roof level)	1/4/08	0.58	Mercury	EPA 324/1631	BRL	1/7/08	< 26.0	No	No	
TotalHg-ST14-1/4/08	0802001-09	West Face - South end at corner (scaffolding level)	1/4/08	0.58	Mercury	EPA 324/1631	BRL	1/7/08	< 26.0	No	No	
TotalHg-ST15-1/4/08	0802001-10	South Face - East end at corner (scaffolding level)	1/4/08	0.57	Mercury	EPA 324/1631	BRL	1/7/08	< 26.0	No	No	
TotalHg-ST16-1/4/08	0802001-11	East Face - North end at corner (scaffolding level)	1/4/08	0.52	Mercury	EPA 324/1631	BRL	1/7/08	< 29.0	No	No	
TotalHg-ST17-1/4/08	0802001-12	North Face - West end at corner (scaffolding level)	1/4/08	0.56	Mercury	EPA 324/1631	BRL	1/7/08	< 27.0	No	No	