

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-1/3/07	07BR0022-01	Southwest Area (sidewalk bridge level)	1/3/07	0.58	Mercury	EPA 324/1631	BRL	1/5/07	< 26.0	No	No	
TotalHg-ST2-1/3/07	07BR0022-02	Southeast Area (sidewalk bridge level)	1/3/07	0.58	Mercury	EPA 324/1631	BRL	1/5/07	< 26.0	No	No	
TotalHg-ST4-1/3/07	07BR0022-03	Northwest Area (street-level)	1/3/07	0.56	Mercury	EPA 324/1631	BRL	1/5/07	< 27.0	No	No	
TotalHg-ST5-1/3/07	07BR0022-04	Firehouse #10 (roof level)	1/3/07	0.58	Mercury	EPA 324/1631	BRL	1/5/07	< 26.0	No	No	
TotalHg-ST10-1/3/07	07BR0022-05	North Side Sidewalk Bridge	1/3/07	0.55	Mercury	EPA 324/1631	BRL	1/5/07	< 27.0	No	No	
TotalHg-ST11-1/3/07	07BR0022-06	90 Trinity Place (roof level)	1/3/07	0.56	Mercury	EPA 324/1631	BRL	1/5/07	< 27.0	No	No	
TotalHg-ST12-1/3/07	07BR0022-07	110 Greenwich Street (roof level)	1/3/07	0.56	Mercury	EPA 324/1631	BRL	1/5/07	< 27.0	No	No	
TotalHg-ST13-1/3/07	07BR0022-08	Marriott Hotel, 38th Floor (roof level)	1/3/07	0.55	Mercury	EPA 324/1631	BRL	1/5/07	< 27.0	No	No	
TotalHg-ST14-1/3/07	07BR0022-09	West Face - South end at corner (scaffolding level)	1/3/07	0.59	Mercury	EPA 324/1631	BRL	1/5/07	< 25.0	No	No	
TotalHg-ST15-1/3/07	07BR0022-10	South Face - East end at corner (scaffolding level)	1/3/07	0.58	Mercury	EPA 324/1631	BRL	1/5/07	< 26.0	No	No	
TotalHg-ST16-1/3/07	07BR0022-11	East Face - North end at corner (scaffolding level)	1/3/07	0.59	Mercury	EPA 324/1631	BRL	1/5/07	< 25.0	No	No	
TotalHg-ST17-1/3/07	07BR0022-12	North Face - West end at corner (scaffolding level)	1/3/07	0.55	Mercury	EPA 324/1631	BRL	1/5/07	< 27.0	No	No	
TotalHg-ST1-1/4/07	07BR0026-01	Southwest Area (sidewalk bridge level)	1/4/07	0.59	Mercury	EPA 324/1631	BRL	1/6/07	< 25.0	No	No	
TotalHg-ST2-1/4/07	07BR0026-02	Southeast Area (sidewalk bridge level)	1/4/07	0.57	Mercury	EPA 324/1631	BRL	1/6/07	< 26.0	No	No	
TotalHg-ST4-1/4/07	07BR0026-03	Northwest Area (street-level)	1/4/07	0.58	Mercury	EPA 324/1631	BRL	1/6/07	< 26.0	No	No	
TotalHg-ST5-1/4/07	07BR0026-04	Firehouse #10 (roof level)	1/4/07	0.58	Mercury	EPA 324/1631	BRL	1/6/07	< 26.0	No	No	
TotalHg-ST10-1/4/07	07BR0026-05	North Side Sidewalk Bridge	1/4/07	0.58	Mercury	EPA 324/1631	BRL	1/6/07	< 26.0	No	No	
TotalHg-ST11-1/4/07	07BR0026-06	90 Trinity Place (roof level)	1/4/07	0.57	Mercury	EPA 324/1631	BRL	1/6/07	< 26.0	No	No	
TotalHg-ST12-1/4/07	07BR0026-07	110 Greenwich Street (roof level)	1/4/07	0.58	Mercury	EPA 324/1631	BRL	1/6/07	< 26.0	No	No	
TotalHg-ST13-1/4/07	07BR0026-08	Marriott Hotel, 38th Floor (roof level)	1/4/07	0.56	Mercury	EPA 324/1631	BRL	1/6/07	< 27.0	No	No	
TotalHg-ST14-1/4/07	07BR0026-09	West Face - South end at corner (scaffolding level)	1/4/07	0.55	Mercury	EPA 324/1631	BRL	1/6/07	< 27.0	No	No	
TotalHg-ST15-1/4/07	07BR0026-10	South Face - East end at corner (scaffolding level)	1/4/07	0.56	Mercury	EPA 324/1631	BRL	1/6/07	< 27.0	No	No	
TotalHg-ST16-1/4/07	07BR0026-11	East Face - North end at corner (scaffolding level)	1/4/07	0.57	Mercury	EPA 324/1631	BRL	1/6/07	< 26.0	No	No	
TotalHg-ST17-1/4/07	07BR0026-12	North Face - West end at corner (scaffolding level)	1/4/07	0.54	Mercury	EPA 324/1631	BRL	1/6/07	< 28.0	No	No	