

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m ³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-1/3/09	0902008-01	Southwest Area (sidewalk bridge level)	1/3/09	0.57	Mercury	EPA 324/1631	BRL	1/6/09	< 26.0	No	No	
TotalHg-ST2-1/3/09	0902008-02	Southeast Area (sidewalk bridge level)	1/3/09	0.58	Mercury	EPA 324/1631	BRL	1/6/09	< 26.0	No	No	
TotalHg-ST4-1/3/09	0902008-03	Northwest Area (street-level)	1/3/09	0.58	Mercury	EPA 324/1631	BRL	1/6/09	< 26.0	No	No	
TotalHg-ST5-1/3/09	0902008-04	Firehouse #10 (roof level)	1/3/09	0.58	Mercury	EPA 324/1631	BRL	1/6/09	< 26.0	No	No	
TotalHg-ST10-1/3/09	0902008-05	North Side Sidewalk Bridge	1/3/09	0.59	Mercury	EPA 324/1631	BRL	1/6/09	< 25.0	No	No	
TotalHg-ST11-1/3/09	0902008-06	90 Trinity Place (roof level)	1/3/09	0.54	Mercury	EPA 324/1631	BRL	1/6/09	< 28.0	No	No	
TotalHg-ST12-1/3/09	0902008-07	110 Greenwich Street (roof level)	1/3/09	0.56	Mercury	EPA 324/1631	BRL	1/6/09	< 27.0	No	No	
TotalHg-ST13-1/3/09	0902008-08	Marriott Hotel, 38th Floor (roof level)	1/3/09	0.56	Mercury	EPA 324/1631	BRL	1/6/09	< 27.0	No	No	
TotalHg-ST14-1/3/09	0902008-09	West Face - South end at corner (scaffolding level)	1/3/09	0.57	Mercury	EPA 324/1631	BRL	1/6/09	< 26.0	No	No	
TotalHg-ST15-1/3/09	0902008-10	South Face - East end at corner (scaffolding level)	1/3/09	0.55	Mercury	EPA 324/1631	BRL	1/6/09	< 27.0	No	No	
TotalHg-ST16-1/3/09	0902008-11	East Face - North end at corner (scaffolding level)	1/3/09	0.53	Mercury	EPA 324/1631	BRL	1/6/09	< 28.0	No	No	
TotalHg-ST17-1/3/09	0902008-12	North Face - West end at corner (scaffolding level)	1/3/09	0.58	Mercury	EPA 324/1631	BRL	1/6/09	< 26.0	No	No	
TotalHg-ST1-1/4/09	0902009-01	Southwest Area (sidewalk bridge level)	1/4/09	0.60	Mercury	EPA 324/1631	BRL	1/6/09	< 25.0	No	No	
TotalHg-ST2-1/4/09	0902009-02	Southeast Area (sidewalk bridge level)	1/4/09	0.57	Mercury	EPA 324/1631	BRL	1/6/09	< 26.0	No	No	
TotalHg-ST4-1/4/09	0902009-03	Northwest Area (street-level)	1/4/09	0.53	Mercury	EPA 324/1631	BRL	1/6/09	< 28.0	No	No	
TotalHg-ST5-1/4/09	0902009-04	Firehouse #10 (roof level)	1/4/09	0.55	Mercury	EPA 324/1631	BRL	1/6/09	< 27.0	No	No	
TotalHg-ST10-1/4/09	0902009-05	North Side Sidewalk Bridge	1/4/09	0.56	Mercury	EPA 324/1631	BRL	1/6/09	< 27.0	No	No	
TotalHg-ST11-1/4/09	0902009-06	90 Trinity Place (roof level)	1/4/09	0.59	Mercury	EPA 324/1631	BRL	1/6/09	< 25.0	No	No	
TotalHg-ST12-1/4/09	0902009-07	110 Greenwich Street (roof level)	1/4/09	0.55	Mercury	EPA 324/1631	BRL	1/6/09	< 27.0	No	No	
TotalHg-ST13-1/4/09	0902009-08	Marriott Hotel, 38th Floor (roof level)	1/4/09	0.59	Mercury	EPA 324/1631	BRL	1/6/09	< 25.0	No	No	
TotalHg-ST14-1/4/09	0902009-09	West Face - South end at corner (scaffolding level)	1/4/09	0.60	Mercury	EPA 324/1631	BRL	1/6/09	< 25.0	No	No	
TotalHg-ST15-1/4/09	0902009-10	South Face - East end at corner (scaffolding level)	1/4/09	0.61	Mercury	EPA 324/1631	BRL	1/6/09	< 25.0	No	No	
TotalHg-ST16-1/4/09	0902009-11	East Face - North end at corner (scaffolding level)	1/4/09	0.58	Mercury	EPA 324/1631	BRL	1/6/09	< 26.0	No	No	
TotalHg-ST17-1/4/09	0902009-12	North Face - West end at corner (scaffolding level)	1/4/09	0.59	Mercury	EPA 324/1631	BRL	1/6/09	< 25.0	No	No	
TotalHg-ST1-1/5/09	0902018-01	Southwest Area (sidewalk bridge level)	1/5/09	0.58	Mercury	EPA 324/1631	BRL	1/7/09	< 26.0	No	No	
TotalHg-ST2-1/5/09	0902018-02	Southeast Area (sidewalk bridge level)	1/5/09	0.57	Mercury	EPA 324/1631	BRL	1/7/09	< 26.0	No	No	
TotalHg-ST4-1/5/09	0902018-03	Northwest Area (street-level)	1/5/09	0.55	Mercury	EPA 324/1631	BRL	1/7/09	< 27.0	No	No	
TotalHg-ST5-1/5/09	0902018-04	Firehouse #10 (roof level)	1/5/09	0.59	Mercury	EPA 324/1631	BRL	1/7/09	< 25.0	No	No	
TotalHg-ST10-1/5/09	0902018-05	North Side Sidewalk Bridge	1/5/09	0.55	Mercury	EPA 324/1631	BRL	1/7/09	< 27.0	No	No	
TotalHg-ST11-1/5/09	0902018-06	90 Trinity Place (roof level)	1/5/09	0.58	Mercury	EPA 324/1631	BRL	1/7/09	< 26.0	No	No	
TotalHg-ST12-1/5/09	0902018-07	110 Greenwich Street (roof level)	1/5/09	0.57	Mercury	EPA 324/1631	BRL	1/7/09	< 26.0	No	No	
TotalHg-ST13-1/5/09	0902018-08	Marriott Hotel, 38th Floor (roof level)	1/5/09	0.57	Mercury	EPA 324/1631	BRL	1/7/09	< 26.0	No	No	
TotalHg-ST14-1/5/09	0902018-09	West Face - South end at corner (scaffolding level)	1/5/09	0.60	Mercury	EPA 324/1631	BRL	1/7/09	< 25.0	No	No	
TotalHg-ST15-1/5/09	0902018-10	South Face - East end at corner (scaffolding level)	1/5/09	0.54	Mercury	EPA 324/1631	BRL	1/7/09	< 28.0	No	No	
TotalHg-ST16-1/5/09	0902018-11	East Face - North end at corner (scaffolding level)	1/5/09	0.54	Mercury	EPA 324/1631	BRL	1/7/09	< 28.0	No	No	
TotalHg-ST17-1/5/09	0902018-12	North Face - West end at corner (scaffolding level)	1/5/09	0.58	Mercury	EPA 324/1631	BRL	1/7/09	< 26.0	No	No	