

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>												
TotalHg-ST1-1/9/08	0802031-01	Southwest Area (sidewalk bridge level)	1/9/08	0.54	Mercury	EPA 324/1631	BRL	1/11/08	< 28.0	No	No	
TotalHg-ST2-1/9/08	0802031-02	Southeast Area (sidewalk bridge level)	1/9/08	0.60	Mercury	EPA 324/1631	BRL	1/11/08	< 25.0	No	No	
TotalHg-ST4-1/9/08	0802031-03	Northwest Area (street-level)	1/9/08	0.57	Mercury	EPA 324/1631	BRL	1/11/08	< 26.0	No	No	
TotalHg-ST5-1/9/08	0802031-04	Firehouse #10 (roof level)	1/9/08	0.54	Mercury	EPA 324/1631	BRL	1/11/08	< 28.0	No	No	
TotalHg-ST10-1/9/08	0802031-05	North Side Sidewalk Bridge	1/9/08	0.57	Mercury	EPA 324/1631	BRL	1/11/08	< 26.0	No	No	
TotalHg-ST11-1/9/08	0802031-06	90 Trinity Place (roof level)	1/9/08	0.54	Mercury	EPA 324/1631	BRL	1/11/08	< 28.0	No	No	
TotalHg-ST12-1/9/08	0802031-07	110 Greenwich Street (roof level)	1/9/08	0.54	Mercury	EPA 324/1631	BRL	1/11/08	< 28.0	No	No	
TotalHg-ST13-1/9/08	0802031-08	Marriott Hotel, 38th Floor (roof level)	1/9/08	0.56	Mercury	EPA 324/1631	BRL	1/11/08	< 27.0	No	No	
TotalHg-ST14-1/9/08	0802031-09	West Face - South end at corner (scaffolding level)	1/9/08	0.56	Mercury	EPA 324/1631	BRL	1/11/08	< 27.0	No	No	
TotalHg-ST15-1/9/08	0802031-10	South Face - East end at corner (scaffolding level)	1/9/08	0.58	Mercury	EPA 324/1631	BRL	1/11/08	< 26.0	No	No	
TotalHg-ST16-1/9/08	0802031-11	East Face - North end at corner (scaffolding level)	1/9/08	0.55	Mercury	EPA 324/1631	BRL	1/11/08	< 27.0	No	No	
TotalHg-ST17-1/9/08	0802031-12	North Face - West end at corner (scaffolding level)	1/9/08	0.57	Mercury	EPA 324/1631	BRL	1/11/08	< 26.0	No	No	
TotalHg-ST1-1/10/08	0802043-01	Southwest Area (sidewalk bridge level)	1/10/08	0.55	Mercury	EPA 324/1631	BRL	1/12/08	< 27.0	No	No	
TotalHg-ST2-1/10/08	0802043-02	Southeast Area (sidewalk bridge level)	1/10/08	0.59	Mercury	EPA 324/1631	BRL	1/12/08	< 25.0	No	No	
TotalHg-ST4-1/10/08	0802043-03	Northwest Area (street-level)	1/10/08	0.58	Mercury	EPA 324/1631	BRL	1/12/08	< 26.0	No	No	
TotalHg-ST5-1/10/08	0802043-04	Firehouse #10 (roof level)	1/10/08	0.60	Mercury	EPA 324/1631	BRL	1/12/08	< 25.0	No	No	
TotalHg-ST10-1/10/08	0802043-05	North Side Sidewalk Bridge	1/10/08	0.63	Mercury	EPA 324/1631	BRL	1/12/08	< 24.0	No	No	
TotalHg-ST11-1/10/08	0802043-06	90 Trinity Place (roof level)	1/10/08	0.56	Mercury	EPA 324/1631	BRL	1/12/08	< 27.0	No	No	
TotalHg-ST12-1/10/08	0802043-07	110 Greenwich Street (roof level)	1/10/08	0.57	Mercury	EPA 324/1631	BRL	1/12/08	< 26.0	No	No	
TotalHg-ST13-1/10/08	0802043-08	Marriott Hotel, 38th Floor (roof level)	1/10/08	0.57	Mercury	EPA 324/1631	BRL	1/12/08	< 26.0	No	No	
TotalHg-ST14-1/10/08	0802043-09	West Face - South end at corner (scaffolding level)	1/10/08	0.58	Mercury	EPA 324/1631	BRL	1/12/08	< 26.0	No	No	
TotalHg-ST15-1/10/08	0802043-10	South Face - East end at corner (scaffolding level)	1/10/08	0.57	Mercury	EPA 324/1631	BRL	1/12/08	< 26.0	No	No	
TotalHg-ST16-1/10/08	0802043-11	East Face - North end at corner (scaffolding level)	1/10/08	0.61	Mercury	EPA 324/1631	BRL	1/12/08	< 25.0	No	No	
TotalHg-ST17-1/10/08	0802043-12	North Face - West end at corner (scaffolding level)	1/10/08	0.60	Mercury	EPA 324/1631	BRL	1/12/08	< 25.0	No	No	