

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-1/10/07	07BR0040-01	Southwest Area (sidewalk bridge level)	1/10/07	0.59	Mercury	EPA 324/1631	BRL	1/12/07	< 25.0	No	No	
TotalHg-ST2-1/10/07	07BR0040-02	Southeast Area (sidewalk bridge level)	1/10/07	0.64	Mercury	EPA 324/1631	BRL	1/12/07	< 23.0	No	No	
TotalHg-ST4-1/10/07	07BR0040-03	Northwest Area (street-level)	1/10/07	0.59	Mercury	EPA 324/1631	BRL	1/12/07	< 25.0	No	No	
TotalHg-ST5-1/10/07	07BR0040-04	Firehouse #10 (roof level)	1/10/07	0.56	Mercury	EPA 324/1631	BRL	1/12/07	< 27.0	No	No	
TotalHg-ST10-1/10/07	07BR0040-05	North Side Sidewalk Bridge	1/10/07	0.58	Mercury	EPA 324/1631	BRL	1/12/07	< 26.0	No	No	
TotalHg-ST11-1/10/07	07BR0040-06	90 Trinity Place (roof level)	1/10/07	0.56	Mercury	EPA 324/1631	BRL	1/12/07	< 27.0	No	No	
TotalHg-ST12-1/10/07	07BR0040-07	110 Greenwich Street (roof level)	1/10/07	0.56	Mercury	EPA 324/1631	BRL	1/12/07	< 27.0	No	No	
TotalHg-ST13-1/10/07	07BR0040-08	Marriott Hotel, 38th Floor (roof level)	1/10/07	0.62	Mercury	EPA 324/1631	BRL	1/12/07	< 24.0	No	No	
TotalHg-ST14-1/10/07	07BR0040-09	West Face - South end at corner (scaffolding level)	1/10/07	0.60	Mercury	EPA 324/1631	BRL	1/12/07	< 25.0	No	No	
TotalHg-ST15-1/10/07	07BR0040-10	South Face - East end at corner (scaffolding level)	1/10/07	0.59	Mercury	EPA 324/1631	BRL	1/12/07	< 25.0	No	No	
TotalHg-ST16-1/10/07	07BR0040-11	East Face - North end at corner (scaffolding level)	1/10/07	0.59	Mercury	EPA 324/1631	BRL	1/12/07	< 25.0	No	No	
TotalHg-ST17-1/10/07	07BR0040-12	North Face - West end at corner (scaffolding level)	1/10/07	0.53	Mercury	EPA 324/1631	BRL	1/12/07	< 28.0	No	No	
TotalHg-ST1-1/11/07	07BR0048-01	Southwest Area (sidewalk bridge level)	1/11/07	0.57	Mercury	EPA 324/1631	BRL	1/13/07	< 26.0	No	No	
TotalHg-ST2-1/11/07	07BR0048-02	Southeast Area (sidewalk bridge level)	1/11/07	0.57	Mercury	EPA 324/1631	BRL	1/13/07	< 26.0	No	No	
TotalHg-ST4-1/11/07	07BR0048-03	Northwest Area (street-level)	1/11/07	0.56	Mercury	EPA 324/1631	BRL	1/13/07	< 27.0	No	No	
TotalHg-ST5-1/11/07	07BR0048-04	Firehouse #10 (roof level)	1/11/07	0.60	Mercury	EPA 324/1631	BRL	1/13/07	< 25.0	No	No	
TotalHg-ST10-1/11/07	07BR0048-05	North Side Sidewalk Bridge	1/11/07	0.57	Mercury	EPA 324/1631	BRL	1/13/07	< 26.0	No	No	
TotalHg-ST11-1/11/07	07BR0048-06	90 Trinity Place (roof level)	1/11/07	0.57	Mercury	EPA 324/1631	BRL	1/13/07	< 26.0	No	No	
TotalHg-ST12-1/11/07	07BR0048-07	110 Greenwich Street (roof level)	1/11/07	0.52	Mercury	EPA 324/1631	BRL	1/13/07	< 29.0	No	No	
TotalHg-ST13-1/11/07	07BR0048-08	Marriott Hotel, 38th Floor (roof level)	1/11/07	0.60	Mercury	EPA 324/1631	BRL	1/13/07	< 25.0	No	No	
TotalHg-ST14-1/11/07	07BR0048-09	West Face - South end at corner (scaffolding level)	1/11/07	0.52	Mercury	EPA 324/1631	BRL	1/13/07	< 29.0	No	No	
TotalHg-ST15-1/11/07	07BR0048-10	South Face - East end at corner (scaffolding level)	1/11/07	0.57	Mercury	EPA 324/1631	BRL	1/13/07	< 26.0	No	No	
TotalHg-ST16-1/11/07	07BR0048-11	East Face - North end at corner (scaffolding level)	1/11/07	0.56	Mercury	EPA 324/1631	BRL	1/13/07	< 27.0	No	No	
TotalHg-ST17-1/11/07	07BR0048-12	North Face - West end at corner (scaffolding level)	1/11/07	0.57	Mercury	EPA 324/1631	BRL	1/13/07	< 26.0	No	No	