

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>									<b>300</b>			
<b>EPA Site Specific Trigger Levels</b>									<b>3,000</b>			
TotalHg-ST1-1/19/09	0904016-01	Southwest Area (sidewalk bridge level)	1/19/09	0.52	Mercury	EPA 324/1631	BRL	1/21/09	< 29.0	No	No	
TotalHg-ST2-1/19/09	0904016-02	Southeast Area (sidewalk bridge level)	1/19/09	0.53	Mercury	EPA 324/1631	BRL	1/21/09	< 28.0	No	No	
TotalHg-ST4-1/19/09	0904016-03	Northwest Area (street-level)	1/19/09	0.54	Mercury	EPA 324/1631	BRL	1/21/09	< 28.0	No	No	
TotalHg-ST5-1/19/09	0904016-04	Firehouse #10 (roof level)	1/19/09	0.55	Mercury	EPA 324/1631	BRL	1/21/09	< 27.0	No	No	
TotalHg-ST10-1/19/09	0904016-05	North Side Sidewalk Bridge	1/19/09	0.55	Mercury	EPA 324/1631	BRL	1/21/09	< 27.0	No	No	
TotalHg-ST11-1/19/09	0904016-06	90 Trinity Place (roof level)	1/19/09	0.58	Mercury	EPA 324/1631	BRL	1/21/09	< 26.0	No	No	
TotalHg-ST12-1/19/09	0904016-07	110 Greenwich Street (roof level)	1/19/09	0.55	Mercury	EPA 324/1631	BRL	1/21/09	< 27.0	No	No	
TotalHg-ST13-1/19/09	0904016-08	Marriott Hotel, 38th Floor (roof level)	1/19/09	0.53	Mercury	EPA 324/1631	BRL	1/21/09	< 28.0	No	No	
TotalHg-ST14-1/19/09	0904016-09	West Face - South end at corner (scaffolding level)	1/19/09	0.55	Mercury	EPA 324/1631	BRL	1/21/09	< 27.0	No	No	
TotalHg-ST15-1/19/09	0904016-10	South Face - East end at corner (scaffolding level)	1/19/09	0.57	Mercury	EPA 324/1631	BRL	1/21/09	< 26.0	No	No	
TotalHg-ST16-1/19/09	0904016-11	East Face - North end at corner (scaffolding level)	1/19/09	0.56	Mercury	EPA 324/1631	BRL	1/21/09	< 27.0	No	No	
TotalHg-ST17-1/19/09	0904016-12	North Face - West end at corner (scaffolding level)	1/19/09	0.56	Mercury	EPA 324/1631	BRL	1/21/09	< 27.0	No	No	
TotalHg-ST1-1/20/09	0904020-01	Southwest Area (sidewalk bridge level)	1/20/09	0.60	Mercury	EPA 324/1632	BRL	1/22/09	< 25.0	No	No	
TotalHg-ST2-1/20/09	0904020-02	Southeast Area (sidewalk bridge level)	1/20/09	0.60	Mercury	EPA 324/1633	BRL	1/22/09	< 25.0	No	No	
TotalHg-ST4-1/20/09	0904020-03	Northwest Area (street-level)	1/20/09	0.59	Mercury	EPA 324/1634	BRL	1/22/09	< 25.0	No	No	
TotalHg-ST5-1/20/09	0904020-04	Firehouse #10 (roof level)	1/20/09	0.57	Mercury	EPA 324/1635	BRL	1/22/09	< 26.0	No	No	
TotalHg-ST10-1/20/09	0904020-05	North Side Sidewalk Bridge	1/20/09	0.59	Mercury	EPA 324/1636	BRL	1/22/09	< 25.0	No	No	
TotalHg-ST11-1/20/09	0904020-06	90 Trinity Place (roof level)	1/20/09	0.57	Mercury	EPA 324/1637	BRL	1/22/09	< 26.0	No	No	
TotalHg-ST12-1/20/09	0904020-07	110 Greenwich Street (roof level)	1/20/09	0.55	Mercury	EPA 324/1638	BRL	1/22/09	< 27.0	No	No	
TotalHg-ST13-1/20/09	0904020-08	Marriott Hotel, 38th Floor (roof level)	1/20/09	0.55	Mercury	EPA 324/1639	BRL	1/22/09	< 27.0	No	No	
TotalHg-ST14-1/20/09	0904020-09	West Face - South end at corner (scaffolding level)	1/20/09	0.63	Mercury	EPA 324/1640	BRL	1/22/09	< 24.0	No	No	
TotalHg-ST15-1/20/09	0904020-10	South Face - East end at corner (scaffolding level)	1/20/09	0.56	Mercury	EPA 324/1641	BRL	1/22/09	< 27.0	No	No	
TotalHg-ST16-1/20/09	0904020-11	East Face - North end at corner (scaffolding level)	1/20/09	0.54	Mercury	EPA 324/1642	BRL	1/22/09	< 28.0	No	No	
TotalHg-ST17-1/20/09	0904020-12	North Face - West end at corner (scaffolding level)	1/20/09	0.55	Mercury	EPA 324/1643	BRL	1/22/09	< 27.0	No	No	