

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-1/20/06	06BR0106-01	Southwest Area (sidewalk bridge level)	1/20/06	0.59	Mercury	EPA 324/1631	BRL	1/24/06	< 25.0	No	No	
TotalHg-ST2-1/20/06	06BR0106-02	Southeast Area (sidewalk bridge level)	1/20/06	0.59	Mercury	EPA 324/1631	BRL	1/24/06	< 25.0	No	No	
TotalHg-ST4-1/20/06	06BR0106-03	Northwest Area (street-level)	1/20/06	0.59	Mercury	EPA 324/1631	BRL	1/24/06	< 25.0	No	No	
TotalHg-ST5-1/20/06	06BR0106-04	Firehouse #10 (roof level)	1/20/06	0.58	Mercury	EPA 324/1631	BRL	1/24/06	< 26.0	No	No	
TotalHg-ST10-1/20/06	06BR0106-05	North Side Sidewalk Bridge	1/20/06	0.59	Mercury	EPA 324/1631	BRL	1/24/06	< 25.0	No	No	
TotalHg-ST11-1/20/06	06BR0106-06	90 Trinity Place (roof level)	1/20/06	0.59	Mercury	EPA 324/1631	BRL	1/24/06	< 25.0	No	No	
TotalHg-ST12-1/20/06	06BR0106-07	110 Greenwich Street (roof level)	1/20/06	0.56	Mercury	EPA 324/1631	BRL	1/24/06	< 27.0	No	No	
TotalHg-ST13-1/20/06	06BR0106-08	Marriott Hotel, 38th Floor (roof level)	1/20/06	0.60	Mercury	EPA 324/1631	BRL	1/24/06	< 25.0	No	No	
TotalHg-ST14-1/20/06	06BR0106-09	West Face - South end at corner (scaffolding level)	1/20/06	0.57	Mercury	EPA 324/1631	BRL	1/24/06	< 26.0	No	No	
TotalHg-ST15-1/20/06	06BR0106-10	South Face - East end at corner (scaffolding level)	1/20/06	0.56	Mercury	EPA 324/1631	BRL	1/24/06	< 27.0	No	No	
TotalHg-ST16-1/20/06	06BR0106-11	East Face - North end at corner (scaffolding level)	1/20/06	0.56	Mercury	EPA 324/1631	BRL	1/24/06	< 27.0	No	No	
TotalHg-ST17-1/20/06	06BR0106-12	North Face - West end at corner (scaffolding level)	1/20/06	0.56	Mercury	EPA 324/1631	BRL	1/24/06	< 27.0	No	No	
TotalHg-ST1-1/21/06	06BR0107-01	Southwest Area (sidewalk bridge level)	1/21/06	0.58	Mercury	EPA 324/1631	BRL	1/24/06	< 26.0	No	No	
TotalHg-ST2-1/21/06	06BR0107-02	Southeast Area (sidewalk bridge level)	1/21/06	0.57	Mercury	EPA 324/1631	BRL	1/24/06	< 26.0	No	No	
TotalHg-ST4-1/21/06	06BR0107-03	Northwest Area (street-level)	1/21/06	0.57	Mercury	EPA 324/1631	BRL	1/24/06	< 26.0	No	No	
TotalHg-ST5-1/21/06	06BR0107-04	Firehouse #10 (roof level)	1/21/06	0.57	Mercury	EPA 324/1631	BRL	1/24/06	< 26.0	No	No	
TotalHg-ST10-1/21/06	06BR0107-05	North Side Sidewalk Bridge	1/21/06	0.57	Mercury	EPA 324/1631	BRL	1/24/06	< 26.0	No	No	
TotalHg-ST11-1/21/06	06BR0107-06	90 Trinity Place (roof level)	1/21/06	0.57	Mercury	EPA 324/1631	BRL	1/24/06	< 26.0	No	No	
TotalHg-ST12-1/21/06	06BR0107-07	110 Greenwich Street (roof level)	1/21/06	0.61	Mercury	EPA 324/1631	BRL	1/24/06	< 25.0	No	No	
TotalHg-ST13-1/21/06	06BR0107-08	Marriott Hotel, 38th Floor (roof level)	1/21/06	0.58	Mercury	EPA 324/1631	BRL	1/24/06	< 26.0	No	No	
TotalHg-ST14-1/21/06	06BR0107-09	West Face - South end at corner (scaffolding level)	1/21/06	0.59	Mercury	EPA 324/1631	BRL	1/24/06	< 25.0	No	No	
TotalHg-ST15-1/21/06	06BR0107-10	South Face - East end at corner (scaffolding level)	1/21/06	0.58	Mercury	EPA 324/1631	BRL	1/24/06	< 26.0	No	No	
TotalHg-ST16-1/21/06	06BR0107-11	East Face - North end at corner (scaffolding level)	1/21/06	0.59	Mercury	EPA 324/1631	BRL	1/24/06	< 25.0	No	No	
TotalHg-ST17-1/21/06	06BR0107-12	North Face - West end at corner (scaffolding level)	1/21/06	0.59	Mercury	EPA 324/1631	BRL	1/24/06	< 25.0	No	No	
TotalHg-ST1-1/22/06	06BR0108-01	Southwest Area (sidewalk bridge level)	1/22/06	0.54	Mercury	EPA 324/1631	BRL	1/24/06	< 28.0	No	No	
TotalHg-ST2-1/22/06	06BR0108-02	Southeast Area (sidewalk bridge level)	1/22/06	0.55	Mercury	EPA 324/1631	BRL	1/24/06	< 27.0	No	No	
TotalHg-ST4-1/22/06	06BR0108-03	Northwest Area (street-level)	1/22/06	0.57	Mercury	EPA 324/1631	BRL	1/24/06	< 26.0	No	No	
TotalHg-ST5-1/22/06	06BR0108-04	Firehouse #10 (roof level)	1/22/06	0.57	Mercury	EPA 324/1631	BRL	1/24/06	< 26.0	No	No	
TotalHg-ST10-1/22/06	06BR0108-05	North Side Sidewalk Bridge	1/22/06	0.57	Mercury	EPA 324/1631	BRL	1/24/06	< 26.0	No	No	
TotalHg-ST11-1/22/06	06BR0108-06	90 Trinity Place (roof level)	1/22/06	0.58	Mercury	EPA 324/1631	BRL	1/24/06	< 26.0	No	No	
TotalHg-ST12-1/22/06	06BR0108-07	110 Greenwich Street (roof level)	1/22/06	0.47	Mercury	EPA 324/1631	BRL	1/24/06	< 32.0	No	No	
TotalHg-ST13-1/22/06	06BR0108-08	Marriott Hotel, 38th Floor (roof level)	1/22/06	0.57	Mercury	EPA 324/1631	BRL	1/24/06	< 26.0	No	No	
TotalHg-ST14-1/22/06	06BR0108-09	West Face - South end at corner (scaffolding level)	1/22/06	0.54	Mercury	EPA 324/1631	BRL	1/24/06	< 28.0	No	No	
TotalHg-ST15-1/22/06	06BR0108-10	South Face - East end at corner (scaffolding level)	1/22/06	0.56	Mercury	EPA 324/1631	BRL	1/24/06	< 27.0	No	No	
TotalHg-ST16-1/22/06	06BR0108-11	East Face - North end at corner (scaffolding level)	1/22/06	0.55	Mercury	EPA 324/1631	BRL	1/24/06	< 27.0	No	No	
TotalHg-ST17-1/22/06	06BR0108-12	North Face - West end at corner (scaffolding level)	1/22/06	0.56	Mercury	EPA 324/1631	BRL	1/24/06	< 27.0	No	No	