

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m <sup>3</sup> )	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-1/23/09	0905003-01	Southwest Area (sidewalk bridge level)	1/23/09	0.54	Mercury	EPA 324/1631	BRL	1/27/09	< 28.0	No	No	
TotalHg-ST2-1/23/09	0905003-02	Southeast Area (sidewalk bridge level)	1/23/09	0.60	Mercury	EPA 324/1631	BRL	1/27/09	< 25.0	No	No	
TotalHg-ST4-1/23/09	0905003-03	Northwest Area (street-level)	1/23/09	0.52	Mercury	EPA 324/1631	BRL	1/27/09	< 29.0	No	No	
TotalHg-ST5-1/23/09	0905003-04	Firehouse #10 (roof level)	1/23/09	0.57	Mercury	EPA 324/1631	BRL	1/27/09	< 26.0	No	No	
TotalHg-ST10-1/23/09	0905003-05	North Side Sidewalk Bridge	1/23/09	0.54	Mercury	EPA 324/1631	BRL	1/27/09	< 28.0	No	No	
TotalHg-ST11-1/23/09	0905003-06	90 Trinity Place (roof level)	1/23/09	0.58	Mercury	EPA 324/1631	BRL	1/27/09	< 26.0	No	No	
TotalHg-ST12-1/23/09	0905003-07	110 Greenwich Street (roof level)	1/23/09	0.58	Mercury	EPA 324/1631	BRL	1/27/09	< 26.0	No	No	
TotalHg-ST13-1/23/09	0905003-08	Marriott Hotel, 38th Floor (roof level)	1/23/09	0.57	Mercury	EPA 324/1631	BRL	1/27/09	< 26.0	No	No	
TotalHg-ST14-1/23/09	0905003-09	West Face - South end at corner (scaffolding level)	1/23/09	0.56	Mercury	EPA 324/1631	BRL	1/27/09	< 27.0	No	No	
TotalHg-ST15-1/23/09	0905003-10	South Face - East end at corner (scaffolding level)	1/23/09	0.53	Mercury	EPA 324/1631	BRL	1/27/09	< 28.0	No	No	
TotalHg-ST16-1/23/09	0905003-11	East Face - North end at corner (scaffolding level)	1/23/09	0.52	Mercury	EPA 324/1631	BRL	1/27/09	< 29.0	No	No	
TotalHg-ST17-1/23/09	0905003-12	North Face - West end at corner (scaffolding level)	1/23/09	0.53	Mercury	EPA 324/1631	BRL	1/27/09	< 28.0	No	No	
TotalHg-ST1-1/24/09	0905004-01	Southwest Area (sidewalk bridge level)	1/24/09	0.55	Mercury	EPA 324/1631	BRL	1/27/09	< 27.0	No	No	
TotalHg-ST2-1/24/09	0905004-02	Southeast Area (sidewalk bridge level)	1/24/09	0.56	Mercury	EPA 324/1631	BRL	1/27/09	< 27.0	No	No	
TotalHg-ST4-1/24/09	0905004-03	Northwest Area (street-level)	1/24/09	0.56	Mercury	EPA 324/1631	BRL	1/27/09	< 27.0	No	No	
TotalHg-ST5-1/24/09	0905004-04	Firehouse #10 (roof level)	1/24/09	0.56	Mercury	EPA 324/1631	BRL	1/27/09	< 27.0	No	No	
TotalHg-ST10-1/24/09	0905004-05	North Side Sidewalk Bridge	1/24/09	0.55	Mercury	EPA 324/1631	BRL	1/27/09	< 27.0	No	No	
TotalHg-ST11-1/24/09	0905004-06	90 Trinity Place (roof level)	1/24/09	0.60	Mercury	EPA 324/1631	BRL	1/27/09	< 25.0	No	No	
TotalHg-ST12-1/24/09	0905004-07	110 Greenwich Street (roof level)	1/24/09	0.57	Mercury	EPA 324/1631	BRL	1/27/09	< 26.0	No	No	
TotalHg-ST13-1/24/09	0905004-08	Marriott Hotel, 38th Floor (roof level)	1/24/09	0.55	Mercury	EPA 324/1631	BRL	1/27/09	< 27.0	No	No	
TotalHg-ST14-1/24/09	0905004-09	West Face - South end at corner (scaffolding level)	1/24/09	0.57	Mercury	EPA 324/1631	BRL	1/27/09	< 26.0	No	No	
TotalHg-ST15-1/24/09	0905004-10	South Face - East end at corner (scaffolding level)	1/24/09	0.55	Mercury	EPA 324/1631	BRL	1/27/09	< 27.0	No	No	
TotalHg-ST16-1/24/09	0905004-11	East Face - North end at corner (scaffolding level)	1/24/09	0.57	Mercury	EPA 324/1631	BRL	1/27/09	< 26.0	No	No	
TotalHg-ST17-1/24/09	0905004-12	North Face - West end at corner (scaffolding level)	1/24/09	0.56	Mercury	EPA 324/1631	BRL	1/27/09	< 27.0	No	No	
TotalHg-ST1-1/25/09	0905005-01	Southwest Area (sidewalk bridge level)	1/25/09	0.61	Mercury	EPA 324/1631	BRL	1/27/09	< 25.0	No	No	
TotalHg-ST2-1/25/09	0905005-02	Southeast Area (sidewalk bridge level)	1/25/09	0.61	Mercury	EPA 324/1631	BRL	1/27/09	< 25.0	No	No	
TotalHg-ST4-1/25/09	0905005-03	Northwest Area (street-level)	1/25/09	0.53	Mercury	EPA 324/1631	BRL	1/27/09	< 28.0	No	No	
TotalHg-ST5-1/25/09	0905005-04	Firehouse #10 (roof level)	1/25/09	0.55	Mercury	EPA 324/1631	BRL	1/27/09	< 27.0	No	No	
TotalHg-ST10-1/25/09	0905005-05	North Side Sidewalk Bridge	1/25/09	0.57	Mercury	EPA 324/1631	BRL	1/27/09	< 26.0	No	No	
TotalHg-ST11-1/25/09	0905005-06	90 Trinity Place (roof level)	1/25/09	0.57	Mercury	EPA 324/1631	BRL	1/27/09	< 26.0	No	No	
TotalHg-ST12-1/25/09	0905005-07	110 Greenwich Street (roof level)	1/25/09	0.56	Mercury	EPA 324/1631	BRL	1/27/09	< 27.0	No	No	
TotalHg-ST13-1/25/09	0905005-08	Marriott Hotel, 38th Floor (roof level)	1/25/09	0.54	Mercury	EPA 324/1631	BRL	1/27/09	< 28.0	No	No	
TotalHg-ST14-1/25/09	0905005-09	West Face - South end at corner (scaffolding level)	1/25/09	0.63	Mercury	EPA 324/1631	BRL	1/27/09	< 24.0	No	No	
TotalHg-ST15-1/25/09	0905005-10	South Face - East end at corner (scaffolding level)	1/25/09	0.60	Mercury	EPA 324/1631	BRL	1/27/09	< 25.0	No	No	
TotalHg-ST16-1/25/09	0905005-11	East Face - North end at corner (scaffolding level)	1/25/09	0.61	Mercury	EPA 324/1631	BRL	1/27/09	< 25.0	No	No	
TotalHg-ST17-1/25/09	0905005-12	North Face - West end at corner (scaffolding level)	1/25/09	0.65	Mercury	EPA 324/1631	BRL	1/27/09	< 23.0	No	No	