

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-1/27/06	06BR0137-01	Southwest Area (sidewalk bridge level)	1/27/06	0.57	Mercury	EPA 324/1631	BRL	1/31/06	< 26.0	No	No	
TotalHg-ST2-1/27/06	06BR0137-02	Southeast Area (sidewalk bridge level)	1/27/06	0.56	Mercury	EPA 324/1631	BRL	1/31/06	< 27.0	No	No	
TotalHg-ST4-1/27/06	06BR0137-03	Northwest Area (street-level)	1/27/06	0.55	Mercury	EPA 324/1631	BRL	1/31/06	< 27.0	No	No	
TotalHg-ST5-1/27/06	06BR0137-04	Firehouse #10 (roof level)	1/27/06	0.58	Mercury	EPA 324/1631	BRL	1/31/06	< 26.0	No	No	
TotalHg-ST10-1/27/06	06BR0137-05	North Side Sidewalk Bridge	1/27/06	0.55	Mercury	EPA 324/1631	BRL	1/31/06	< 27.0	No	No	
TotalHg-ST11-1/27/06	06BR0137-06	90 Trinity Place (roof level)	1/27/06	0.59	Mercury	EPA 324/1631	BRL	1/31/06	< 25.0	No	No	
TotalHg-ST12-1/27/06	06BR0137-07	110 Greenwich Street (roof level)	1/27/06	0.59	Mercury	EPA 324/1631	BRL	1/31/06	< 25.0	No	No	
TotalHg-ST13-1/27/06	06BR0137-08	Marriott Hotel, 38th Floor (roof level)	1/27/06	0.60	Mercury	EPA 324/1631	BRL	1/31/06	< 25.0	No	No	
TotalHg-ST14-1/27/06	06BR0137-09	West Face - South end at corner (scaffolding level)	1/27/06	0.53	Mercury	EPA 324/1631	BRL	1/31/06	< 28.0	No	No	
TotalHg-ST15-1/27/06	06BR0137-10	South Face - East end at corner (scaffolding level)	1/27/06	0.53	Mercury	EPA 324/1631	BRL	1/31/06	< 28.0	No	No	
TotalHg-ST16-1/27/06	06BR0137-11	East Face - North end at corner (scaffolding level)	1/27/06	0.54	Mercury	EPA 324/1631	BRL	1/31/06	< 28.0	No	No	
TotalHg-ST17-1/27/06	06BR0137-12	North Face - West end at corner (scaffolding level)	1/27/06	0.52	Mercury	EPA 324/1631	BRL	1/31/06	< 29.0	No	No	
TotalHg-ST1-1/28/06	06BR0138-01	Southwest Area (sidewalk bridge level)	1/28/06	0.58	Mercury	EPA 324/1631	BRL	1/31/06	< 26.0	No	No	
TotalHg-ST2-1/28/06	06BR0138-02	Southeast Area (sidewalk bridge level)	1/28/06	0.58	Mercury	EPA 324/1631	BRL	1/31/06	< 26.0	No	No	
TotalHg-ST4-1/28/06	06BR0138-03	Northwest Area (street-level)	1/28/06	0.58	Mercury	EPA 324/1631	BRL	1/31/06	< 26.0	No	No	
TotalHg-ST5-1/28/06	06BR0138-04	Firehouse #10 (roof level)	1/28/06	0.59	Mercury	EPA 324/1631	BRL	1/31/06	< 25.0	No	No	
TotalHg-ST10-1/28/06	06BR0138-05	North Side Sidewalk Bridge	1/28/06	0.58	Mercury	EPA 324/1631	BRL	1/31/06	< 26.0	No	No	
TotalHg-ST11-1/28/06	06BR0138-06	90 Trinity Place (roof level)	1/28/06	0.58	Mercury	EPA 324/1631	BRL	1/31/06	< 26.0	No	No	
TotalHg-ST12-1/28/06	06BR0138-07	110 Greenwich Street (roof level)	1/28/06	0.56	Mercury	EPA 324/1631	BRL	1/31/06	< 27.0	No	No	
TotalHg-ST13-1/28/06	06BR0138-08	Marriott Hotel, 38th Floor (roof level)	1/28/06	0.57	Mercury	EPA 324/1631	BRL	1/31/06	< 26.0	No	No	
TotalHg-ST14-1/28/06	06BR0138-09	West Face - South end at corner (scaffolding level)	1/28/06	0.57	Mercury	EPA 324/1631	BRL	1/31/06	< 26.0	No	No	
TotalHg-ST15-1/28/06	06BR0138-10	South Face - East end at corner (scaffolding level)	1/28/06	0.57	Mercury	EPA 324/1631	BRL	1/31/06	< 26.0	No	No	
TotalHg-ST16-1/28/06	06BR0138-11	East Face - North end at corner (scaffolding level)	1/28/06	0.57	Mercury	EPA 324/1631	BRL	1/31/06	< 26.0	No	No	
TotalHg-ST17-1/28/06	06BR0138-12	North Face - West end at corner (scaffolding level)	1/28/06	0.57	Mercury	EPA 324/1631	BRL	1/31/06	< 26.0	No	No	
TotalHg-ST1-1/29/06	06BR0139-01	Southwest Area (sidewalk bridge level)	1/29/06	0.56	Mercury	EPA 324/1631	BRL	1/31/06	< 27.0	No	No	
TotalHg-ST2-1/29/06	06BR0139-02	Southeast Area (sidewalk bridge level)	1/29/06	0.56	Mercury	EPA 324/1631	BRL	1/31/06	< 27.0	No	No	
TotalHg-ST4-1/29/06	06BR0139-03	Northwest Area (street-level)	1/29/06	0.59	Mercury	EPA 324/1631	BRL	1/31/06	< 25.0	No	No	
TotalHg-ST5-1/29/06	06BR0139-04	Firehouse #10 (roof level)	1/29/06	0.56	Mercury	EPA 324/1631	BRL	1/31/06	< 27.0	No	No	
TotalHg-ST10-1/29/06	06BR0139-05	North Side Sidewalk Bridge	1/29/06	0.59	Mercury	EPA 324/1631	BRL	1/31/06	< 25.0	No	No	
TotalHg-ST11-1/29/06	06BR0139-06	90 Trinity Place (roof level)	1/29/06	0.56	Mercury	EPA 324/1631	BRL	1/31/06	< 27.0	No	No	
TotalHg-ST12-1/29/06	06BR0139-07	110 Greenwich Street (roof level)	1/29/06	0.57	Mercury	EPA 324/1631	BRL	1/31/06	< 26.0	No	No	
TotalHg-ST13-1/29/06	06BR0139-08	Marriott Hotel, 38th Floor (roof level)	1/29/06	0.57	Mercury	EPA 324/1631	BRL	1/31/06	< 26.0	No	No	
TotalHg-ST14-1/29/06	06BR0139-09	West Face - South end at corner (scaffolding level)	1/29/06	0.63	Mercury	EPA 324/1631	BRL	1/31/06	< 24.0	No	No	
TotalHg-ST15-1/29/06	06BR0139-10	South Face - East end at corner (scaffolding level)	1/29/06	0.63	Mercury	EPA 324/1631	BRL	1/31/06	< 24.0	No	No	
TotalHg-ST16-1/29/06	06BR0139-11	East Face - North end at corner (scaffolding level)	1/29/06	0.63	Mercury	EPA 324/1631	BRL	1/31/06	< 24.0	No	No	
TotalHg-ST17-1/29/06	06BR0139-12	North Face - West end at corner (scaffolding level)	1/29/06	0.63	Mercury	EPA 324/1631	BRL	1/31/06	< 24.0	No	No	