

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m ³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-2/15/06	06BR0235-01	Southwest Area (sidewalk bridge level)	2/15/06	0.57	Mercury	EPA 324/1631	BRL	2/17/06	< 26.0	No	No	
TotalHg-ST2-2/15/06	06BR0235-02	Southeast Area (sidewalk bridge level)	2/15/06	0.57	Mercury	EPA 324/1631	BRL	2/17/06	< 26.0	No	No	
TotalHg-ST5-2/15/06	06BR0235-03	Firehouse #10 (roof level)	2/15/06	0.57	Mercury	EPA 324/1631	BRL	2/17/06	< 26.0	No	No	
TotalHg-ST10-2/15/06	06BR0235-04	North Side Sidewalk Bridge	2/15/06	0.58	Mercury	EPA 324/1631	BRL	2/17/06	< 26.0	No	No	
TotalHg-ST11-2/15/06	06BR0235-05	90 Trinity Place (roof level)	2/15/06	0.57	Mercury	EPA 324/1631	BRL	2/17/06	< 26.0	No	No	
TotalHg-ST12-2/15/06	06BR0235-06	110 Greenwich Street (roof level)	2/15/06	0.57	Mercury	EPA 324/1631	BRL	2/17/06	< 26.0	No	No	
TotalHg-ST13-2/15/06	06BR0235-07	Marriott Hotel, 38th Floor (roof level)	2/15/06	0.57	Mercury	EPA 324/1631	BRL	2/17/06	< 26.0	No	No	
TotalHg-ST14-2/15/06	06BR0235-08	West Face - South end at corner (scaffolding level)	2/15/06	0.57	Mercury	EPA 324/1631	BRL	2/17/06	< 26.0	No	No	
TotalHg-ST16-2/15/06	06BR0235-09	East Face - North end at corner (scaffolding level)	2/15/06	0.58	Mercury	EPA 324/1631	BRL	2/17/06	< 26.0	No	No	
TotalHg-ST17-2/15/06	06BR0235-10	North Face - West end at corner (scaffolding level)	2/15/06	0.57	Mercury	EPA 324/1631	BRL	2/17/06	< 26.0	No	No	

Note:

- Mercury samples at Station 4 (Northwest Area [street-level]) and at Station 15 (South Face - East end at corner [scaffolding level]) on February 15, 2006 were not available for analysis due to the pump failure.