

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-2/18/09	0908019-01	Southwest Area (sidewalk bridge level)	2/18/09	0.62	Mercury	EPA 324/1631	BRL	2/20/09	< 24.0	No	No	
TotalHg-ST2-2/18/09	0908019-02	Southeast Area (sidewalk bridge level)	2/18/09	0.60	Mercury	EPA 324/1631	BRL	2/20/09	< 25.0	No	No	
TotalHg-ST4-2/18/09	0908019-03	Northwest Area (street-level)	2/18/09	0.52	Mercury	EPA 324/1631	BRL	2/20/09	< 29.0	No	No	
TotalHg-ST5-2/18/09	0908019-04	Firehouse #10 (roof level)	2/18/09	0.57	Mercury	EPA 324/1631	BRL	2/20/09	< 26.0	No	No	
TotalHg-ST10-2/18/09	0908019-05	North Side Sidewalk Bridge	2/18/09	0.55	Mercury	EPA 324/1631	BRL	2/20/09	< 27.0	No	No	
TotalHg-ST11-2/18/09	0908019-06	90 Trinity Place (roof level)	2/18/09	0.52	Mercury	EPA 324/1631	BRL	2/20/09	< 29.0	No	No	
TotalHg-ST12-2/18/09	0908019-07	110 Greenwich Street (roof level)	2/18/09	0.58	Mercury	EPA 324/1631	BRL	2/20/09	< 26.0	No	No	
TotalHg-ST13-2/18/09	0908019-08	Marriott Hotel, 38th Floor (roof level)	2/18/09	0.59	Mercury	EPA 324/1631	BRL	2/20/09	< 25.0	No	No	
TotalHg-ST14-2/18/09	0908019-09	West Face - South end at corner (scaffolding level)	2/18/09	0.62	Mercury	EPA 324/1631	BRL	2/20/09	< 24.0	No	No	
TotalHg-ST15-2/18/09	0908019-10	South Face - East end at corner (scaffolding level)	2/18/09	0.56	Mercury	EPA 324/1631	BRL	2/20/09	< 27.0	No	No	
TotalHg-ST16-2/18/09	0908019-11	East Face - North end at corner (scaffolding level)	2/18/09	0.53	Mercury	EPA 324/1631	BRL	2/20/09	< 28.0	No	No	
TotalHg-ST17-2/18/09	0908019-12	North Face - West end at corner (scaffolding level)	2/18/09	0.53	Mercury	EPA 324/1631	BRL	2/20/09	< 28.0	No	No	
TotalHg-ST1-2/19/09	0908025-01	Southwest Area (sidewalk bridge level)	2/19/09	0.62	Mercury	EPA 324/1631	BRL	2/21/09	< 24.0	No	No	
TotalHg-ST2-2/19/09	0908025-02	Southeast Area (sidewalk bridge level)	2/19/09	0.59	Mercury	EPA 324/1631	BRL	2/21/09	< 25.0	No	No	
TotalHg-ST4-2/19/09	0908025-03	Northwest Area (street-level)	2/19/09	0.60	Mercury	EPA 324/1631	BRL	2/21/09	< 25.0	No	No	
TotalHg-ST5-2/19/09	0908025-04	Firehouse #10 (roof level)	2/19/09	0.55	Mercury	EPA 324/1631	BRL	2/21/09	< 27.0	No	No	
TotalHg-ST10-2/19/09	0908025-05	North Side Sidewalk Bridge	2/19/09	0.55	Mercury	EPA 324/1631	BRL	2/21/09	< 27.0	No	No	
TotalHg-ST11-2/19/09	0908025-06	90 Trinity Place (roof level)	2/19/09	0.55	Mercury	EPA 324/1631	BRL	2/21/09	< 27.0	No	No	
TotalHg-ST12-2/19/09	0908025-07	110 Greenwich Street (roof level)	2/19/09	0.55	Mercury	EPA 324/1631	BRL	2/21/09	< 27.0	No	No	
TotalHg-ST13-2/19/09	0908025-08	Marriott Hotel, 38th Floor (roof level)	2/19/09	0.57	Mercury	EPA 324/1631	BRL	2/21/09	< 26.0	No	No	
TotalHg-ST14-2/19/09	0908025-09	West Face - South end at corner (scaffolding level)	2/19/09	0.61	Mercury	EPA 324/1631	BRL	2/21/09	< 25.0	No	No	
TotalHg-ST15-2/19/09	0908025-10	South Face - East end at corner (scaffolding level)	2/19/09	0.53	Mercury	EPA 324/1631	BRL	2/21/09	< 28.0	No	No	
TotalHg-ST16-2/19/09	0908025-11	East Face - North end at corner (scaffolding level)	2/19/09	0.56	Mercury	EPA 324/1631	BRL	2/21/09	< 27.0	No	No	
TotalHg-ST17-2/19/09	0908025-12	North Face - West end at corner (scaffolding level)	2/19/09	0.55	Mercury	EPA 324/1631	BRL	2/21/09	< 27.0	No	No	
TotalHg-ST1-2/20/09	0909002-01	Southwest Area (sidewalk bridge level)	2/20/09	0.59	Mercury	EPA 324/1631	BRL	2/23/09	< 25.0	No	No	
TotalHg-ST2-2/20/09	0909002-02	Southeast Area (sidewalk bridge level)	2/20/09	0.60	Mercury	EPA 324/1631	BRL	2/23/09	< 25.0	No	No	
TotalHg-ST4-2/20/09	0909002-03	Northwest Area (street-level)	2/20/09	0.57	Mercury	EPA 324/1631	BRL	2/23/09	< 26.0	No	No	
TotalHg-ST5-2/20/09	0909002-04	Firehouse #10 (roof level)	2/20/09	0.53	Mercury	EPA 324/1631	BRL	2/23/09	< 28.0	No	No	
TotalHg-ST10-2/20/09	0909002-05	North Side Sidewalk Bridge	2/20/09	0.56	Mercury	EPA 324/1631	BRL	2/23/09	< 27.0	No	No	
TotalHg-ST11-2/20/09	0909002-06	90 Trinity Place (roof level)	2/20/09	0.56	Mercury	EPA 324/1631	BRL	2/23/09	< 27.0	No	No	
TotalHg-ST12-2/20/09	0909002-07	110 Greenwich Street (roof level)	2/20/09	0.52	Mercury	EPA 324/1631	BRL	2/23/09	< 29.0	No	No	
TotalHg-ST13-2/20/09	0909002-08	Marriott Hotel, 38th Floor (roof level)	2/20/09	0.55	Mercury	EPA 324/1631	BRL	2/23/09	< 27.0	No	No	
TotalHg-ST14-2/20/09	0909002-09	West Face - South end at corner (scaffolding level)	2/20/09	0.57	Mercury	EPA 324/1631	BRL	2/23/09	< 26.0	No	No	
TotalHg-ST15-2/20/09	0909002-10	South Face - East end at corner (scaffolding level)	2/20/09	0.55	Mercury	EPA 324/1631	BRL	2/23/09	< 27.0	No	No	
TotalHg-ST16-2/20/09	0909002-11	East Face - North end at corner (scaffolding level)	2/20/09	0.52	Mercury	EPA 324/1631	BRL	2/23/09	< 29.0	No	No	
TotalHg-ST17-2/20/09	0909002-12	North Face - West end at corner (scaffolding level)	2/20/09	0.57	Mercury	EPA 324/1631	BRL	2/23/09	< 26.0	No	No	
TotalHg-ST1-2/21/09	0909009-01	Southwest Area (sidewalk bridge level)	2/21/09	0.55	Mercury	EPA 324/1631	BRL	2/24/09	< 27.0	No	No	
TotalHg-ST2-2/21/09	0909009-02	Southeast Area (sidewalk bridge level)	2/21/09	0.57	Mercury	EPA 324/1631	BRL	2/24/09	< 26.0	No	No	
TotalHg-ST4-2/21/09	0909009-03	Northwest Area (street-level)	2/21/09	0.53	Mercury	EPA 324/1631	BRL	2/24/09	< 28.0	No	No	
TotalHg-ST5-2/21/09	0909009-04	Firehouse #10 (roof level)	2/21/09	0.56	Mercury	EPA 324/1631	BRL	2/24/09	< 27.0	No	No	
TotalHg-ST10-2/21/09	0909009-05	North Side Sidewalk Bridge	2/21/09	0.55	Mercury	EPA 324/1631	BRL	2/24/09	< 27.0	No	No	
TotalHg-ST11-2/21/09	0909009-06	90 Trinity Place (roof level)	2/21/09	0.55	Mercury	EPA 324/1631	BRL	2/24/09	< 27.0	No	No	
TotalHg-ST12-2/21/09	0909009-07	110 Greenwich Street (roof level)	2/21/09	0.57	Mercury	EPA 324/1631	BRL	2/24/09	< 26.0	No	No	
TotalHg-ST13-2/21/09	0909009-08	Marriott Hotel, 38th Floor (roof level)	2/21/09	0.55	Mercury	EPA 324/1631	BRL	2/24/09	< 27.0	No	No	
TotalHg-ST14-2/21/09	0909009-09	West Face - South end at corner (scaffolding level)	2/21/09	0.53	Mercury	EPA 324/1631	BRL	2/24/09	< 28.0	No	No	
TotalHg-ST15-2/21/09	0909009-10	South Face - East end at corner (scaffolding level)	2/21/09	0.54	Mercury	EPA 324/1631	BRL	2/24/09	< 28.0	No	No	
TotalHg-ST16-2/21/09	0909009-11	East Face - North end at corner (scaffolding level)	2/21/09	0.55	Mercury	EPA 324/1631	BRL	2/24/09	< 27.0	No	No	
TotalHg-ST17-2/21/09	0909009-12	North Face - West end at corner (scaffolding level)	2/21/09	0.52	Mercury	EPA 324/1631	BRL	2/24/09	< 29.0	No	No	
TotalHg-ST1-2/22/09	0909011-01	Southwest Area (sidewalk bridge level)	2/22/09	0.61	Mercury	EPA 324/1631	BRL	2/24/09	< 25.0	No	No	
TotalHg-ST2-2/22/09	0909011-02	Southeast Area (sidewalk bridge level)	2/22/09	0.57	Mercury	EPA 324/1631	BRL	2/24/09	< 26.0	No	No	
TotalHg-ST4-2/22/09	0909011-03	Northwest Area (street-level)	2/22/09	0.56	Mercury	EPA 324/1631	BRL	2/24/09	< 27.0	No	No	
TotalHg-ST5-2/22/09	0909011-04	Firehouse #10 (roof level)	2/22/09	0.56	Mercury	EPA 324/1631	BRL	2/24/09	< 27.0	No	No	
TotalHg-ST10-2/22/09	0909011-05	North Side Sidewalk Bridge	2/22/09	0.53	Mercury	EPA 324/1631	BRL	2/24/09	< 28.0	No	No	
TotalHg-ST11-2/22/09	0909011-06	90 Trinity Place (roof level)	2/22/09	0.56	Mercury	EPA 324/1631	BRL	2/24/09	< 27.0	No	No	
TotalHg-ST12-2/22/09	0909011-07	110 Greenwich Street (roof level)	2/22/09	0.55	Mercury	EPA 324/1631	BRL	2/24/09	< 27.0	No	No	
TotalHg-ST13-2/22/09	0909011-08	Marriott Hotel, 38th Floor (roof level)	2/22/09	0.54	Mercury	EPA 324/1631	BRL	2/24/09	< 28.0	No	No	
TotalHg-ST14-2/22/09	0909011-09	West Face - South end at corner (scaffolding level)	2/22/09	0.66	Mercury	EPA 324/1631	BRL	2/24/09	< 23.0	No	No	
TotalHg-ST15-2/22/09	0909011-10	South Face - East end at corner (scaffolding level)	2/22/09	0.56	Mercury	EPA 324/1631	BRL	2/24/09	< 27.0	No	No	
TotalHg-ST16-2/22/09	0909011-11	East Face - North end at corner (scaffolding level)	2/22/09	0.60	Mercury	EPA 324/1631	BRL	2/24/09	< 25.0	No	No	
TotalHg-ST17-2/22/09	0909011-12	North Face - West end at corner (scaffolding level)	2/22/09	0.58	Mercury	EPA 324/1631	BRL	2/24/09	< 26.0	No	No	