

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-2/28/07	07BR0275-01	Southwest Area (sidewalk bridge level)	2/28/07	0.58	Mercury	EPA 324/1631	BRL	3/2/07	< 26.0	No	No	
TotalHg-ST2-2/28/07	07BR0275-02	Southeast Area (sidewalk bridge level)	2/28/07	0.60	Mercury	EPA 324/1631	BRL	3/2/07	< 25.0	No	No	
TotalHg-ST4-2/28/07	07BR0275-03	Northwest Area (street-level)	2/28/07	0.54	Mercury	EPA 324/1631	BRL	3/2/07	< 28.0	No	No	
TotalHg-ST5-2/28/07	07BR0275-04	Firehouse #10 (roof level)	2/28/07	0.58	Mercury	EPA 324/1631	BRL	3/2/07	< 26.0	No	No	
TotalHg-ST10-2/28/07	07BR0275-05	North Side Sidewalk Bridge	2/28/07	0.56	Mercury	EPA 324/1631	BRL	3/2/07	< 27.0	No	No	
TotalHg-ST11-2/28/07	07BR0275-06	90 Trinity Place (roof level)	2/28/07	0.59	Mercury	EPA 324/1631	BRL	3/2/07	< 25.0	No	No	
TotalHg-ST12-2/28/07	07BR0275-07	110 Greenwich Street (roof level)	2/28/07	0.59	Mercury	EPA 324/1631	BRL	3/2/07	< 25.0	No	No	
TotalHg-ST13-2/28/07	07BR0275-08	Marriott Hotel, 38th Floor (roof level)	2/28/07	0.59	Mercury	EPA 324/1631	BRL	3/2/07	< 25.0	No	No	
TotalHg-ST14-2/28/07	07BR0275-09	West Face - South end at corner (scaffolding level)	2/28/07	0.55	Mercury	EPA 324/1631	BRL	3/2/07	< 27.0	No	No	
TotalHg-ST15-2/28/07	07BR0275-10	South Face - East end at corner (scaffolding level)	2/28/07	0.58	Mercury	EPA 324/1631	BRL	3/2/07	< 26.0	No	No	
TotalHg-ST16-2/28/07	07BR0275-11	East Face - North end at corner (scaffolding level)	2/28/07	0.55	Mercury	EPA 324/1631	BRL	3/2/07	< 27.0	No	No	
TotalHg-ST17-2/28/07	07BR0275-12	North Face - West end at corner (scaffolding level)	2/28/07	0.56	Mercury	EPA 324/1631	BRL	3/2/07	< 27.0	No	No	
TotalHg-ST1-3/1/07	07BR0279-01	Southwest Area (sidewalk bridge level)	3/1/07	0.58	Mercury	EPA 324/1631	BRL	3/3/07	< 26.0	No	No	
TotalHg-ST2-3/1/07	07BR0279-02	Southeast Area (sidewalk bridge level)	3/1/07	0.58	Mercury	EPA 324/1631	BRL	3/3/07	< 26.0	No	No	
TotalHg-ST4-3/1/07	07BR0279-03	Northwest Area (street-level)	3/1/07	0.60	Mercury	EPA 324/1631	BRL	3/3/07	< 25.0	No	No	
TotalHg-ST5-3/1/07	07BR0279-04	Firehouse #10 (roof level)	3/1/07	0.60	Mercury	EPA 324/1631	BRL	3/3/07	< 25.0	No	No	
TotalHg-ST10-3/1/07	07BR0279-05	North Side Sidewalk Bridge	3/1/07	0.58	Mercury	EPA 324/1631	BRL	3/3/07	< 26.0	No	No	
TotalHg-ST11-3/1/07	07BR0279-06	90 Trinity Place (roof level)	3/1/07	0.54	Mercury	EPA 324/1631	BRL	3/3/07	< 28.0	No	No	
TotalHg-ST12-3/1/07	07BR0279-07	110 Greenwich Street (roof level)	3/1/07	0.60	Mercury	EPA 324/1631	BRL	3/3/07	< 25.0	No	No	
TotalHg-ST13-3/1/07	07BR0279-08	Marriott Hotel, 38th Floor (roof level)	3/1/07	0.57	Mercury	EPA 324/1631	BRL	3/3/07	< 26.0	No	No	
TotalHg-ST14-3/1/07	07BR0279-09	West Face - South end at corner (scaffolding level)	3/1/07	0.59	Mercury	EPA 324/1631	BRL	3/3/07	< 25.0	No	No	
TotalHg-ST15-3/1/07	07BR0279-10	South Face - East end at corner (scaffolding level)	3/1/07	0.58	Mercury	EPA 324/1631	BRL	3/3/07	< 26.0	No	No	
TotalHg-ST16-3/1/07	07BR0279-11	East Face - North end at corner (scaffolding level)	3/1/07	0.58	Mercury	EPA 324/1631	BRL	3/3/07	< 26.0	No	No	
TotalHg-ST17-3/1/07	07BR0279-12	North Face - West end at corner (scaffolding level)	3/1/07	0.58	Mercury	EPA 324/1631	BRL	3/3/07	< 26.0	No	No	