

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-3/3/06	06BR0325-01	Southwest Area (sidewalk bridge level)	3/3/06	0.57	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST2-3/3/06	06BR0325-02	Southeast Area (sidewalk bridge level)	3/3/06	0.57	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST4-3/3/06	06BR0325-03	Northwest Area (street-level)	3/3/06	0.59	Mercury	EPA 324/1631	BRL	3/7/06	< 25.0	No	No	
TotalHg-ST5-3/3/06	06BR0325-04	Firehouse #10 (roof level)	3/3/06	0.58	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST10-3/3/06	06BR0325-05	North Side Sidewalk Bridge	3/3/06	0.59	Mercury	EPA 324/1631	BRL	3/7/06	< 25.0	No	No	
TotalHg-ST11-3/3/06	06BR0325-06	90 Trinity Place (roof level)	3/3/06	0.58	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST12-3/3/06	06BR0325-07	110 Greenwich Street (roof level)	3/3/06	0.58	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST13-3/3/06	06BR0325-08	Marriott Hotel, 38th Floor (roof level)	3/3/06	0.60	Mercury	EPA 324/1631	BRL	3/7/06	< 25.0	No	No	
TotalHg-ST15-3/3/06	06BR0325-09	South Face - East end at corner (scaffolding level)	3/3/06	0.58	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST16-3/3/06	06BR0325-10	East Face - North end at corner (scaffolding level)	3/3/06	0.58	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST17-3/3/06	06BR0325-11	North Face - West end at corner (scaffolding level)	3/3/06	0.58	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST1-3/4/06	06BR0326-01	Southwest Area (sidewalk bridge level)	3/4/06	0.57	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST2-3/4/06	06BR0326-02	Southeast Area (sidewalk bridge level)	3/4/06	0.57	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST4-3/4/06	06BR0326-03	Northwest Area (street-level)	3/4/06	0.57	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST5-3/4/06	06BR0326-04	Firehouse #10 (roof level)	3/4/06	0.58	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST10-3/4/06	06BR0326-05	North Side Sidewalk Bridge	3/4/06	0.57	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST11-3/4/06	06BR0326-06	90 Trinity Place (roof level)	3/4/06	0.58	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST12-3/4/06	06BR0326-07	110 Greenwich Street (roof level)	3/4/06	0.54	Mercury	EPA 324/1631	BRL	3/7/06	< 28.0	No	No	
TotalHg-ST13-3/4/06	06BR0326-08	Marriott Hotel, 38th Floor (roof level)	3/4/06	0.57	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST14-3/4/06	06BR0326-09	West Face - South end at corner (scaffolding level)	3/4/06	0.56	Mercury	EPA 324/1631	BRL	3/7/06	< 27.0	No	No	
TotalHg-ST15-3/4/06	06BR0326-10	South Face - East end at corner (scaffolding level)	3/4/06	0.56	Mercury	EPA 324/1631	BRL	3/7/06	< 27.0	No	No	
TotalHg-ST16-3/4/06	06BR0326-11	East Face - North end at corner (scaffolding level)	3/4/06	0.55	Mercury	EPA 324/1631	BRL	3/7/06	< 27.0	No	No	
TotalHg-ST17-3/4/06	06BR0326-12	North Face - West end at corner (scaffolding level)	3/4/06	0.56	Mercury	EPA 324/1631	BRL	3/7/06	< 27.0	No	No	
TotalHg-ST1-3/5/06	06BR0327-01	Southwest Area (sidewalk bridge level)	3/5/06	0.56	Mercury	EPA 324/1631	BRL	3/7/06	< 27.0	No	No	
TotalHg-ST2-3/5/06	06BR0327-02	Southeast Area (sidewalk bridge level)	3/5/06	0.55	Mercury	EPA 324/1631	BRL	3/7/06	< 27.0	No	No	
TotalHg-ST4-3/5/06	06BR0327-03	Northwest Area (street-level)	3/5/06	0.57	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST5-3/5/06	06BR0327-04	Firehouse #10 (roof level)	3/5/06	0.56	Mercury	EPA 324/1631	BRL	3/7/06	< 27.0	No	No	
TotalHg-ST10-3/5/06	06BR0327-05	North Side Sidewalk Bridge	3/5/06	0.56	Mercury	EPA 324/1631	BRL	3/7/06	< 27.0	No	No	
TotalHg-ST11-3/5/06	06BR0327-06	90 Trinity Place (roof level)	3/5/06	0.54	Mercury	EPA 324/1631	BRL	3/7/06	< 28.0	No	No	
TotalHg-ST12-3/5/06	06BR0327-07	110 Greenwich Street (roof level)	3/5/06	0.58	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST13-3/5/06	06BR0327-08	Marriott Hotel, 38th Floor (roof level)	3/5/06	0.55	Mercury	EPA 324/1631	BRL	3/7/06	< 27.0	No	No	
TotalHg-ST14-3/5/06	06BR0327-09	West Face - South end at corner (scaffolding level)	3/5/06	0.58	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST15-3/5/06	06BR0327-10	South Face - East end at corner (scaffolding level)	3/5/06	0.58	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST16-3/5/06	06BR0327-11	East Face - North end at corner (scaffolding level)	3/5/06	0.58	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	
TotalHg-ST17-3/5/06	06BR0327-12	North Face - West end at corner (scaffolding level)	3/5/06	0.58	Mercury	EPA 324/1631	BRL	3/7/06	< 26.0	No	No	

Note:

1. The mercury sample at Station 14 (South end at corner [scaffolding level]) on March 3, 2006 was not available for analysis as extreme weather conditions and related worker safety considerations prevented worker access to the scaffolding at this location.