

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									300			
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-3/7/09	0911005-01	Southwest Area (sidewalk bridge level)	3/7/09	0.52	Mercury	EPA 324/1631	BRL	3/10/09	< 29.0	No	No	
TotalHG-ST2-3/7/09	0911005-02	Southeast Area (sidewalk bridge level)	3/7/09	0.54	Mercury	EPA 324/1631	BRL	3/10/09	< 28.0	No	No	
TotalHg-ST4-3/7/09	0911005-03	Northwest Area (street-level)	3/7/09	0.56	Mercury	EPA 324/1631	BRL	3/10/09	< 27.0	No	No	
TotalHg-ST5-3/7/09	0911005-04	Firehouse #10 (roof level)	3/7/09	0.55	Mercury	EPA 324/1631	BRL	3/10/09	< 27.0	No	No	
TotalHg-ST10-3/7/09	0911005-05	North Side Sidewalk Bridge	3/7/09	0.57	Mercury	EPA 324/1631	BRL	3/10/09	< 26.0	No	No	
TotalHg-ST11-3/7/09	0911005-06	90 Trinity Place (roof level)	3/7/09	0.54	Mercury	EPA 324/1631	BRL	3/10/09	< 28.0	No	No	
TotalHg-ST12-3/7/09	0911005-07	110 Greenwich Street (roof level)	3/7/09	0.51	Mercury	EPA 324/1631	BRL	3/10/09	< 29.0	No	No	
TotalHg-ST13-3/7/09	0911005-08	Marriott Hotel, 38th Floor (roof level)	3/7/09	0.52	Mercury	EPA 324/1631	BRL	3/10/09	< 29.0	No	No	
TotalHg-ST14-3/7/09	0911005-09	West Face - South end at corner (scaffolding level)	3/7/09	0.51	Mercury	EPA 324/1631	BRL	3/10/09	< 29.0	No	No	
TotalHg-ST15-3/7/09	0911005-10	South Face - East end at corner (scaffolding level)	3/7/09	0.53	Mercury	EPA 324/1631	BRL	3/10/09	< 28.0	No	No	
TotalHg-ST16-3/7/09	0911005-11	East Face - North end at corner (scaffolding level)	3/7/09	0.55	Mercury	EPA 324/1631	BRL	3/10/09	< 27.0	No	No	
TotalHg-ST17-3/7/09	0911005-12	North Face - West end at corner (scaffolding level)	3/7/09	0.57	Mercury	EPA 324/1631	BRL	3/10/09	< 26.0	No	No	
TotalHg-ST1-3/8/09	0911006-01	Southwest Area (sidewalk bridge level)	3/8/09	0.54	Mercury	EPA 324/1631	BRL	3/10/09	< 28.0	No	No	
TotalHG-ST2-3/8/09	0911006-02	Southeast Area (sidewalk bridge level)	3/8/09	0.55	Mercury	EPA 324/1631	BRL	3/10/09	< 27.0	No	No	
TotalHg-ST4-3/8/09	0911006-03	Northwest Area (street-level)	3/8/09	0.54	Mercury	EPA 324/1631	BRL	3/10/09	< 28.0	No	No	
TotalHg-ST5-3/8/09	0911006-04	Firehouse #10 (roof level)	3/8/09	0.55	Mercury	EPA 324/1631	BRL	3/10/09	< 27.0	No	No	
TotalHg-ST10-3/8/09	0911006-05	North Side Sidewalk Bridge	3/8/09	0.56	Mercury	EPA 324/1631	BRL	3/10/09	< 27.0	No	No	
TotalHg-ST11-3/8/09	0911006-06	90 Trinity Place (roof level)	3/8/09	0.53	Mercury	EPA 324/1631	BRL	3/10/09	< 28.0	No	No	
TotalHg-ST12-3/8/09	0911006-07	110 Greenwich Street (roof level)	3/8/09	0.57	Mercury	EPA 324/1631	BRL	3/10/09	< 26.0	No	No	
TotalHg-ST13-3/8/09	0911006-08	Marriott Hotel, 38th Floor (roof level)	3/8/09	0.57	Mercury	EPA 324/1631	BRL	3/10/09	< 26.0	No	No	
TotalHg-ST14-3/8/09	0911006-09	West Face - South end at corner (scaffolding level)	3/8/09	0.63	Mercury	EPA 324/1631	BRL	3/10/09	< 24.0	No	No	
TotalHg-ST15-3/8/09	0911006-10	South Face - East end at corner (scaffolding level)	3/8/09	0.57	Mercury	EPA 324/1631	BRL	3/10/09	< 26.0	No	No	
TotalHg-ST16-3/8/09	0911006-11	East Face - North end at corner (scaffolding level)	3/8/09	0.57	Mercury	EPA 324/1631	BRL	3/10/09	< 26.0	No	No	
TotalHg-ST17-3/8/09	0911006-12	North Face - West end at corner (scaffolding level)	3/8/09	0.58	Mercury	EPA 324/1631	BRL	3/10/09	< 26.0	No	No	