

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-3/8/06	06BR0349-01	Southwest Area (sidewalk bridge level)	3/8/06	0.56	Mercury	EPA 324/1631	BRL	3/10/06	< 27.0	No	No	
TotalHg-ST2-3/8/06	06BR0349-02	Southeast Area (sidewalk bridge level)	3/8/06	0.56	Mercury	EPA 324/1631	BRL	3/10/06	< 27.0	No	No	
TotalHg-ST4-3/8/06	06BR0349-03	Northwest Area (street-level)	3/8/06	0.57	Mercury	EPA 324/1631	BRL	3/10/06	< 26.0	No	No	
TotalHg-ST5-3/8/06	06BR0349-04	Firehouse #10 (roof level)	3/8/06	0.57	Mercury	EPA 324/1631	BRL	3/10/06	< 26.0	No	No	
TotalHg-ST10-3/8/06	06BR0349-05	North Side Sidewalk Bridge	3/8/06	0.55	Mercury	EPA 324/1631	BRL	3/10/06	< 27.0	No	No	
TotalHg-ST11-3/8/06	06BR0349-06	90 Trinity Place (roof level)	3/8/06	0.57	Mercury	EPA 324/1631	BRL	3/10/06	< 26.0	No	No	
TotalHg-ST12-3/8/06	06BR0349-07	110 Greenwich Street (roof level)	3/8/06	0.57	Mercury	EPA 324/1631	BRL	3/10/06	< 26.0	No	No	
TotalHg-ST13-3/8/06	06BR0349-08	Marriott Hotel, 38th Floor (roof level)	3/8/06	0.56	Mercury	EPA 324/1631	BRL	3/10/06	< 27.0	No	No	
TotalHg-ST14-3/8/06	06BR0349-09	West Face - South end at corner (scaffolding level)	3/8/06	0.58	Mercury	EPA 324/1631	BRL	3/10/06	< 26.0	No	No	
TotalHg-ST15-3/8/06	06BR0349-10	South Face - East end at corner (scaffolding level)	3/8/06	0.57	Mercury	EPA 324/1631	BRL	3/10/06	< 26.0	No	No	
TotalHg-ST16-3/8/06	06BR0349-11	East Face - North end at corner (scaffolding level)	3/8/06	0.57	Mercury	EPA 324/1631	BRL	3/10/06	< 26.0	No	No	
TotalHg-ST17-3/8/06	06BR0349-12	North Face - West end at corner (scaffolding level)	3/8/06	0.58	Mercury	EPA 324/1631	BRL	3/10/06	< 26.0	No	No	
TotalHg-ST1-3/9/06	06BR0354-01	Southwest Area (sidewalk bridge level)	3/9/06	0.57	Mercury	EPA 324/1631	BRL	3/11/06	< 26.0	No	No	
TotalHg-ST2-3/9/06	06BR0354-02	Southeast Area (sidewalk bridge level)	3/9/06	0.57	Mercury	EPA 324/1631	BRL	3/11/06	< 26.0	No	No	
TotalHg-ST4-3/9/06	06BR0354-03	Northwest Area (street-level)	3/9/06	0.57	Mercury	EPA 324/1631	BRL	3/11/06	< 26.0	No	No	
TotalHg-ST5-3/9/06	06BR0354-04	Firehouse #10 (roof level)	3/9/06	0.57	Mercury	EPA 324/1631	BRL	3/11/06	< 26.0	No	No	
TotalHg-ST10-3/9/06	06BR0354-05	North Side Sidewalk Bridge	3/9/06	0.57	Mercury	EPA 324/1631	BRL	3/11/06	< 26.0	No	No	
TotalHg-ST100-3/9/06FD	06BR0354-13	Station 10 Field Duplicate	3/9/06	0.57	Mercury	EPA 324/1631	BRL	3/11/06	< 26.0	No	No	
TotalHg-ST11-3/9/06	06BR0354-06	90 Trinity Place (roof level)	3/9/06	0.57	Mercury	EPA 324/1631	BRL	3/11/06	< 26.0	No	No	
TotalHg-ST12-3/9/06	06BR0354-07	110 Greenwich Street (roof level)	3/9/06	0.58	Mercury	EPA 324/1631	BRL	3/11/06	< 26.0	No	No	
TotalHg-ST13-3/9/06	06BR0354-08	Marriott Hotel, 38th Floor (roof level)	3/9/06	0.57	Mercury	EPA 324/1631	BRL	3/11/06	< 26.0	No	No	
TotalHg-ST14-3/9/06	06BR0354-09	West Face - South end at corner (scaffolding level)	3/9/06	0.57	Mercury	EPA 324/1631	BRL	3/11/06	< 26.0	No	No	
TotalHg-ST15-3/9/06	06BR0354-10	South Face - East end at corner (scaffolding level)	3/9/06	0.57	Mercury	EPA 324/1631	BRL	3/11/06	< 26.0	No	No	
TotalHg-ST16-3/9/06	06BR0354-11	East Face - North end at corner (scaffolding level)	3/9/06	0.57	Mercury	EPA 324/1631	BRL	3/11/06	< 26.0	No	No	
TotalHg-ST17-3/9/06	06BR0354-12	North Face - West end at corner (scaffolding level)	3/9/06	0.57	Mercury	EPA 324/1631	BRL	3/11/06	< 26.0	No	No	