

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-3/15/08	0812005-01	Southwest Area (sidewalk bridge level)	3/15/08	0.55	Mercury	EPA 324/1631	BRL	3/18/08	< 27.0	No	No	
TotalHg-ST2-3/15/08	0812005-02	Southeast Area (sidewalk bridge level)	3/15/08	0.57	Mercury	EPA 324/1631	BRL	3/18/08	< 26.0	No	No	
TotalHg-ST4-3/15/08	0812005-03	Northwest Area (street-level)	3/15/08	0.55	Mercury	EPA 324/1631	BRL	3/18/08	< 27.0	No	No	
TotalHg-ST5-3/15/08	0812005-04	Firehouse #10 (roof level)	3/15/08	0.56	Mercury	EPA 324/1631	BRL	3/18/08	< 27.0	No	No	
TotalHg-ST10-3/15/08	0812005-05	North Side Sidewalk Bridge	3/15/08	0.60	Mercury	EPA 324/1631	BRL	3/18/08	< 25.0	No	No	
TotalHg-ST11-3/15/08	0812005-06	90 Trinity Place (roof level)	3/15/08	0.59	Mercury	EPA 324/1631	BRL	3/18/08	< 25.0	No	No	
TotalHg-ST12-3/15/08	0812005-07	110 Greenwich Street (roof level)	3/15/08	0.60	Mercury	EPA 324/1631	BRL	3/18/08	< 25.0	No	No	
TotalHg-ST13-3/15/08	0812005-08	Marriott Hotel, 38th Floor (roof level)	3/15/08	0.55	Mercury	EPA 324/1631	BRL	3/18/08	< 27.0	No	No	
TotalHg-ST14-3/15/08	0812005-09	West Face - South end at corner (scaffolding level)	3/15/08	0.60	Mercury	EPA 324/1631	BRL	3/18/08	< 25.0	No	No	
TotalHg-ST15-3/15/08	0812005-10	South Face - East end at corner (scaffolding level)	3/15/08	0.55	Mercury	EPA 324/1631	BRL	3/18/08	< 27.0	No	No	
TotalHg-ST16-3/15/08	0812005-11	East Face - North end at corner (scaffolding level)	3/15/08	0.63	Mercury	EPA 324/1631	BRL	3/18/08	< 24.0	No	No	
TotalHg-ST17-3/15/08	0812005-12	North Face - West end at corner (scaffolding level)	3/15/08	0.58	Mercury	EPA 324/1631	BRL	3/18/08	< 26.0	No	No	
TotalHg-ST1-3/16/08	0812007-01	Southwest Area (sidewalk bridge level)	3/16/08	0.56	Mercury	EPA 324/1631	BRL	3/18/08	< 27.0	No	No	
TotalHg-ST2-3/16/08	0812007-02	Southeast Area (sidewalk bridge level)	3/16/08	0.55	Mercury	EPA 324/1631	BRL	3/18/08	< 27.0	No	No	
TotalHg-ST4-3/16/08	0812007-03	Northwest Area (street-level)	3/16/08	0.55	Mercury	EPA 324/1631	BRL	3/18/08	< 27.0	No	No	
TotalHg-ST5-3/16/08	0812007-04	Firehouse #10 (roof level)	3/16/08	0.60	Mercury	EPA 324/1631	BRL	3/18/08	< 25.0	No	No	
TotalHg-ST10-3/16/08	0812007-05	North Side Sidewalk Bridge	3/16/08	0.56	Mercury	EPA 324/1631	BRL	3/18/08	< 27.0	No	No	
TotalHg-ST11-3/16/08	0812007-06	90 Trinity Place (roof level)	3/16/08	0.57	Mercury	EPA 324/1631	BRL	3/18/08	< 26.0	No	No	
TotalHg-ST12-3/16/08	0812007-07	110 Greenwich Street (roof level)	3/16/08	0.55	Mercury	EPA 324/1631	BRL	3/18/08	< 27.0	No	No	
TotalHg-ST13-3/16/08	0812007-08	Marriott Hotel, 38th Floor (roof level)	3/16/08	0.57	Mercury	EPA 324/1631	BRL	3/18/08	< 26.0	No	No	
TotalHg-ST14-3/16/08	0812007-09	West Face - South end at corner (scaffolding level)	3/16/08	0.62	Mercury	EPA 324/1631	BRL	3/18/08	< 24.0	No	No	
TotalHg-ST15-3/16/08	0812007-10	South Face - East end at corner (scaffolding level)	3/16/08	0.62	Mercury	EPA 324/1631	BRL	3/18/08	< 24.0	No	No	
TotalHg-ST16-3/16/08	0812007-11	East Face - North end at corner (scaffolding level)	3/16/08	0.58	Mercury	EPA 324/1631	BRL	3/18/08	< 26.0	No	No	
TotalHg-ST17-3/16/08	0812007-12	North Face - West end at corner (scaffolding level)	3/16/08	0.59	Mercury	EPA 324/1631	BRL	3/18/08	< 25.0	No	No	