

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-3/24/06	06BR0459-01	Southwest Area (sidewalk bridge level)	3/24/06	0.58	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST2-3/24/06	06BR0459-02	Southeast Area (sidewalk bridge level)	3/24/06	0.58	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST4-3/24/06	06BR0459-03	Northwest Area (street-level)	3/24/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST5-3/24/06	06BR0459-04	Firehouse #10 (roof level)	3/24/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST10-3/24/06	06BR0459-05	North Side Sidewalk Bridge	3/24/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST11-3/24/06	06BR0459-06	90 Trinity Place (roof level)	3/24/06	0.58	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST12-3/24/06	06BR0459-07	110 Greenwich Street (roof level)	3/24/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST13-3/24/06	06BR0459-08	Marriott Hotel, 38th Floor (roof level)	3/24/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST14-3/24/06	06BR0459-09	West Face - South end at corner (scaffolding level)	3/24/06	0.52	Mercury	EPA 324/1631	BRL	3/29/06	< 29.0	No	No	
TotalHg-ST15-3/24/06	06BR0459-10	South Face - East end at corner (scaffolding level)	3/24/06	0.52	Mercury	EPA 324/1631	BRL	3/29/06	< 29.0	No	No	
TotalHg-ST16-3/24/06	06BR0459-11	East Face - North end at corner (scaffolding level)	3/24/06	0.52	Mercury	EPA 324/1631	BRL	3/29/06	< 29.0	No	No	
TotalHg-ST17-3/24/06	06BR0459-12	North Face - West end at corner (scaffolding level)	3/24/06	0.52	Mercury	EPA 324/1631	BRL	3/29/06	< 29.0	No	No	
TotalHg-ST1-3/25/06	06BR0460-01	Southwest Area (sidewalk bridge level)	3/25/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST2-3/25/06	06BR0460-02	Southeast Area (sidewalk bridge level)	3/25/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST4-3/25/06	06BR0460-03	Northwest Area (street-level)	3/25/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST5-3/25/06	06BR0460-04	Firehouse #10 (roof level)	3/25/06	0.58	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST10-3/25/06	06BR0460-05	North Side Sidewalk Bridge	3/25/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST11-3/25/06	06BR0460-06	90 Trinity Place (roof level)	3/25/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST12-3/25/06	06BR0460-07	110 Greenwich Street (roof level)	3/25/06	0.58	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST13-3/25/06	06BR0460-08	Marriott Hotel, 38th Floor (roof level)	3/25/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST14-3/25/06	06BR0460-09	West Face - South end at corner (scaffolding level)	3/25/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST15-3/25/06	06BR0460-10	South Face - East end at corner (scaffolding level)	3/25/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST16-3/25/06	06BR0460-11	East Face - North end at corner (scaffolding level)	3/25/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST17-3/25/06	06BR0460-12	North Face - West end at corner (scaffolding level)	3/25/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST1-3/26/06	06BR0461-01	Southwest Area (sidewalk bridge level)	3/26/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST2-3/26/06	06BR0461-02	Southeast Area (sidewalk bridge level)	3/26/06	0.58	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST4-3/26/06	06BR0461-03	Northwest Area (street-level)	3/26/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST5-3/26/06	06BR0461-04	Firehouse #10 (roof level)	3/26/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST10-3/26/06	06BR0461-05	North Side Sidewalk Bridge	3/26/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST11-3/26/06	06BR0461-06	90 Trinity Place (roof level)	3/26/06	0.56	Mercury	EPA 324/1631	BRL	3/29/06	< 27.0	No	No	
TotalHg-ST12-3/26/06	06BR0461-07	110 Greenwich Street (roof level)	3/26/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST13-3/26/06	06BR0461-08	Marriott Hotel, 38th Floor (roof level)	3/26/06	0.53	Mercury	EPA 324/1631	BRL	3/29/06	< 28.0	No	No	
TotalHg-ST14-3/26/06	06BR0461-09	West Face - South end at corner (scaffolding level)	3/26/06	0.62	Mercury	EPA 324/1631	BRL	3/29/06	< 24.0	No	No	
TotalHg-ST15-3/26/06	06BR0461-10	South Face - East end at corner (scaffolding level)	3/26/06	0.63	Mercury	EPA 324/1631	BRL	3/29/06	< 24.0	No	No	
TotalHg-ST16-3/26/06	06BR0461-11	East Face - North end at corner (scaffolding level)	3/26/06	0.63	Mercury	EPA 324/1631	BRL	3/29/06	< 24.0	No	No	
TotalHg-ST17-3/26/06	06BR0461-12	North Face - West end at corner (scaffolding level)	3/26/06	0.62	Mercury	EPA 324/1631	BRL	3/29/06	< 24.0	No	No	
TotalHg-ST1-3/27/06	06BR0462-01	Southwest Area (sidewalk bridge level)	3/27/06	0.55	Mercury	EPA 324/1631	BRL	3/29/06	< 27.0	No	No	
TotalHg-ST2-3/27/06	06BR0462-02	Southeast Area (sidewalk bridge level)	3/27/06	0.55	Mercury	EPA 324/1631	BRL	3/29/06	< 27.0	No	No	
TotalHg-ST4-3/27/06	06BR0462-03	Northwest Area (street-level)	3/27/06	0.58	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST5-3/27/06	06BR0462-04	Firehouse #10 (roof level)	3/27/06	0.49	Mercury	EPA 324/1631	BRL	3/29/06	< 31.0	No	No	Note 1
TotalHg-ST10-3/27/06	06BR0462-05	North Side Sidewalk Bridge	3/27/06	0.55	Mercury	EPA 324/1631	BRL	3/29/06	< 27.0	No	No	Note 1
TotalHg-ST100-3/27/06FD	06BR0462-13	Station 10 Field Duplicate	3/27/06	0.53	Mercury	EPA 324/1631	BRL	3/29/06	< 28.0	No	No	Note 1
TotalHg-ST11-3/27/06	06BR0462-06	90 Trinity Place (roof level)	3/27/06	0.57	Mercury	EPA 324/1631	BRL	3/29/06	< 26.0	No	No	
TotalHg-ST12-3/27/06	06BR0462-07	110 Greenwich Street (roof level)	3/27/06	0.56	Mercury	EPA 324/1631	BRL	3/29/06	< 27.0	No	No	
TotalHg-ST13-3/27/06	06BR0462-08	Marriott Hotel, 38th Floor (roof level)	3/27/06	0.61	Mercury	EPA 324/1631	BRL	3/29/06	< 25.0	No	No	
TotalHg-ST14-3/27/06	06BR0462-09	West Face - South end at corner (scaffolding level)	3/27/06	0.59	Mercury	EPA 324/1631	BRL	3/29/06	< 25.0	No	No	
TotalHg-ST15-3/27/06	06BR0462-10	South Face - East end at corner (scaffolding level)	3/27/06	0.60	Mercury	EPA 324/1631	BRL	3/29/06	< 25.0	No	No	
TotalHg-ST16-3/27/06	06BR0462-11	East Face - North end at corner (scaffolding level)	3/27/06	0.60	Mercury	EPA 324/1631	BRL	3/29/06	< 25.0	No	No	
TotalHg-ST17-3/27/06	06BR0462-12	North Face - West end at corner (scaffolding level)	3/27/06	0.60	Mercury	EPA 324/1631	BRL	3/29/06	< 25.0	No	No	
TotalHg-ST1-3/28/06	06BR0472-01	Southwest Area (sidewalk bridge level)	3/28/06	0.58	Mercury	EPA 324/1631	BRL	3/30/06	< 26.0	No	No	
TotalHg-ST2-3/28/06	06BR0472-02	Southeast Area (sidewalk bridge level)	3/28/06	0.57	Mercury	EPA 324/1631	BRL	3/30/06	< 26.0	No	No	
TotalHg-ST4-3/28/06	06BR0472-03	Northwest Area (street-level)	3/28/06	0.57	Mercury	EPA 324/1631	BRL	3/30/06	< 26.0	No	No	
TotalHg-ST5-3/28/06	06BR0472-04	Firehouse #10 (roof level)	3/28/06	0.57	Mercury	EPA 324/1631	BRL	3/30/06	< 26.0	No	No	
TotalHg-ST10-3/28/06	06BR0472-05	North Side Sidewalk Bridge	3/28/06	0.54	Mercury	EPA 324/1631	BRL	3/30/06	< 26.0	No	No	
TotalHg-ST11-3/28/06	06BR0472-06	90 Trinity Place (roof level)	3/28/06	0.57	Mercury	EPA 324/1631	BRL	3/30/06	< 26.0	No	No	
TotalHg-ST12-3/28/06	06BR0472-07	110 Greenwich Street (roof level)	3/28/06	0.57	Mercury	EPA 324/1631	BRL	3/30/06	< 26.0	No	No	
TotalHg-ST13-3/28/06	06BR0472-08	Marriott Hotel, 38th Floor (roof level)	3/28/06	0.58	Mercury	EPA 324/1631	BRL	3/30/06	< 26.0	No	No	
TotalHg-ST14-3/28/06	06BR0472-09	West Face - South end at corner (scaffolding level)	3/28/06	0.57	Mercury	EPA 324/1631	BRL	3/30/06	< 26.0	No	No	
TotalHg-ST15-3/28/06	06BR0472-10	South Face - East end at corner (scaffolding level)	3/28/06	0.56	Mercury	EPA 324/1631	BRL	3/30/06	< 27.0	No	No	
TotalHg-ST16-3/28/06	06BR0472-11	East Face - North end at corner (scaffolding level)	3/28/06	0.56	Mercury	EPA 324/1631	BRL	3/30/06	< 27.0	No	No	
TotalHg-ST17-3/28/06	06BR0472-12	North Face - West end at corner (scaffolding level)	3/28/06	0.56	Mercury	EPA 324/1631	BRL	3/30/06	< 27.0	No	No	

Note:

1. Samples collected at Station 5 (Firehouse #10 [roof level]), Station 10 (North Side [sidewalk bridge]) and Station 100 (Station 10 Field Duplicate) on March 27, 2006 do not reflect a continuous sampling period due to a temporary power outage from 11:40 AM to 3:10 PM.