

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									300			
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-3/30/09	0914008-01	Southwest Area (sidewalk bridge level)	3/30/09	0.62	Mercury	EPA 324/1631	BRL	4/1/09	< 24.0	No	No	
TotalHg-ST2-3/30/09	0914008-02	Southeast Area (sidewalk bridge level)	3/30/09	0.57	Mercury	EPA 324/1631	BRL	4/1/09	< 26.0	No	No	
TotalHg-ST4-3/30/09	0914008-03	Northwest Area (street-level)	3/30/09	0.58	Mercury	EPA 324/1631	BRL	4/1/09	< 26.0	No	No	
TotalHg-ST5-3/30/09	0914008-04	Firehouse #10 (roof level)	3/30/09	0.55	Mercury	EPA 324/1631	BRL	4/1/09	< 27.0	No	No	
TotalHg-ST10-3/30/09	0914008-05	North Side Sidewalk Bridge	3/30/09	0.61	Mercury	EPA 324/1631	BRL	4/1/09	< 25.0	No	No	
TotalHg-ST11-3/30/09	0914008-06	90 Trinity Place (roof level)	3/30/09	0.56	Mercury	EPA 324/1631	BRL	4/1/09	< 27.0	No	No	
TotalHg-ST12-3/30/09	0914008-07	110 Greenwich Street (roof level)	3/30/09	0.56	Mercury	EPA 324/1631	BRL	4/1/09	< 27.0	No	No	
TotalHg-ST13-3/30/09	0914008-08	Marriott Hotel, 38th Floor (roof level)	3/30/09	0.56	Mercury	EPA 324/1631	BRL	4/1/09	< 27.0	No	No	
TotalHg-ST14-3/30/09	0914008-09	West Face - South end at corner (scaffolding level)	3/30/09	0.56	Mercury	EPA 324/1631	BRL	4/1/09	< 27.0	No	No	
TotalHg-ST15-3/30/09	0914008-10	South Face - East end at corner (scaffolding level)	3/30/09	0.58	Mercury	EPA 324/1631	BRL	4/1/09	< 26.0	No	No	
TotalHg-ST16-3/30/09	0914008-11	East Face - North end at corner (scaffolding level)	3/30/09	0.57	Mercury	EPA 324/1631	BRL	4/1/09	< 26.0	No	No	
TotalHg-ST17-3/30/09	0914008-12	North Face - West end at corner (scaffolding level)	3/30/09	0.56	Mercury	EPA 324/1631	BRL	4/1/09	< 27.0	No	No	
TotalHg-ST1-3/31/09	0914013-01	Southwest Area (sidewalk bridge level)	3/31/09	0.61	Mercury	EPA 324/1631	BRL	4/2/09	< 25.0	No	No	
TotalHg-ST2-3/31/09	0914013-02	Southeast Area (sidewalk bridge level)	3/31/09	0.54	Mercury	EPA 324/1631	BRL	4/2/09	< 28.0	No	No	
TotalHg-ST4-3/31/09	0914013-03	Northwest Area (street-level)	3/31/09	0.54	Mercury	EPA 324/1631	BRL	4/2/09	< 28.0	No	No	
TotalHg-ST5-3/31/09	0914013-04	Firehouse #10 (roof level)	3/31/09	0.61	Mercury	EPA 324/1631	BRL	4/2/09	< 25.0	No	No	
TotalHg-ST10-3/31/09	0914013-05	North Side Sidewalk Bridge	3/31/09	0.55	Mercury	EPA 324/1631	BRL	4/2/09	< 27.0	No	No	
TotalHg-ST100-3/31/09 FD	0914013-13	Station 10 Field Duplicate	3/31/09	0.57	Mercury	EPA 324/1631	BRL	4/2/09	< 26.0	No	No	
TotalHg-ST11-3/31/09	0914013-06	90 Trinity Place (roof level)	3/31/09	0.54	Mercury	EPA 324/1631	BRL	4/2/09	< 28.0	No	No	
TotalHg-ST12-3/31/09	0914013-07	110 Greenwich Street (roof level)	3/31/09	0.56	Mercury	EPA 324/1631	BRL	4/2/09	< 27.0	No	No	
TotalHg-ST13-3/31/09	0914013-08	Marriott Hotel, 38th Floor (roof level)	3/31/09	0.63	Mercury	EPA 324/1631	BRL	4/2/09	< 24.0	No	No	
TotalHg-ST14-3/31/09	0914013-09	West Face - South end at corner (scaffolding level)	3/31/09	0.57	Mercury	EPA 324/1631	BRL	4/2/09	< 26.0	No	No	
TotalHg-ST15-3/31/09	0914013-10	South Face - East end at corner (scaffolding level)	3/31/09	0.55	Mercury	EPA 324/1631	BRL	4/2/09	< 27.0	No	No	
TotalHg-ST16-3/31/09	0914013-11	East Face - North end at corner (scaffolding level)	3/31/09	0.57	Mercury	EPA 324/1631	BRL	4/2/09	< 26.0	No	No	
TotalHg-ST17-3/31/09	0914013-12	North Face - West end at corner (scaffolding level)	3/31/09	0.54	Mercury	EPA 324/1631	BRL	4/2/09	< 28.0	No	No	
TotalHg-ST2-4/1/09	0914020-01	Southeast Area (sidewalk bridge level)	4/1/09	0.56	Mercury	EPA 324/1631	BRL	4/3/09	< 27.0	No	No	
TotalHg-ST4-4/1/09	0914020-02	Northwest Area (street-level)	4/1/09	0.57	Mercury	EPA 324/1631	BRL	4/3/09	< 26.0	No	No	
TotalHg-ST5-4/1/09	0914020-03	Firehouse #10 (roof level)	4/1/09	0.61	Mercury	EPA 324/1631	BRL	4/3/09	< 25.0	No	No	
TotalHg-ST10-4/1/09	0914020-04	North Side Sidewalk Bridge	4/1/09	0.54	Mercury	EPA 324/1631	BRL	4/3/09	< 28.0	No	No	
TotalHg-ST11-4/1/09	0914020-05	90 Trinity Place (roof level)	4/1/09	0.54	Mercury	EPA 324/1631	BRL	4/3/09	< 28.0	No	No	
TotalHg-ST12-4/1/09	0914020-06	110 Greenwich Street (roof level)	4/1/09	0.59	Mercury	EPA 324/1631	BRL	4/3/09	< 25.0	No	No	
TotalHg-ST13-4/1/09	0914020-07	Marriott Hotel, 38th Floor (roof level)	4/1/09	0.56	Mercury	EPA 324/1631	BRL	4/3/09	< 27.0	No	No	
TotalHg-ST14-4/1/09	0914020-08	West Face - South end at corner (scaffolding level)	4/1/09	0.55	Mercury	EPA 324/1631	BRL	4/3/09	< 27.0	No	No	
TotalHg-ST15-4/1/09	0914020-09	South Face - East end at corner (scaffolding level)	4/1/09	0.61	Mercury	EPA 324/1631	BRL	4/3/09	< 25.0	No	No	
TotalHg-ST16-4/1/09	0914020-10	East Face - North end at corner (scaffolding level)	4/1/09	0.54	Mercury	EPA 324/1631	BRL	4/3/09	< 28.0	No	No	
TotalHg-ST17-4/1/09	0914020-11	North Face - West end at corner (scaffolding level)	4/1/09	0.58	Mercury	EPA 324/1631	BRL	4/3/09	< 26.0	No	No	

Note:

1. The mercury sample from Station 1 (Southwest Area [sidewalk bridge level]) on April 1, 2009 was not collected until April 3, 2009 on account of accessibility issues to that location; the data will be posted when it becomes available.