

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-4/5/08	0815006-01	Southwest Area (sidewalk bridge level)	4/5/08	0.55	Mercury	EPA 324/1631	BRL	4/8/08	< 27.0	No	No	
TotalHg-ST2-4/5/08	0815006-02	Southeast Area (sidewalk bridge level)	4/5/08	0.61	Mercury	EPA 324/1631	BRL	4/8/08	< 25.0	No	No	
TotalHg-ST4-4/5/08	0815006-03	Northwest Area (street-level)	4/5/08	0.55	Mercury	EPA 324/1631	BRL	4/8/08	< 27.0	No	No	
TotalHg-ST5-4/5/08	0815006-04	Firehouse #10 (roof level)	4/5/08	0.52	Mercury	EPA 324/1631	BRL	4/8/08	< 29.0	No	No	
TotalHg-ST10-4/5/08	0815006-05	North Side Sidewalk Bridge	4/5/08	0.57	Mercury	EPA 324/1631	BRL	4/8/08	< 26.0	No	No	
TotalHg-ST11-4/5/08	0815006-06	90 Trinity Place (roof level)	4/5/08	0.54	Mercury	EPA 324/1631	BRL	4/8/08	< 28.0	No	No	
TotalHg-ST12-4/5/08	0815006-07	110 Greenwich Street (roof level)	4/5/08	0.54	Mercury	EPA 324/1631	BRL	4/8/08	< 28.0	No	No	
TotalHg-ST13-4/5/08	0815006-08	Marriott Hotel, 38th Floor (roof level)	4/5/08	0.54	Mercury	EPA 324/1631	BRL	4/8/08	< 28.0	No	No	
TotalHg-ST14-4/5/08	0815006-09	West Face - South end at corner (scaffolding level)	4/5/08	0.53	Mercury	EPA 324/1631	BRL	4/8/08	< 28.0	No	No	
TotalHg-ST15-4/5/08	0815006-10	South Face - East end at corner (scaffolding level)	4/5/08	0.52	Mercury	EPA 324/1631	BRL	4/8/08	< 29.0	No	No	
TotalHg-ST16-4/5/08	0815006-11	East Face - North end at corner (scaffolding level)	4/5/08	0.54	Mercury	EPA 324/1631	BRL	4/8/08	< 28.0	No	No	
TotalHg-ST17-4/5/08	0815006-12	North Face - West end at corner (scaffolding level)	4/5/08	0.57	Mercury	EPA 324/1631	BRL	4/8/08	< 26.0	No	No	
TotalHg-ST1-4/6/08	0815007-01	Southwest Area (sidewalk bridge level)	4/6/08	0.58	Mercury	EPA 324/1631	BRL	4/8/08	< 26.0	No	No	
TotalHg-ST2-4/6/08	0815007-02	Southeast Area (sidewalk bridge level)	4/6/08	0.57	Mercury	EPA 324/1631	BRL	4/8/08	< 26.0	No	No	
TotalHg-ST4-4/6/08	0815007-03	Northwest Area (street-level)	4/6/08	0.57	Mercury	EPA 324/1631	BRL	4/8/08	< 26.0	No	No	
TotalHg-ST5-4/6/08	0815007-04	Firehouse #10 (roof level)	4/6/08	0.59	Mercury	EPA 324/1631	BRL	4/8/08	< 25.0	No	No	
TotalHg-ST10-4/6/08	0815007-05	North Side Sidewalk Bridge	4/6/08	0.54	Mercury	EPA 324/1631	BRL	4/8/08	< 28.0	No	No	
TotalHg-ST11-4/6/08	0815007-06	90 Trinity Place (roof level)	4/6/08	0.57	Mercury	EPA 324/1631	BRL	4/8/08	< 26.0	No	No	
TotalHg-ST12-4/6/08	0815007-07	110 Greenwich Street (roof level)	4/6/08	0.59	Mercury	EPA 324/1631	BRL	4/8/08	< 25.0	No	No	
TotalHg-ST13-4/6/08	0815007-08	Marriott Hotel, 38th Floor (roof level)	4/6/08	0.56	Mercury	EPA 324/1631	BRL	4/8/08	< 27.0	No	No	
TotalHg-ST14-4/6/08	0815007-09	West Face - South end at corner (scaffolding level)	4/6/08	0.63	Mercury	EPA 324/1631	BRL	4/8/08	< 24.0	No	No	
TotalHg-ST15-4/6/08	0815007-10	South Face - East end at corner (scaffolding level)	4/6/08	0.58	Mercury	EPA 324/1631	BRL	4/8/08	< 26.0	No	No	
TotalHg-ST16-4/6/08	0815007-11	East Face - North end at corner (scaffolding level)	4/6/08	0.64	Mercury	EPA 324/1631	BRL	4/8/08	< 23.0	No	No	
TotalHg-ST17-4/6/08	0815007-12	North Face - West end at corner (scaffolding level)	4/6/08	0.61	Mercury	EPA 324/1631	BRL	4/8/08	< 25.0	No	No	