

| TRC Field Sample No. | Sample No.  | Sampling Location                                   | Collection Start Date | Sample Volume (m <sup>3</sup> ) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Mercury (Total) Concentration (ng/m3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|----------------------|-------------|---|-----------------------|---------------------------------|---------|-------------------|-----|-------------------------|---------------------------------------|-----------------------------------|--|----------|
|                      |             |   |                       |                                 |         |                   |     |                         | 300                                   |                                   |  |          |
|                      |             |   |                       |                                 |         |                   |     |                         | 3,000                                 |                                   |  |          |
| TotalHg-ST1-4/06/07  | 07BR0458-01 | Southwest Area (sidewalk bridge level)              | 4/6/07                | 0.57                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST2-4/06/07  | 07BR0458-02 | Southeast Area (sidewalk bridge level)              | 4/6/07                | 0.54                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 28.0                                | No                                | No                                       |          |
| TotalHg-ST4-4/06/07  | 07BR0458-03 | Northwest Area (street-level)                       | 4/6/07                | 0.56                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST5-4/06/07  | 07BR0458-04 | Firehouse #10 (roof level)                          | 4/6/07                | 0.58                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST10-4/06/07 | 07BR0458-05 | North Side Sidewalk Bridge                          | 4/6/07                | 0.56                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST11-4/06/07 | 07BR0458-06 | 90 Trinity Place (roof level)                       | 4/6/07                | 0.59                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST12-4/06/07 | 07BR0458-07 | 110 Greenwich Street (roof level)                   | 4/6/07                | 0.59                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST13-4/06/07 | 07BR0458-08 | Marriott Hotel, 38th Floor (roof level)             | 4/6/07                | 0.58                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST14-4/06/07 | 07BR0458-09 | West Face - South end at corner (scaffolding level) | 4/6/07                | 0.56                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST15-4/06/07 | 07BR0458-10 | South Face - East end at corner (scaffolding level) | 4/6/07                | 0.53                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 28.0                                | No                                | No                                       |          |
| TotalHg-ST16-4/06/07 | 07BR0458-11 | East Face - North end at corner (scaffolding level) | 4/6/07                | 0.55                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST17-4/06/07 | 07BR0458-12 | North Face - West end at corner (scaffolding level) | 4/6/07                | 0.56                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST1-4/07/07  | 07BR0459-01 | Southwest Area (sidewalk bridge level)              | 4/7/07                | 0.54                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 28.0                                | No                                | No                                       |          |
| TotalHg-ST2-4/07/07  | 07BR0459-02 | Southeast Area (sidewalk bridge level)              | 4/7/07                | 0.59                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST4-4/07/07  | 07BR0459-03 | Northwest Area (street-level)                       | 4/7/07                | 0.55                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST5-4/07/07  | 07BR0459-04 | Firehouse #10 (roof level)                          | 4/7/07                | 0.59                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST10-4/07/07 | 07BR0459-05 | North Side Sidewalk Bridge                          | 4/7/07                | 0.53                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 28.0                                | No                                | No                                       |          |
| TotalHg-ST11-4/07/07 | 07BR0459-06 | 90 Trinity Place (roof level)                       | 4/7/07                | 0.59                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST12-4/07/07 | 07BR0459-07 | 110 Greenwich Street (roof level)                   | 4/7/07                | 0.56                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST13-4/07/07 | 07BR0459-08 | Marriott Hotel, 38th Floor (roof level)             | 4/7/07                | 0.57                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST14-4/07/07 | 07BR0459-09 | West Face - South end at corner (scaffolding level) | 4/7/07                | 0.58                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST15-4/07/07 | 07BR0459-10 | South Face - East end at corner (scaffolding level) | 4/7/07                | 0.58                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST16-4/07/07 | 07BR0459-11 | East Face - North end at corner (scaffolding level) | 4/7/07                | 0.58                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST17-4/07/07 | 07BR0459-12 | North Face - West end at corner (scaffolding level) | 4/7/07                | 0.58                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST1-4/8/07   | 07BR0460-01 | Southwest Area (sidewalk bridge level)              | 4/8/07                | 0.60                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST2-4/8/07   | 07BR0460-02 | Southeast Area (sidewalk bridge level)              | 4/8/07                | 0.55                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST4-4/8/07   | 07BR0460-03 | Northwest Area (street-level)                       | 4/8/07                | 0.60                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST5-4/8/07   | 07BR0460-04 | Firehouse #10 (roof level)                          | 4/8/07                | 0.52                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 29.0                                | No                                | No                                       |          |
| TotalHg-ST10-4/8/07  | 07BR0460-05 | North Side Sidewalk Bridge                          | 4/8/07                | 0.59                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST11-4/8/07  | 07BR0460-06 | 90 Trinity Place (roof level)                       | 4/8/07                | 0.58                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST12-4/8/07  | 07BR0460-07 | 110 Greenwich Street (roof level)                   | 4/8/07                | 0.57                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST13-4/8/07  | 07BR0460-08 | Marriott Hotel, 38th Floor (roof level)             | 4/8/07                | 0.53                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 28.0                                | No                                | No                                       |          |
| TotalHg-ST14-4/8/07  | 07BR0460-09 | West Face - South end at corner (scaffolding level) | 4/8/07                | 0.60                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST15-4/8/07  | 07BR0460-10 | South Face - East end at corner (scaffolding level) | 4/8/07                | 0.61                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST16-4/8/07  | 07BR0460-11 | East Face - North end at corner (scaffolding level) | 4/8/07                | 0.62                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 24.0                                | No                                | No                                       |          |
| TotalHg-ST17-4/8/07  | 07BR0460-12 | North Face - West end at corner (scaffolding level) | 4/8/07                | 0.60                            | Mercury | EPA 324/1631      | BRL | 4/10/07                 | < 25.0                                | No                                | No                                       |          |