

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m <sup>3</sup> )	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									<b>300</b>			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>									<b>3,000</b>			
TotalHg-ST1-4/8/09	0915032-01	Southwest Area (sidewalk bridge level)	4/8/09	0.56	Mercury	EPA 324/1631	BRL	4/11/09	< 27.0	No	No	
TotalHg-ST2-4/8/09	0915032-02	Southeast Area (sidewalk bridge level)	4/8/09	0.61	Mercury	EPA 324/1631	BRL	4/11/09	< 25.0	No	No	
TotalHg-ST4-4/8/09	0915032-03	Northwest Area (street-level)	4/8/09	0.59	Mercury	EPA 324/1631	BRL	4/11/09	< 25.0	No	No	
TotalHg-ST5-4/8/09	0915032-04	Firehouse #10 (roof level)	4/8/09	0.57	Mercury	EPA 324/1631	BRL	4/11/09	< 26.0	No	No	
TotalHg-ST10-4/8/09	0915032-05	North Side Sidewalk Bridge	4/8/09	0.59	Mercury	EPA 324/1631	BRL	4/11/09	< 25.0	No	No	
TotalHg-ST11-4/8/09	0915032-06	90 Trinity Place (roof level)	4/8/09	0.56	Mercury	EPA 324/1631	BRL	4/11/09	< 27.0	No	No	
TotalHg-ST12-4/8/09	0915032-07	110 Greenwich Street (roof level)	4/8/09	0.59	Mercury	EPA 324/1631	BRL	4/11/09	< 25.0	No	No	
TotalHg-ST13-4/8/09	0915032-08	Marriott Hotel, 38th Floor (roof level)	4/8/09	0.56	Mercury	EPA 324/1631	BRL	4/11/09	< 27.0	No	No	
TotalHg-ST14-4/8/09	0915032-09	West Face - South end at corner (scaffolding level)	4/8/09	0.57	Mercury	EPA 324/1631	BRL	4/11/09	< 26.0	No	No	
TotalHg-ST15-4/8/09	0915032-10	South Face - East end at corner (scaffolding level)	4/8/09	0.57	Mercury	EPA 324/1631	BRL	4/11/09	< 26.0	No	No	
TotalHg-ST16-4/8/09	0915032-11	East Face - North end at corner (scaffolding level)	4/8/09	0.60	Mercury	EPA 324/1631	BRL	4/11/09	< 25.0	No	No	
TotalHg-ST17-4/8/09	0915032-12	North Face - West end at corner (scaffolding level)	4/8/09	0.54	Mercury	EPA 324/1631	BRL	4/11/09	< 28.0	No	No	
TotalHg-ST1-4/9/09	0915033-01	Southwest Area (sidewalk bridge level)	4/9/09	0.55	Mercury	EPA 324/1631	BRL	4/11/09	< 27.0	No	No	
TotalHg-ST2-4/9/09	0915033-02	Southeast Area (sidewalk bridge level)	4/9/09	0.60	Mercury	EPA 324/1631	BRL	4/11/09	< 25.0	No	No	
TotalHg-ST4-4/9/09	0915033-03	Northwest Area (street-level)	4/9/09	0.62	Mercury	EPA 324/1631	BRL	4/11/09	< 24.0	No	No	
TotalHg-ST5-4/9/09	0915033-04	Firehouse #10 (roof level)	4/9/09	0.56	Mercury	EPA 324/1631	BRL	4/11/09	< 27.0	No	No	
TotalHg-ST10-4/9/09	0915033-05	North Side Sidewalk Bridge	4/9/09	0.54	Mercury	EPA 324/1631	BRL	4/11/09	< 28.0	No	No	
TotalHg-ST11-4/9/09	0915033-06	90 Trinity Place (roof level)	4/9/09	0.54	Mercury	EPA 324/1631	BRL	4/11/09	< 28.0	No	No	
TotalHg-ST12-4/9/09	0915033-07	110 Greenwich Street (roof level)	4/9/09	0.57	Mercury	EPA 324/1631	BRL	4/11/09	< 26.0	No	No	
TotalHg-ST13-4/9/09	0915033-08	Marriott Hotel, 38th Floor (roof level)	4/9/09	0.57	Mercury	EPA 324/1631	BRL	4/11/09	< 26.0	No	No	
TotalHg-ST14-4/9/09	0915033-09	West Face - South end at corner (scaffolding level)	4/9/09	0.55	Mercury	EPA 324/1631	BRL	4/11/09	< 27.0	No	No	
TotalHg-ST15-4/9/09	0915033-10	South Face - East end at corner (scaffolding level)	4/9/09	0.54	Mercury	EPA 324/1631	BRL	4/11/09	< 28.0	No	No	
TotalHg-ST16-4/9/09	0915033-11	East Face - North end at corner (scaffolding level)	4/9/09	0.57	Mercury	EPA 324/1631	BRL	4/11/09	< 26.0	No	No	
TotalHg-ST17-4/9/09	0915033-12	North Face - West end at corner (scaffolding level)	4/9/09	0.54	Mercury	EPA 324/1631	BRL	4/11/09	< 28.0	No	No	
TotalHg-ST1-4/10/09	0916001-01	Southwest Area (sidewalk bridge level)	4/10/09	0.56	Mercury	EPA 324/1631	BRL	4/13/09	< 27.0	No	No	
TotalHg-ST2-4/10/09	0916001-02	Southeast Area (sidewalk bridge level)	4/10/09	0.53	Mercury	EPA 324/1631	BRL	4/13/09	< 28.0	No	No	
TotalHg-ST4-4/10/09	0916001-03	Northwest Area (street-level)	4/10/09	0.62	Mercury	EPA 324/1631	BRL	4/13/09	< 24.0	No	No	
TotalHg-ST5-4/10/09	0916001-04	Firehouse #10 (roof level)	4/10/09	0.59	Mercury	EPA 324/1631	BRL	4/13/09	< 25.0	No	No	
TotalHg-ST10-4/10/09	0916001-05	North Side Sidewalk Bridge	4/10/09	0.55	Mercury	EPA 324/1631	BRL	4/13/09	< 27.0	No	No	
TotalHg-ST11-4/10/09	0916001-06	90 Trinity Place (roof level)	4/10/09	0.55	Mercury	EPA 324/1631	BRL	4/13/09	< 27.0	No	No	
TotalHg-ST12-4/10/09	0916001-07	110 Greenwich Street (roof level)	4/10/09	0.55	Mercury	EPA 324/1631	BRL	4/13/09	< 27.0	No	No	
TotalHg-ST13-4/10/09	0916001-08	Marriott Hotel, 38th Floor (roof level)	4/10/09	0.55	Mercury	EPA 324/1631	BRL	4/13/09	< 27.0	No	No	
TotalHg-ST14-4/10/09	0916001-09	West Face - South end at corner (scaffolding level)	4/10/09	0.53	Mercury	EPA 324/1631	BRL	4/13/09	< 28.0	No	No	
TotalHg-ST15-4/10/09	0916001-10	South Face - East end at corner (scaffolding level)	4/10/09	0.54	Mercury	EPA 324/1631	BRL	4/13/09	< 28.0	No	No	
TotalHg-ST16-4/10/09	0916001-11	East Face - North end at corner (scaffolding level)	4/10/09	0.55	Mercury	EPA 324/1631	BRL	4/13/09	< 27.0	No	No	
TotalHg-ST17-4/10/09	0916001-12	North Face - West end at corner (scaffolding level)	4/10/09	0.55	Mercury	EPA 324/1631	BRL	4/13/09	< 27.0	No	No	