

| TRC Field Sample No. | Sample No.  | Sampling Location                                   | Collection Start Date | Sample Volume (m <sup>3</sup> ) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Mercury (Total) Concentration (ng/m3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|----------------------|-------------|---|-----------------------|---------------------------------|---------|-------------------|-----|-------------------------|---------------------------------------|-----------------------------------|--|----------|
|                      |             |   |                       |                                 |         |                   |     |                         | 300                                   |                                   |  |          |
|                      |             |   |                       |                                 |         |                   |     |                         | 3,000                                 |                                   |  |          |
| TotalHg-ST1-4/10/06  | 06BR0524-01 | Southwest Area (sidewalk bridge level)              | 4/10/06               | 0.57                            | Mercury | EPA 324/1631      | BRL | 4/12/06                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST2-4/10/06  | 06BR0524-02 | Southeast Area (sidewalk bridge level)              | 4/10/06               | 0.57                            | Mercury | EPA 324/1631      | BRL | 4/12/06                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST4-4/10/06  | 06BR0524-03 | Northwest Area (street-level)                       | 4/10/06               | 0.59                            | Mercury | EPA 324/1631      | BRL | 4/12/06                 | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST10-4/10/06 | 06BR0524-04 | North Side Sidewalk Bridge                          | 4/10/06               | 0.58                            | Mercury | EPA 324/1631      | BRL | 4/12/06                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST11-4/10/06 | 06BR0524-05 | 90 Trinity Place (roof level)                       | 4/10/06               | 0.57                            | Mercury | EPA 324/1631      | BRL | 4/12/06                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST12-4/10/06 | 06BR0524-06 | 110 Greenwich Street (roof level)                   | 4/10/06               | 0.58                            | Mercury | EPA 324/1631      | BRL | 4/12/06                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST13-4/10/06 | 06BR0524-07 | Marriott Hotel, 38th Floor (roof level)             | 4/10/06               | 0.60                            | Mercury | EPA 324/1631      | BRL | 4/12/06                 | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST14-4/10/06 | 06BR0524-08 | West Face - South end at corner (scaffolding level) | 4/10/06               | 0.58                            | Mercury | EPA 324/1631      | BRL | 4/12/06                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST15-4/10/06 | 06BR0524-09 | South Face - East end at corner (scaffolding level) | 4/10/06               | 0.58                            | Mercury | EPA 324/1631      | BRL | 4/12/06                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST16-4/10/06 | 06BR0524-10 | East Face - North end at corner (scaffolding level) | 4/10/06               | 0.58                            | Mercury | EPA 324/1631      | BRL | 4/12/06                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST17-4/10/06 | 06BR0524-11 | North Face - West end at corner (scaffolding level) | 4/10/06               | 0.58                            | Mercury | EPA 324/1631      | BRL | 4/12/06                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST1-4/11/06  | 06BR0534-01 | Southwest Area (sidewalk bridge level)              | 4/11/06               | 0.57                            | Mercury | EPA 324/1631      | BRL | 4/14/06                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST2-4/11/06  | 06BR0534-02 | Southeast Area (sidewalk bridge level)              | 4/11/06               | 0.57                            | Mercury | EPA 324/1631      | BRL | 4/14/06                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST4-4/11/06  | 06BR0534-03 | Northwest Area (street-level)                       | 4/11/06               | 0.56                            | Mercury | EPA 324/1631      | BRL | 4/14/06                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST5-4/11/06  | 06BR0534-04 | Firehouse #10 (roof level)                          | 4/11/06               | 0.57                            | Mercury | EPA 324/1631      | BRL | 4/14/06                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST10-4/11/06 | 06BR0534-05 | North Side Sidewalk Bridge                          | 4/11/06               | 0.56                            | Mercury | EPA 324/1631      | BRL | 4/14/06                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST11-4/11/06 | 06BR0534-06 | 90 Trinity Place (roof level)                       | 4/11/06               | 0.57                            | Mercury | EPA 324/1631      | BRL | 4/14/06                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST12-4/11/06 | 06BR0534-07 | 110 Greenwich Street (roof level)                   | 4/11/06               | 0.58                            | Mercury | EPA 324/1631      | BRL | 4/14/06                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST13-4/11/06 | 06BR0534-08 | Marriott Hotel, 38th Floor (roof level)             | 4/11/06               | 0.56                            | Mercury | EPA 324/1631      | BRL | 4/14/06                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST14-4/11/06 | 06BR0534-09 | West Face - South end at corner (scaffolding level) | 4/11/06               | 0.56                            | Mercury | EPA 324/1631      | BRL | 4/14/06                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST15-4/11/06 | 06BR0534-10 | South Face - East end at corner (scaffolding level) | 4/11/06               | 0.57                            | Mercury | EPA 324/1631      | BRL | 4/14/06                 | < 26.0                                | No                                | No                                       |          |
| TotalHg-ST16-4/11/06 | 06BR0534-11 | East Face - North end at corner (scaffolding level) | 4/11/06               | 0.56                            | Mercury | EPA 324/1631      | BRL | 4/14/06                 | < 27.0                                | No                                | No                                       |          |
| TotalHg-ST17-4/11/06 | 06BR0534-12 | North Face - West end at corner (scaffolding level) | 4/11/06               | 0.57                            | Mercury | EPA 324/1631      | BRL | 4/14/06                 | < 26.0                                | No                                | No                                       |          |

Note:

- Mercury sample at Station 5 (Firehouse #10 [roof level]) on April 10, 2006 was not available for analysis on account of pump failure.