

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>												
TotalHg-ST1-4/14/08	0816018-01	Southwest Area (sidewalk bridge level)	4/14/08	0.58	Mercury	EPA 324/1631	BRL	4/16/08	< 26.0	No	No	
TotalHg-ST2-4/14/08	0816018-02	Southeast Area (sidewalk bridge level)	4/14/08	0.56	Mercury	EPA 324/1631	BRL	4/16/08	< 27.0	No	No	
TotalHg-ST4-4/14/08	0816018-03	Northwest Area (street-level)	4/14/08	0.54	Mercury	EPA 324/1631	BRL	4/16/08	< 28.0	No	No	
TotalHg-ST5-4/14/08	0816018-04	Firehouse #10 (roof level)	4/14/08	0.59	Mercury	EPA 324/1631	BRL	4/16/08	< 25.0	No	No	
TotalHg-ST10-4/14/08	0816018-05	North Side Sidewalk Bridge	4/14/08	0.59	Mercury	EPA 324/1631	BRL	4/16/08	< 25.0	No	No	
TotalHg-ST11-4/14/08	0816018-06	90 Trinity Place (roof level)	4/14/08	0.56	Mercury	EPA 324/1631	BRL	4/16/08	< 27.0	No	No	
TotalHg-ST12-4/14/08	0816018-07	110 Greenwich Street (roof level)	4/14/08	0.60	Mercury	EPA 324/1631	BRL	4/16/08	< 25.0	No	No	
TotalHg-ST13-4/14/08	0816018-08	Marriott Hotel, 38th Floor (roof level)	4/14/08	0.57	Mercury	EPA 324/1631	BRL	4/16/08	< 26.0	No	No	
TotalHg-ST14-4/14/08	0816018-09	West Face - South end at corner (scaffolding level)	4/14/08	0.54	Mercury	EPA 324/1631	BRL	4/16/08	< 28.0	No	No	
TotalHg-ST15-4/14/08	0816018-10	South Face - East end at corner (scaffolding level)	4/14/08	0.59	Mercury	EPA 324/1631	BRL	4/16/08	< 25.0	No	No	
TotalHg-ST16-4/14/08	0816018-11	East Face - North end at corner (scaffolding level)	4/14/08	0.55	Mercury	EPA 324/1631	BRL	4/16/08	< 27.0	No	No	
TotalHg-ST17-4/14/08	0816018-12	North Face - West end at corner (scaffolding level)	4/14/08	0.56	Mercury	EPA 324/1631	BRL	4/16/08	< 27.0	No	No	
TotalHg-ST1-4/15/08	0816026-01	Southwest Area (sidewalk bridge level)	4/15/08	0.57	Mercury	EPA 324/1631	BRL	4/17/08	< 26.0	No	No	
TotalHg-ST2-4/15/08	0816026-02	Southeast Area (sidewalk bridge level)	4/15/08	0.56	Mercury	EPA 324/1631	BRL	4/17/08	< 27.0	No	No	
TotalHg-ST4-4/15/08	0816026-03	Northwest Area (street-level)	4/15/08	0.57	Mercury	EPA 324/1631	BRL	4/17/08	< 26.0	No	No	
TotalHg-ST5-4/15/08	0816026-04	Firehouse #10 (roof level)	4/15/08	0.59	Mercury	EPA 324/1631	BRL	4/17/08	< 25.0	No	No	
TotalHg-ST10-4/15/08	0816026-05	North Side Sidewalk Bridge	4/15/08	0.61	Mercury	EPA 324/1631	BRL	4/17/08	202.0	No	No	
TotalHg-ST11-4/15/08	0816026-06	90 Trinity Place (roof level)	4/15/08	0.57	Mercury	EPA 324/1631	BRL	4/17/08	< 26.0	No	No	
TotalHg-ST12-4/15/08	0816026-07	110 Greenwich Street (roof level)	4/15/08	0.60	Mercury	EPA 324/1631	BRL	4/17/08	< 25.0	No	No	
TotalHg-ST13-4/15/08	0816026-08	Marriott Hotel, 38th Floor (roof level)	4/15/08	0.55	Mercury	EPA 324/1631	BRL	4/17/08	< 27.0	No	No	
TotalHg-ST14-4/15/08	0816026-09	West Face - South end at corner (scaffolding level)	4/15/08	0.60	Mercury	EPA 324/1631	BRL	4/17/08	< 25.0	No	No	
TotalHg-ST15-4/15/08	0816026-10	South Face - East end at corner (scaffolding level)	4/15/08	0.55	Mercury	EPA 324/1631	BRL	4/17/08	< 27.0	No	No	
TotalHg-ST16-4/15/08	0816026-11	East Face - North end at corner (scaffolding level)	4/15/08	0.57	Mercury	EPA 324/1631	BRL	4/17/08	< 26.0	No	No	
TotalHg-ST17-4/15/08	0816026-12	North Face - West end at corner (scaffolding level)	4/15/08	0.54	Mercury	EPA 324/1631	BRL	4/17/08	< 28.0	No	No	