

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-4/17/06	06BR0560-01	Southwest Area (sidewalk bridge level)	4/17/06	0.56	Mercury	EPA 324/1631	BRL	4/19/06	< 27.0	No	No	
TotalHg-ST2-4/17/06	06BR0560-02	Southeast Area (sidewalk bridge level)	4/17/06	0.56	Mercury	EPA 324/1631	BRL	4/19/06	< 27.0	No	No	
TotalHg-ST4-4/17/06	06BR0560-03	Northwest Area (street-level)	4/17/06	0.56	Mercury	EPA 324/1631	BRL	4/19/06	< 27.0	No	No	
TotalHg-ST5-4/17/06	06BR0560-04	Firehouse #10 (roof level)	4/17/06	0.57	Mercury	EPA 324/1631	BRL	4/19/06	< 26.0	No	No	
TotalHg-ST10-4/17/06	06BR0560-05	North Side Sidewalk Bridge	4/17/06	0.56	Mercury	EPA 324/1631	BRL	4/19/06	< 27.0	No	No	
TotalHg-ST11-4/17/06	06BR0560-06	90 Trinity Place (roof level)	4/17/06	0.56	Mercury	EPA 324/1631	BRL	4/19/06	< 27.0	No	No	
TotalHg-ST12-4/17/06	06BR0560-07	110 Greenwich Street (roof level)	4/17/06	0.60	Mercury	EPA 324/1631	BRL	4/19/06	< 25.0	No	No	
TotalHg-ST13-4/17/06	06BR0560-08	Marriott Hotel, 38th Floor (roof level)	4/17/06	0.57	Mercury	EPA 324/1631	BRL	4/19/06	< 26.0	No	No	
TotalHg-ST14-4/17/06	06BR0560-09	West Face - South end at corner (scaffolding level)	4/17/06	0.58	Mercury	EPA 324/1631	BRL	4/19/06	< 26.0	No	No	
TotalHg-ST15-4/17/06	06BR0560-10	South Face - East end at corner (scaffolding level)	4/17/06	0.58	Mercury	EPA 324/1631	BRL	4/19/06	< 26.0	No	No	
TotalHg-ST16-4/17/06	06BR0560-11	East Face - North end at corner (scaffolding level)	4/17/06	0.58	Mercury	EPA 324/1631	BRL	4/19/06	< 26.0	No	No	
TotalHg-ST17-4/17/06	06BR0560-12	North Face - West end at corner (scaffolding level)	4/17/06	0.58	Mercury	EPA 324/1631	BRL	4/19/06	< 26.0	No	No	
TotalHg-ST1-4/18/06	06BR0565-01	Southwest Area (sidewalk bridge level)	4/18/06	0.58	Mercury	EPA 324/1631	BRL	4/20/06	< 26.0	No	No	
TotalHg-ST2-4/18/06	06BR0565-02	Southeast Area (sidewalk bridge level)	4/18/06	0.58	Mercury	EPA 324/1631	BRL	4/20/06	< 26.0	No	No	
TotalHg-ST4-4/18/06	06BR0565-03	Northwest Area (street-level)	4/18/06	0.57	Mercury	EPA 324/1631	BRL	4/20/06	< 26.0	No	No	
TotalHg-ST5-4/18/06	06BR0565-04	Firehouse #10 (roof level)	4/18/06	0.57	Mercury	EPA 324/1631	BRL	4/20/06	< 26.0	No	No	
TotalHg-ST10-4/18/06	06BR0565-05	North Side Sidewalk Bridge	4/18/06	0.56	Mercury	EPA 324/1631	BRL	4/20/06	< 27.0	No	No	
TotalHg-ST11-4/18/06	06BR0565-06	90 Trinity Place (roof level)	4/18/06	0.57	Mercury	EPA 324/1631	BRL	4/20/06	< 26.0	No	No	
TotalHg-ST12-4/18/06	06BR0565-07	110 Greenwich Street (roof level)	4/18/06	0.55	Mercury	EPA 324/1631	BRL	4/20/06	< 27.0	No	No	
TotalHg-ST13-4/18/06	06BR0565-08	Marriott Hotel, 38th Floor (roof level)	4/18/06	0.59	Mercury	EPA 324/1631	BRL	4/20/06	< 25.0	No	No	
TotalHg-ST14-4/18/06	06BR0565-09	West Face - South end at corner (scaffolding level)	4/18/06	0.57	Mercury	EPA 324/1631	BRL	4/20/06	< 26.0	No	No	
TotalHg-ST15-4/18/06	06BR0565-10	South Face - East end at corner (scaffolding level)	4/18/06	0.57	Mercury	EPA 324/1631	BRL	4/20/06	< 26.0	No	No	
TotalHg-ST16-4/18/06	06BR0565-11	East Face - North end at corner (scaffolding level)	4/18/06	0.58	Mercury	EPA 324/1631	BRL	4/20/06	< 26.0	No	No	
TotalHg-ST17-4/18/06	06BR0565-12	North Face - West end at corner (scaffolding level)	4/18/06	0.57	Mercury	EPA 324/1631	BRL	4/20/06	< 26.0	No	No	